

**Douglas County Surveyor's Record of  
Government Corners Renewed**

T 25      T. S.      R 1      R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

**134**

Cont. from last page -

Dennis Gaylord, U.S.F.S.  
Doug. Co. Surveyors Office Deputy  
Witness: Travis Worthen  
Sept. 1977  
C.S. 59/40

New BT - A 13" D. Fir bears S.42°E., 88.7 ft. scribed "1/4 S1 CS BT"  
on a double blaze. Placed County BT sign on Fir.

Note: Found two fir trees 100 ft. + East which appeared to be  
bearing trees but when chopped out, no scribing was found.  
Face well chopped by an axe. 50 years growth over face.  
9/14/77

**135**

W.C. for C.C. for Secs. 4 and 3 only, T26-1.

Found - Orig. 12" now 16" D. Fir corner tree. Has been previously opened  
on the south & west sides. Has a healed scar on the east side.  
Fragmentary scribing is visible on the opened face and on the  
removed pieces of wood (in reverse). There are 3 healed hacks  
on the east and west sides at chest height.

Orig. 14" now 31" D. Fir bears S.25°E., 30.2 ft. (Rec. 23.76 ft.)  
Orig. distance to this BT could be 10 lks. in error. Has a  
healed scar.

Orig. 14" now 30" D. Fir bears S.71°W., 13.3 ft. (Rec. 11.88 ft.)  
Has faint sign of a healed scar. Placed County BT signs on  
both trees, which are healthy and in good condition.

Set - I placed a Forest Service location sign on the east & one on the  
west side of the corner tree, marked "Corner Tree". 1 ft.  
south of the corner tree I Set a 2 1/2" brass cap on a 1" I.P.  
marked County Surveyors Office W.C.

1977      1.0' N  
                 C.C.  
                 S4 | S3  
                 T26S RLW

No new accessories. Corner lies 350 ft. west of the Williams Creek Trail.

9/13/77

Jan 78

Closing Corner for Secs. 7 and 18 only.

**136**

Found - A 1 1/2" I.P. displaced from record position by uprooted tree,  
with 1957 GLO brass cap attached. (1957 resurvey).  
A 1" I.P. with unmarked steel cap displaced from record position  
by uprooted tree. Ren. #7.  
A 15" now 18" Fir (1957 resurvey) now a 6 ft. tall uprooted stump  
with well-healed blazes.  
A 12" now 13" D. Fir (ren. #7), now a 6 ft. tall uprooted stump  
with well healed blazes.  
All other bearing trees of record were destroyed by road const.

Set - At the corner point determined at record measurements S.81°W.,  
15.8 ft. from the NE 1957 resurvey BT previously described, we  
reset the BLM brass cap extending 6" above ground and add the  
markings "CS 1978" to the cap. The 1" I.P. now bears approx.  
S.4 1/2°W., 7.3 ft. (Rec. S.16°E., 7.3 ft., 1957 resurvey).

Bearing Objects:

The area surrounding this corner has been logged, therefore we  
use the points established as bearing objects in 1976 reference  
as follows:

A boat spike marked "BO 1" set on top of 50" D. Fir stump bears  
N.56°W., 59.35 ft.

A boat spike marked "BO 2" set on top of a 72" D. Fir stump bears  
N.8 1/2°W., 110.18 ft.

An 18" uprooted D. Fir stump bears N.81°E., 15.8 ft.

Corner located approx 20 ft. north of road 25-1-7.7

3/29/78

**137**

1/4 Corner for Sec. 5 and Sec. 32 of T24-1

Found - A 1" x 30" I.P. lying on the ground out of position with brass cap  
attached marked: County Surveyors Office T24S 1/4 S32 S5 T25S  
RLW 1966. Ren. #97

An orig. 14" R. Cedar, now a 17" shattered stob, 3 ft. tall,  
scribing "4 S" visible on previously opened blaze on downed por-  
tion of the tree located downhill from the shattered stump, bears  
N.43°W., 5.3 ft.

An orig. 36" D. Fir now 40" and uprooted with well healed blaze,  
stump hole bears approx. S.74°E., 18.5 ft.

A 6" now 7" Hemlock, blown down but still alive with scribing  
"1/4 S 32 CS BT" visible on unhealed double blaze bears N.56 1/2°  
W., 26.7 ft. (Rec. N.52°W., 26.2 ft.)

O V E R      C O N T.

Gary L. Langlitz  
P.L. Earle  
F.C. Silagy  
Doug. Co. Surveyors  
Office  
March 29, 1978  
C.S. 59/46

Gary L. Langlitz  
Doug. Co. Surveyors  
Office  
May 1, 1978  
C.S. 60/11