

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25 T. S. R 1 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

137

C O N T ---

Gary L. Langlitz
Frank C. Silagy
Doug. Co. Surveyors
Office
May 1, 1978
C.S. 60/11

A 5" now 6" Hemlock, alive with scribing "14/ S 5 CS BT" visible on unhealed double blaze, bears S.44 1/2 E., 32.5 ft. (Rec. S.49 E., 32.5 ft.)
Set - At a location which agrees with the measurements listed for the previously described corner accessories, WE RESET the 1966 County Surveyors brass cap 28" in the ground on a steep north slope, and add the markings "Reset 1978" to the brass cap.
New accessories: A boat spike marked "BO 1" set near the heart on top of a 54" S. Pine stump bears S.87 1/2 W., 32.3 ft.
Corner is located in cut over area.

5/1/78

138

1/4 Corner for Secs. 28 and 33
Set - 3" Brass cap on 2 1/2" galv. I.P. marked T25S R1W 1/4 S28 S33 1978 RLS 1005.
Scribed: 20" D. Fir. S.16°E., 10.2 ft. "1/4 S33 T25S R1W BT"
10" D. Fir. N.56°W., 57.4 ft. "1/4 S28 T25S R1W BT".
Nailed brass washer stamped RLS 1005 to lower blaze of each BT.

Romanso E. Ware
L.S. #1005
For: U.S. Forest
Service
August, 1978
M 70 - 33

Section corner for Secs. 28, 27, 33 and 34.
Found - Markings on solid rock " + ' "'
16" Fir snag, N.74°E., 21.8 ft. visible scribing.
12" D. Fir S.87°E., 90.0 ft. visible scribing.
16" D. Fir, N.36°E., 24.3 ft. visible scribing.
11" D Fir N.29 1/2°W., 37.1 ft. visible scribing.
"X BO" marked in rock outcrop, S.65 1/2°W., 20.4 ft.
Set - 3" Brass cap in concrete on solid rock at location of found markings, Marked: T25S R1W S28 S27 S33 S34 1978 RLS 1005.

Ren. #131

140

1/4 Corner for Secs. 28 and 27.
Set - 3" Brass cap on 2 1/2" Galv. I.P. marked: T25S R1W S28 S27 1978 RLS 1005.
Scribed; 6" D. Fir, S.44°W., 16.8 ft. "1/4 S28 T25S R1W BT"
8" D. Fir, N.70°E., 16.1 ft. "1/4 S27 T25S R1W BT"
Nailed a brass washer stamped RLS 1005 to lower blaze of each BT.

8/78

Romanso E. Ware
For: U.S. Forest
Service
Sept. 1978
M 73 - 69

Section corner for Secs. 35 and 36 only. (south)
Found - 1.2' x 1' x 1' slate rock with "X". Ren. #38
Set - 3" brass cap in rock. (Steel fence post 4 ft. north)
Found BT's:
25" D. Fir bears S.48°W., 12 ft. (good scar)
6" White Oak bears N.39°E., 23.4 ft. (good scar)
New BTs - 7" B. Oak bears N.50°W., 26.9 ft. with washer scribed "T25S R1W S35 BT"
Brass cap stamped T25S R1W S.C. S35 S36 L.S. 1005 1978

141

9/78

William Ruppert
L.S. #866
For: U.S. Forest
Service
Nov. 1978
C.S. 58/176

Closing Corner for Secs. 7 and 18 only of T.25-1E.
Found - 1927 U.S. GLO brass cap properly marked on 1 1/2" Pipe. Both had slid several feet down hill with pile of stones.
38" D. Fir, N.23°49'E., 90.5 ft. Shows good scar.
22" D. Fir, S.36°06'E., 97.3 ft. Shows good scar.
Set - I reset orig. pipe with brass cap, S.00°58'E., 1.32 ft. from the pipe I had previously set for the witness corner to the corner of Sections 12 and 13. I constructed a mound of stones around it

142

1/4 Corner for Sec. 13 only, T.25-1W.
Found - 5/8" Steel tube buried 12" under the berm at the side of a skid trail. 1" Alum. cap attached marked "Property Corner" Ren. #23
36" D. Fir stump with axe marks in bark bears S.26°55'W., 20.8 ft.
12" Cedar stump cut approx. 36" high with face charred from slash fire bears N.44°05'W., 55.8 ft.
Set - Replaced tube with 2"x30" Gal. steel pipe 26" in the ground. Planted tube next to pipe. Marked the attached 2 1/2" brass cap "T25S R1W 1/4 S13 PLS 866 1978"
New BT's- 15" Cedar "1/4 S13 BT" and attached brass washer marked "L.S. 866" bears S.20°55'W 77,8 ft. Drove green 6 ft. steel fence post 18" into the ground and painted red. bears N.45°56'W., 55.8 ft. Constructed mound of stones around the 2"x30" steel pipe.

143

RE-RENEWED, SEE CORNER NO. 157