

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 T. S. R 1 R. W. W. M.

HOKE-CHAPMAN CO., EUGENE, ORE. 21881

155

Gregory Quibell
Deputy, Douglas
Co. Surveyors
Office.
Teresa Buley
Oct. 26, 1981
C.S. 61/29

1/4 Corner for Sections 27 and 26.
Found - 1966 County brass cap properly marked, firmly set. Ren. #60
Orig. 15" fir now 24" Hemlock snag 30 ft. high, with scribed
"S" visible in previously opened blaze, bears S.25°W., 5.3 ft.
(Rec. S.35°W.)
Orig. 18" now 30" Hemlock stump with good scar bears N.68°E.,
23.1 ft.
10" now 12" Hemlock, Ren. #60, with "1/4 S27 CS BT" visible in
unhealed blaze bears S.56°W., 10.8 ft. (Rec. S.58°W.)
17" now 22" Hemlock stump, Ren. #60, with "1/4 S26 CS BT" visible
in unhealed blaze bears N.29°E., 44.8 ft.
New BT's- 7" Hemlock scribed "1/4 S26 CS BT" in double blaze bears N.34°E.,
42.3 ft.
12" Hemlock scribed "1/4 S26 CS BT" in double blaze bears
S.56°E., 61.3 ft.
20" Hemlock scribed "1/4 S27 CS BT" in double blaze bears
S.74°W., 77.2 ft.

10/26/81

156

Section Corner for Secs. 18 and 19 only of T.25-1E.
Found - 1927 GLO brass cap properly marked.
30" Cedar snag bears S.28°E., 6.4 ft.
9" D. fir snag (down) bears S.40°E., 27.7 ft. Ren. No. 144
10" D. fir bears N.77°E., 80.5 ft.
15" D. fir snag bears S.07°30'E., 31.3 ft.
New BT - 6" D. fir bears N.02°W., 21.5 ft. scribed "X" on small upper
blaze and "BT" on small lower blaze. A 1/2" brass washer
marked "RLS 1035" is nailed flush to lower blaze.

Gerald V. Nygren
For: U.S.F.S.
June 11, 1987
C. S. 63/50

157

1/4 Corner for Section 13 only (East)
Found - 1978 brass cap set by PLS 866 properly marked. Ren. No. 143
36" Fir stump bears S.26°55'W., 20.8 ft.
12" Cedar stump bears N.44°05'W., 55.8 ft.
16" Cedar bears S.20°55'W., 77.8 ft.
A 6' steel fence post bears N.45°56'W., 55.8 ft.
New BT - 8" D. fir bears N.37°W., 7.0 ft. with single blaze scribed
"1/4 S13 RS1035 BT". A 1/2" brass washer marked "RLS 1035" is
nailed blush to lower end of blaze.

"I hereby certify the above corner points were perpetuated as hereon
described on June 11, 1987. U.S.F.S. bearing tree signs and monument
signs were placed on all BT's without them and a 6" red band was
painted around each BT.

158

Closing Corner for Sections 1 and 2 only of T.26-1
CORNER REPORT ONLY.

Found - 18" x 9" x 5" water-worn stone laying on the ground with marks
"X" on east side (top of stone); (CC on north side; one
groove on top and 5 grooves on bottom.
I was unable to locate the hole the stone came out of. I use
the center of the stone as the position for the corner point.
A 20" madrone stump, bears S.13°E., 27.7 ft. (Rec. S.21°E.,
42 lks.) with no marks visible on partially healed decayed
blaze.
A 30" D. fir stump, S.40°W., 20.2 ft. (Rec. S.44°W., 31 lks.
with healed blaze. I chop open and find scribe marks "W"
at 8" diameter.

I place bearing tree tags on both BT stumps.
Corner is about 150 ft. south of timber inside a clearcut and 50 ft. east
of a small creek on a steep west slope. To reach corner from Forest Road
No. 3800-010, turn west onto Rd. No. 3800-017, drive 1.0 mi. and turn
left onto Rd. No. 3800-026, drive 0.5 miles to location poster at clear-
cut. Corner is approx. 1050 feet west of location poster, at the bottom
of the clearcut, 1000 ft. lower than road.

5/12/88

Maurice E. Farr
U. S. Forest
Service
Leonard Herzstein
Dave Burr
May 12, 1988
C. S. 63/73

51