

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

V. W. Hosford  
Oct. 18, 21, 1957  
C. S. File No. 42/308

C. S. File No. 15/338  
Nov. 10, 1958  
for Evans Ploughing Co.

James W. Byron, Deputy  
Milo Godfrey  
S. Ellow  
July 14, 1958  
C. S. File No. 49/102

**31**  
¼ Section Corner to Section 7 & 8.  
After logging in Section 7, I found the original corner stone dislodged. Both original bearing trees are in good condition, the Yew now 11" in diam., the Hemlock now 24".  
At the true point of the corner, I drove a 1½" iron pipe 36" long, 24" in the ground and placed the original corner stone at its East edge.  
Oct. 17, 1957

**32**  
¼ Section Corner to Sections 21 & 22.  
At this corner I found the original bearing tree for Section 21 in good condition ( now 60" in diam.), the bearing mark was rotted and only dim traces of scribing visible. The original B.T. for Section 22 is a badly rotted stub.  
At the point of the corner, I drove a 1½" iron pipe 36" long, 24" in the ground, from which;  
A Fir 16" in diam. bears East 4.6 ft. marked ¼S 22 253 B.T.  
A Fir 13" in diam. bears N. 22½°W. 19.7 ft. marked ¼S 21 253 B.T.  
Oct. 18, 1957

**33**  
¼ Section Corner to Sections 15 & 22.  
At this corner I found a stone answering the description of the original corner stone. However, I could find no markings on it, probably due to erosion.  
The original bearing tree for Section 15 is in good condition, for Section 22 a dead snag. I drove a 1½" iron pipe 36" long, 24" in the ground at the South edge of the corner stone and marked a new bearing tree for Section 22.  
From the point of the corner:  
A Hemlock 30" in diam. bears S. 55°W. 21.7 ft. marked ¼S 22 253 B.T.  
Oct. 18, 1957

**34**  
Section Corner to Sections 14, 15, 22, & 23.  
Found - Scribed Wooden Stake, probably set by B. Irving, 1948. REN.#3  
All trees mentioned by Irving:  
18" Pine, now 20" N.46°E. 4 ft., lower scar grown over. Upper scar partially grown over & pitched over, no scribing visible.  
24" Pine, now 28" N.35°W. 11.9 ft., Lower Scar grown over. Upper Scar nearly grown over, traces of scribing visible.  
8" Hemlock, now 10" S.83°E. 38.3 ft. Both scars open. Scribing visible "T25S R2W S14 CS BT."  
16" Pine, now 19" S.29°W. 18.4 ft., lower scar grown over. Upper blaze badly pitched over, traces of scribing visible.  
11" Hemlock Snag scribed "25S R2W S23" bears S.66°E. 20.2 ft.  
At Corner Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1958 T25S R2S 

S15	S14
S22	S23

**35**  
¼ Section Corner to Sections 14 & 15.  
Found - 15" Fir, now 26" N.42°W. 16.5 ft. Recently shopped open to show plain scribing "¼".  
6" Chinquapin, now 10" Alive, S.57°E. 17.2 ft. The scars on this tree have never grown over & faint traces of old scribing can be seen. REN #4  
At Corner Point find square hole in dirt a few inches below surface.  
Set Iron Pipe with Brass Cap Mkd: "County Surveyor's Office, 1958 T.25S R.2W ¼ S15/S14.  
Blaze & Scribe: 5" Hemlock S.45°E. 11.5 ft. "¼ S14 CS BT".  
Note: Pipe set by Irving by Prop. Dist. for this ¼ Corner bears S.59°W. 111.5 ft. (Found 1" Pipe 5" above ground. Both trees alive and in good condition.

SEE ALSO WEYERHAEUSER NOTES IN C.S. 59/11