

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 2 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

58

Vernon "Ray"
Tracy &
Crew
Feb. 25, 1966
C.S. File
No. 49/102

$\frac{1}{4}$ Corner to Sections 2 and 11.
Found - 14"x8"x6" Basalt Stone Mkd: "1" & GLO Brass Cap, 1951. #139
Orig. 42" D. Fir N. 18 $\frac{1}{2}$ ° E. 30.4 ft. (found), now stump, shows good
scar & has "W" nail at base.
Orig. 10" Hemlock S. 40° W. 9.9 ft., down & badly rotted, fd. "BT".
30" D. Fir stump S. 13° E. 54.9 ft. with "W" Nail & Tag.
New BT's: 10" W. Fir N. 31 $\frac{1}{2}$ ° W. 30.0 ft. Mkd: $\frac{1}{4}$ " S 2 CS BT.
14" E. Cedar S. 37° E. 77.3 ft. mkd: $\frac{1}{4}$ " S 11 CS BT.
Note - This corner lies approx. 325 ft. East of Rock Creek.

RE-REVIEWED CORNER NO.

59

Vernon "Ray"
Tracy &
Crew
4/27/66
C.S.
49/102

$\frac{1}{4}$ Corner to Sections 23 and 24.
Found - Cadastral Brass Cap & $\frac{1}{2}$ " I.P. alongside in Mound of Stone, #102
See Ren. #25.
Orig. 66" Fir N. 69° E. 11.9 ft., shows good scar. Do not open.
Orig. 30" Fir N. 37° W. 17.2 ft., badly rotted stump, shows scribe.
BT. recorded in Ren. #25 destroyed.
N.W. BT. mkd. by Cadastral, destroyed.
New BT's: 12" Hemlock S. 48° E. 26.0 ft. Mkd: $\frac{1}{4}$ " S24 CS BT.
7" Hemlock N. 57° W. 83.6 ft. Mkd: $\frac{1}{4}$ " S23 CS BT.

RE-REVIEWED CORNER NO.

60

Vernon "Ray"
Tracy &
Crew
June 9, 1966
C. S. File
No.
52/77

TOWNSHIP CORNER- T25S R2W S 36
T26S S 1
Found - Orig. 16", now 30" Pine S. 60° W. 43.6 ft., scribe visible,
on prev. opened scar.
Orig. 16", now 30" Pine S. 55° E. 29.7 ft., shows old scar,
recorded as marks obliterated.
Orig. 30", now 40" Fir N. 85° E. 76.6 ft., shows fragmentary bark
scribe, recorded as being obliterated. N. W. BT. gone
Do not find Stone as called for.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1966 T25S R2W S 36
T26S S 1 RLW
New BT's: 7" D. Fir N. 56° W. 28.2 ft. Mkd: T25SR2W S36 CS BT.
15" Hemlock S. 50° W. 8.1 ft. Mkd: T26S R2W S1 CS BT.
Note - Corner lies on N.E. slope in mound of stone 12" high.

$\frac{1}{4}$ Corner Section 7 only, T25-2W. #61
Found - GLO Brass Cap, 1943, under 36" log.
36", now 38" Fir, 4 ft. high stump, S. 57 $\frac{1}{2}$ ° E. 37.6 ft.,
face pitched over & nearly healed. No scribe visible.
30", now 32" Fir, 3 Ft. high stump, S. 81 $\frac{1}{2}$ ° E. 33.0 ft.,
healed blaze, we do not open.
New BT: 30" Hemlock N. 18° E. 19.4 ft. Mkd: $\frac{1}{4}$ " S 7 CS BT.
(Bearing approx. from on top of log over brass cap).
No trees to SE due to logging. Corner lies in NW corner of
cutoff unit.

Closing Corner to Secs. 18 & 19, T25-2W. #62
Found - GLO Brass Cap, 1943, marked appropriately.
All BT's. are now turned out or stumps including BT's. recorded
in Ren. #57
New BT's: 15" R. Cedar N. 42° E. 49.1 ft. Mkd: CC T25S R2W S18 CS BT.
9" Laurel S. 21° E. 22.3 ft. Mkd: CC T25S R2W S19 CS BT.
4" I. Pipe is driven into stump of 14" Hemlock S. 28° E. 55.2 ft.
Pipe is weld marked "T25S R2W S19 CC BT" & stands 4.4 ft.
above stump.

$\frac{1}{4}$ Corner to Section 19 only, T25S-R2W. #63
Found - 1943 GLO Brass Cap, mkd. & BT's. as follows:
30", now 36" Fir S. 21° E. 28.4 ft. Alive, shows very good scar.
N. E. BT., now stump.
New BT's: 6" Hemlock N. 89° E. 39.1 ft. Mkd: $\frac{1}{4}$ " S19 CS BT.
5" Hemlock S. 36° E. 2.3 ft. Mkd: $\frac{1}{4}$ " S19 CS BT.
Note - This corner lies on N. - S. cutting line, cut off to East.
Basalt Boulder 6' x 4' x 4' bears west 1.0 feet.

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
June & July 1966
C. S. File No. 54/27