

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 2 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

70

$\frac{1}{4}$  Corner to Sections 13 only, T25-3W.  
Found - GLO Brass Cap mkd. " $\frac{1}{4}$  S 13/ 1943" & BT's., as follows:  
12", Now 16" Sugar Pine, S. 13° W. 14.0 ft., appears to be  
dying, shows very good scar, we do not open.  
14", now 20" D. Fir N. 59 $\frac{1}{2}$ ° W. 42.9 ft. Alive, good condition,  
shows very good scar. We do not open.  
New BT: 7" D. Fir S. 10° W. 18.8 ft. Mkd:  $\frac{1}{4}$  S13 CS BT.  
This corner lies at bottom of 20 ft. high rock bluff, course NW - SE on  
very steep, S. W. slope.

Section Corner to  $\bar{R}$  - - -  $\bar{R}$  - - -  
3 S 12 | S 7 T25S  
W S 13 | W

71

Found - 1943 GLO Brass Cap mkd. as above.  
Orig. 22", now 24" Hemlock, burned snag, N. 15° W. 11.2 ft.,  
no scribe found.  
14", now 18" Fir S. 56 $\frac{1}{2}$ ° W. 31.0 ft. Alive, healed blaze. Do not open.  
14", now 16" Fir N. 53 $\frac{1}{2}$ ° W. 24.4 ft. Alive, frag. scribe visible  
on burned face. We rescribe: "T25SR3W S12 CS BT".  
New BT: 10" D. Fir S. 14° W. 8.6 ft. mkd. T25S R3W S13 CS BT.  
Note - This corner lies on gentle, rolling to steep, S.W. slope.

Closing Corner to  $\bar{R}$  - - - | S 7  $\bar{R}$  - - -  
3W S 13 | S 18 2W T25S

72

Found - 1943 GLO Brass Cap, mkd. as above.  
20", now 24" I. Cedar N. 11 $\frac{3}{4}$ ° E. 52.1 ft., now stump, scribe  
visible on unhealed blaze.  
21" I. Cedar S. 63° E. 74.6 ft. Alive, shows partial scribe on  
nearly healed blaze.  
New BT: 18" I. Cedar N. 84° E. 61.2 ft. mkd. T25S R2W S7 CS BT.  
Note - This corner lies on very steep, S. W. slope approx. 40 ft. N.  
of top of 80 ft. bluff, course N.W. & S.E.

73

$\frac{1}{4}$  Corner Section 18 only,  
Found - 1943 GLO Brass Cap mkd.  
22", now 26" Hemlock N. 77° E. 13.9 ft. mkd.  $\frac{1}{4}$  S18 CC BT on unhealed  
blaze.  
54", now 60" Fir S. 18 $\frac{1}{2}$ ° E. 42.9 ft., shows good scar. Alive.  
New BT's: 11" Hemlock S. 45° E. 25.6 ft. mkd.  $\frac{1}{4}$  S18 CS BT (4' off ground).  
18" Red Cedar N. 60° E. 32.2 ft. mkd.  $\frac{1}{4}$  S18 CS BT.  
Note - Corner lays on S.W. moderate slope.

74

$\frac{1}{4}$  Corner to Sections 15 and 16 .  
Found - No trace of Brass Cap.  
BT's. as recorded in Ren. #5 by B.B.I, 1948, as follows: 93  
10", now 14" Maple N. 49° E. 44.5 ft., scribe visible on partially  
healed blaze, T25SR2WS15 CS 274 BT". Tree alive.  
14", now 18" Maple West 52.8 ft., scribe visible on unhealed blaze.  
Tree Alive.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T 25 S R 2 W  
Office, 1966  $\frac{1}{4}$  S 16/S 15  
New BT's: 18" Cedar S. 32° W. 109.1 ft. mkd.  $\frac{1}{4}$  S16 BS BT.  
16" Maple N. 29° E. 32.0 ft. Mkd:  $\frac{1}{4}$  S15 CS BT.  
Note - Corner lies 60 ft. N. of Rock Creek, course S.W. & 280 ft. South  
of Rock Creek Road; N.E. & S.W.

75

Closing Corner Secs. 6 and 7, T25-2W. T 25 S S12 | S 6 CC R2W  
Found - GLO Brass Cap mkd. 1943 R3W | S 7  
30", now 34" Fir 6 ft. high stump, N. 50 $\frac{3}{4}$ ° E. 15.2 ft.,  
scribe marks visible on nearly healed blaze.  
32", now 36" Fir, 6 ft. high stump, S. 20 $\frac{1}{2}$ ° E. 13.9 ft.,  
blaze nearly healed. 146  
New BT's: 8" Yew S. 63° E. 168.2 ft. mkd. T25S R2W S 7 CS CC BT.  
12" Hemlock N. 7° E. 222.3 ft. mkd. T25S R2W S 6 CS CC BT.  
Marked only available trees.- Corner lies in old logged-off area.

Aug. 30, 1966

Vernon "Ray" Tracy  
Joe Brady & Jack Heritage  
June - July 1966  
C. S. File No. 54/27

RE-FILED IN FILE NO. 146