

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25S. T. S. R. 2.W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

76

Sec. Corner to Sections 1 and 12 only, T25-3W.

Found - GLO Brass Cap mkd, 1943:

T 25 S	
S 1	R2W
S 12	

with steel fence post alongside R3W

All BT's. destroyed by logging.
No live trees available.

New BT's: 40" Fir Stump S. 73° W. 41.2 ft. mkd. T25S R3W S12 CS BT.
43" Fir Stump N. 71° W. 46.0 ft. mkd. T25S R3W S 1 CS BT.

Note - This corner lies approx. 500 ft. North of closing corner
of Sections 6 and 7, T25-2W in large logged-off area.

August 30, 1966

C.
S.
F
I
L
E
54/27

1/4 Corner to Sections 9 and 16. 77

Found - 1962 Cadastral Brass Cap, properly mkd.

Orig. 32", now 33" Fir, alive, N. 27° E. 2.6 ft., shows
good scar. Do not open.

Orig. broken Hemlock Stump 7" diam., S. 30° W. 4.0 ft. with
"4" scribe visible. 105

No trace of BT. marked in 1962, due to logging.

New BT: 8" Hemlock S. 6 1/2° E. 95.5 ft. mkd. 1/4 S16 CS BT.

Note - This corner lies on S.W. slope in logged-off unit.

1/4 Corner to Sections 12 and 13. 78

Found - 1962 Cadastral Brass Cap on 2 1/2" I.P., pushed out of position
& buried 6" below surface of ground. #117

Reset - Brass Cap in proper position from BT's
1962-13", now 14" Hemlock South 28.4 ft. Alive, badly injured
& filled to 3" of top of unhealed scribed blaze.

Orig. Fir BT., now only shattered remains of sawed stump,
S. 54° W. 12.5 ft., no scribe found. - REN. #9.

No trace of NE BT.

New BT's: 8" Hemlock N. 19° E. 141.6 ft. mkd. 1/4 S12 CS BT.

24" Cedar S. 57° W. 51.0 ft. mkd. 1/4 S13 CS BT.

Set - 6 ft. Red Steel Fence Post alongside Brass Cap. This corner
lies in recent logged off unit approx. 200 ft. N. of East fork
of Rock Creek Road.

Closing Corner

2W	S 31	T24-1W	1W
T25-1W	S 1	S 6	T25-2W

 79

Found - 1951 Cadastral Brass Cap, properly mkd. & BT's. down
and out of place.

I.P. & Steel Cap, (See Ren. #19) N. 21° W. 2.8 ft. The BT's.
for this corner are also down.

Cadastral Corner lies on E. slope on cutting line, course E-W with
timber to North.

New BT's: 8" Cedar S. 64° W. 114.6 ft. mkd. T25S R2W S1 CC CS BT.

34" D. Fir S. 79 1/2° E. 41.6 ft. mkd. T25S R1W S6 CC CS BT.

Vernon "Ray"
and Crew
May 5, 1967
C.S. File
No.
52/30

Section Corner to Sections 25 and 36, T25-2W. 80

Found - Orig. Corner Tree, 6", now 17" Hemlock, showing faint scars.

Orig. 30", now 48" Fir, S. 26° E. 20.5 ft. Alive, shows good scar. #111

Orig. 6", now 8" Fir, S. 25° W. 42.9 ft. Alive, scribe marks
visible on unhealed blaze.

Orig. 6", now 10" Fir, N. 35 1/2° W. 17.8 ft. Alive, scribe marks
visible on unhealed blaze. Orig. N.E. BT. gone.

Set - 3/4" Iron Rod on W. side & at base of corner tree 1' from center.

New BT: 8" W. Fir S. 43° W. 39.3 ft. mkd. T25S R2W S36 CS BT.

Note - This corner lies 175 ft. south of old scared man jeep road
at cutting corner, flogged to N.W.

SEE
e.
ALSO M 12-61
C.S. 90/279
1999 WEYER HANSEN
SURVEY

RE-PLACED CORNER NO.