

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 2 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21861

Vernon "Ray" Tracy  
Jack Heritage & E. West  
May, 1967  
C.S. File No. 52/30

Vernon "Ray" Tracy  
Jack Heritage & E. West  
June, 1967  
C.S. File No. 54/27

Vernon "Ray"  
Tracy &  
Crew  
8/10/67  
C.S. File  
No. 54/40

1/4 Corner to Section 36 only, T25-2W. 81  
Found - Orig. 6", now 10" Hemlock, S. 55° W. 14.5 ft. Alive & chopped  
open showing "1/4 S36" scribe & unopened lower scar. #12  
Orig. 14" Fir, now down & badly decayed, S. 88° E. 14.5 ft.,  
find edge of old axe face.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 

T 25 S	
R2W 1/4 S 36	RLW

  
New BT's: 17" Hemlock S. 47° W. 35.7 ft. mkd. 1/4 S36 CS BT.  
8" Hemlock N. 46° W. 20.8 ft. mkd. 1/4 S36 CS BT.  
Note - This corner lies 50 ft. E. of creek, course S.

Closing Corner to Sec. 31, T25-1W. & Sec. 6, T26-1W. 82  
Found - Orig. Corner Stone, 17"x14"x7", set in mound of stone  
and marked "CC" & 6 notches on N. & S.  
Orig. 24", now 33" Fir, N. 58° E. 41.6 ft., alive, shows  
good scar. Do not open.  
Orig. 6", now 21" Fir, S. 71° E. 29.7 ft., alive, shows  
good scar. Do not open. Rescribed "CCT26SRLW S6 CSBT".  
Set - Brass Cap in Mound of Stone Mkd: County Surveyor's Office, 1967  

R2W CC	S 31	T25S
	S 6	T26S RLW

  
New BT: 10" D. Fir N. 37° E. 17.3 ft. mkd. CC T25S RLW S31 CS BT.  
Note - This corner lies approx. 100 ft. S. of creek, course SE.  
May 31, 1967

Section Corner to Sections 10 - 11 - 14 - 15 83  
Found - Co. Surv. Brass Cap, properly marked, See Ren. #2.  
Orig. 11" Hemlock, now shattered & decayed stump, N. 27° E.  
11.2 ft., no scribe found.  
Orig. 16" Hemlock, now snag, S. 43° E. 19.1 ft., scribe visible  
on open blaze.  
Orig. 7", now 14" Cedar, alive, S. 56° W. 22.4 ft., rescribed  
by B.B.I. & orig. scribe visible on badly decaying face.  
No trace Original N.W. BT.  
24" Cedar, now sawed stump, N. 80° W. 58.9 ft., scribe visible.  
16" Fir, turned out & partially buried, N. 57° E. 33.4 ft.  
18" Cedar, alive & in good condition, S. 84° E. 51.7 ft., scribe vis.  
New BT's: 26" Hemlock N. 20° E. 57.1 ft. mkd. T25S R2W S11 CS BT.  
14" Cedar S. 69° W. 40.3 ft. mkd. T25S R2W S15 CS BT.  
No trees available to N.W.

1/4 Corner to Sections 26 and 35. 84  
Found - Orig. 6", now 8" Hemlock Corner Tree, previously opened on  
S. side & shows "1/4 S" scribe. Alive.  
Orig. 16" (?), now 11" Hemlock N. 10° W. 2.0 ft. Alive. We open  
& find "4" scribe & reverse.  
Orig. 7", now 28" W. Fir, Alive, S. 4° W. 16.5 ft. We open &  
find "1/4 S3" scribe & reverse under 66 years growth. (both BT's).  
48" D. Fir bears S. 32° E. 127.0 ft. scribed "1/4 S". Ring count of  
64 years & faces approx. west. No other evidence of BT/s.  
in this area.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 

T 25 S	R 2 W
1/4 S 26	
1/4 S 35	

  
New BT's: 20" Hemlock S. 25° W. 42.0 ft. mkd. 1/4 S35 CS BT.  
18" Hemlock N. 61° W. 4.6 ft. mkd. "1/4 S26 CS BT.  
June 16, 1967

1/4 Corner to Section 6 only, T26-2W. 85  
Found - Remains of very old cedar post, badly decayed, no scribing.  
40", now 60" Fir, S. 31° E. 25.7 ft., alive, shows good scar. Do not open.  
36", now 56" Fir S. 54° W. 23.8 ft., alive Open & find "B" scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1967 

1/4 S 6	T25S R2W
	T26S

  
New BT's: 7" D. Fir S. 32° W. 14.3 ft. mkd. 1/4 S 6 CS BT.  
14" D. Fir S. 54° E. 15.2 ft. mkd. 1/4 S6 CS BT.  
Note - This corner lies S.W. slope.  
August 10, 1967  
- FD. OK 3/76 G. BAUGHMAN -  
C.S. 58/100