

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 2 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

86

North $\frac{1}{4}$ Corner to Section 1 only, T26-2W.
Found - Basalt Corner Stone 18' x 10" x 8" mkd. " $\frac{1}{4}$ " on S. side,
firmly set by Collier in 1913.
Orig. 36", now 48" Fir, Alive, S.5°W. 44.2 ft., shows " $\frac{1}{4}$ S"
bark scribe.
Orig. 36", now 50" Fir, alive, N.60°E. 25.1 ft. (Record 23.1)
shows edge of old axe bark blaze & possible frag.scribe marks.
Set - Brass Cap at Cor. Mkd: County Surveyors T25S
(Reset Stone alongside) Office, 1967 T26S R2W $\frac{1}{4}$ S 1
New BT's: 14" D. Fir S. 36° E. 23.0 ft. mkd. $\frac{1}{4}$ S 1 CS BT.
16" D. Fir S. 53° W. 4.3 ft. mkd. $\frac{1}{4}$ S 1 CS BT.
Note - This corner lies on very steep west slope approx. 220 ft.
east of small creek, course S.W.

87

North $\frac{1}{4}$ Corner to Section 4 only, T26-2W.
Found - Orig. 10", now 16" Cedar, alive, N.30°E. 10.6 ft., scribe
marks visible on unhealed blaze.
Orig. 16", now 32" Cedar, alive, S.20°W. 19.8 ft., shows good scar.
(Rescribe: " $\frac{1}{4}$ S4 CS BT".)
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S
Office, 1967 T26S R2W $\frac{1}{4}$ S 4
New BT: 16" Cedar S. 72° E. 19.6 ft. mkd. $\frac{1}{4}$ S4 CS BT.
Note - This corner lies on bench approx. 400 ft. N. of top of ridge,
course N.E. & S.W.
Note - Excavating to set Brass Cap, we find remains of old corner post.

MICROFILM TO HERE 10/67 88

$\frac{1}{4}$ Corner to Sections 19 and 20.
Found - 1962 Cadastral Brass Cap & BT's. as follows:
Orig. 22" Hemlock, now snag, S.80°E. 17.8 ft., scribe visible
on unhealed blaze, "W" nail & tag.
Orig. 32" Hemlock, now stump, S.49°W. 26.4 ft., scribe visible,
"W" nail & tag.
9", now 10" Hemlock, alive, N.33 $\frac{1}{2}$ °E. 47.8 ft., scribe visible
on unhealed blaze.
No trace of 1962 S.W. BT. due to cat. road.
New BT: 7" Hemlock N.89°W. 42.2 ft. mkd. " $\frac{1}{4}$ S19 CS BT".
Note - This corner falls on N-S cutting line, clear cut west.
Best route to $\frac{1}{4}$ corner, follow cat. road from vicinity of
section corner $\frac{1}{2}$ mile south.

SEPT. 68

~~$\frac{1}{4}$ Corner to Sections 34 and 35.
Found - 1 $\frac{1}{2}$ " I. P. & 1" Steel Pipe with U.S. Plywood Alumn. Cap, Ren.#45
properly marked but unrecorded. Set from Orig. BT's:
Orig. 18" Fir, now decayed stump, S.40°E. 52.1 ft., scribe visible
on unhealed blaze.
Orig. 24", now 28" Hemlock, alive, S.54 3/4°W. 41.6 ft., old scar
unopened. Rescribed: " $\frac{1}{4}$ S34 BT" & Alumn. Tag #4287.
New BT: 26" Hemlock S.1°E. 36.3 ft. mkd: " $\frac{1}{4}$ S35 CS BT".
This corner lies in marshy area in clearing about 100' in diam.
11/7/68~~

89

1/4 Corner to Sections 9 and 10.
Found - 1962 Cadastral Brass Cap, in place & properly marked.
Orig. Corner Stone Mkd: "1/4" set on S. Side of B.C.
Orig. 8", now 12" Yew N.75°W. 13.2 ft., broken, dead,
No scribe.
27", now 28" Hemlock N.26°W. 66.0 ft., alive, good
scribe "1/4 S9 BT" visible.
32" Cedar, now snag, S.45 1/2°E. 60.1 ft., bent over
by Large Fir Log.
New BT: 36" Cedar N.1°E. 20.0 ft. scribed "1/4 S10 CS BT".
Old line tree N. 135.0 ft., now 80 ft. high Snag, notches
on N. & S. Sides visible.
This corner lies on very steep southerly slope in canyon.
6/26/72

90

MARCH 71

Vernon "Ray" Tracy
Jack Heritage & E. West
August, 1967
C. S. File No. 54/40

Vernon "Ray" Tracy
& Crew
Feb. 5, 1968
C.S. File No. 54/27

FD. OK 2-92 8Y
G. LANG M 114-57