Douglas County Surveyor's Record of Government Corners Renewed

T 25 T. S. R 2 R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

103

Closing corner for Secs. 31 and 32.
Found - 21" now 22" Incense Cedar, bears N.68°E., 21.1 ft. scribing visible. Ren. #91 (to center of tree)
25" now 28" Incense Cedar bears N.68°W., 28.3 ft., face healed over
Hosford's 4" Fir post, down. Ren. #54 (to center of tree)
1972 Doug. Co. brass cap and BT tags. Ren. #91
New BT - 48" Fir bears S.70°W., 12.3 ft. with "W" nail and plate.

4/28/76

104

Frank O. Williams by Glen McChesney
For: Weyerhaeuser Company
April 28, 1976
C.S. 58/8

South 1/4 Corner for Sec. 31 only.
Found - BLM Cadastral survey 1972 brass cap. (not of record at this date)
20" Hemlock, N.41°E., 86.1 ft. (plate reads 132 lks. S.41°E.)
10" Hemlock, N.27°W., 48.3 ft. (plate reads 73 lks. S.31 1/2°E.)
Referenced: Brass cap with plates and "W" nails on:
56" Fir, N.41°W., 54.0 ft. and
60" Fir, N.41°W., 40.9 ft.
Also drove 5/8" x 40" rebar 2' North of brass cap and 1" x 36" pipe 2.0 ft. East of brass cap, both driven down flush with ground.
Note: A Baughman Surveying Serv. 3/76 survey shows the brass cap to be 0.67' South of the North line of Sec. 6, T26S, R2W.
(see sketch in file) 4/28/76

Rod B. Kimberling
Peter L. Earle
Michael W. Cline
Do. Co. Surveyors Off.
August 31, 1977
C.S. File 59/38

105

1/4 Corner for Secs. 9 and 16
Found - BLM brass cap marked " 1/4 $\frac{S\ 9}{S\ 16}$ " on a 2 in. diam. iron
T25S R2W
1962
pipe buried at a 45° angle under a 34 ins. diam., D. Fir log.
A stone, 14" x 12"x4" now 14" x 9"x 4" (brokenin resetting) at the south side of brass cap with "1/4" chisled on North face.
Other stones found around iron pipe.
Found - A 20 ins. now 34 in. diam., D. fir, uprooted and laying across brass cap. Blaze apparently on ground side, Center of root hole bears approx. N.27° E., 2.6 ft.
An 8 in. hemlock snag bears S. 6 1/2° E., 96.2 ft. (Recorded 95.5 ft.) blazed and marked "1/4 S16 CS BT. Ren. #77
Renewal - Cut away section of log and straightened iron pipe with brass cap at ground level. Stamped "Reset 1977" above 1962. Reset chisled stone at north side of brass cap.
New BT's- A 6 in. diam., D. fir bears N.54°W., 44.4 ft., double blazed and marked "1/4 S9 T25S R2W CS BT.
A 5 in. diam., D. Fir, bears S22°E., 14.6 ft., double blazed and marked "1/4 S16 T25S R2W CS BT.".
Set a boat spike on root wad directly above brass cap. Stamped " B.O. No. 1"

8-31-77

106

Les Roberts
For: Weyerhaeuser Company
Oct. 1977
M 67 - 61

Witness Corner to 1/4 Cor. for Secs. 35 and 36.
Set - 5/8" x 42" Rebar in large mound of stone N.1°10 3/4'W., 44.0 ft. from point for 1/4 corner.
BT's - 36" Fir, bears N.10°E., 14.3 ft. to R.R. spike.
18" Fir, bears S.35°W., 31.0 ft. to R.R. spike.

10/77

107

Standard Corner for Secs. 1 and 2, T.26-2.
Found - 22" Down Fir, S.44°E., 67 ft.
12" Fir, N.38°E., 18.5 ft.
12" Fir, S.07°W., 33.5 ft.
10" Fir, N.04°W., 10.5 ft. Ren. #16, T.26-2.
Set - 1" Alum. pipe.
BT's - 20" Fir, S.75°E., 46.0 ft.to R.R. spike.
16" Fir, S.89°W., 21.1 ft to R.R. spike.
10" Fir N.04°W., 9.9 ft. to R.R. spike.

10/77