

**Douglas County Surveyor's Record of
Government Corners Renewed**

T 25 T. S. R 2 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

108

Les Roberts
For: Weyerhaeuser Com.
Oct. 1977
M 67 - 61

Closing Corner for Secs. 35 and 36 only.
Set - 5/8" x 42" Rebar
BT's - 10" Fir, N.20°E., 8.2 ft. to R.R. spike.
18" Fir, N.42°W., 11.9 ft. to R.R. spike.

10/77 **109**

Jan 78
SW corner Parcel 41, Section 4.
Found - A 70" D. Fir now a stump with scribing "P42 S4 BT" visible on unhealed blaze bears S.34 3/4°E., 64.7 ft.
A 33" D. Fir now a windfall with scribing "P41 S4 BT" visible on unhealed blaze bears approx. N.45°E., 6.6 ft.
1963 Cadastral brass cap no found. Probably displaced by nearby uprooted tree.
Set - At a location which agrees with the previously described corner accessories, WE SET a 5/8" x 30" Iron Rod 27" in the ground with aluminum cap attached marked: Douglas Co. Surveyor 1978

P 41
P 42

Also found - A "W-nail" set in the base of a 44" D. Fir stump, N.65°E., 47.8 ft. to the nail. See Weyerhaeuser Company notes in C.S.59/46 4/3/78

110

Section Corner for Secs. 5 and 4; and 32, 33 of T24-2
Found - 1951 GLO survey brass cap and 1 1/2" I.P set by C alder & Watson (Weyerhaeuser). Both monuments are out of position, displaced by logging activity.
A 48" D. Fir, now a 54" stump (OBT, 1883) with rescribing "24S R2W S33 B" visible on unhealed blaze bears N.65°E., 23.8 ft. (Rec. N.65°E., 16.5 ft.)
An orig. 12" now 22" Yew (1883 OBT) alive with rescribing "T25S R2W S5 BT" visible on unhealed blaze. (no orig. scribing found) bears S.20°W., 31.7 ft. (Rec. S.15°E., 33.0 ft.)
An orig. 24" D. Fir now a 37" snag (OBT, 1883) no scribing found, bears S.42°W., 49.5 ft. (Rec. S.40°W., 49.5 ft.)
An orig. 14" now 20" Yew (1883 OBT) alive with faint scribing "B" visible on orig. blaze & rescribing "T24S R2W S32 BT" visible on unhealed blaze bears N.26 1/2°W., 16.5 ft. (Rec. N.40°W., 16.5 ft.)
We do not find the SE bearing tree marked in 1963, a 40" Fir.
Set - At a location which agrees with the previously described bearing trees, WE RESET the 1951 GLO monument, a 2" x 36" I.P. 30" in the ground, with brass cap attached marked as described in the official record. WE ADD the markings "CS 1978" to the brass cap & place the 1 1/2" I.P. alongside the brass cap extending 18" above ground.
We confirm the bearings and distances to the accessories referenced by Weyerhaeuser Co. as shown on Page 3 of the notes filed in C.S. 59/46 with the following exception:

A 20" Yew, "W" nail bears S.20°W., 30.1 ft. (Weyerhaeuser record S.20°W., 30.5 ft.).

4/3/78
111

Glenn Baughman
For: Weyerhaeuser Co.
Aug. 1975 - Filed
June 1979
M 77 - 57

Section Corner for Secs. 25 and 36 only, T.25-2
Found - 56" Fir, face grown over, bears S.26°E., 20.5 ft. Orig.
17" Hemlock with visible scribe (down) orig.
8" Fir bears S.25°W., 42.9 ft. Orig.
10" Fir bears S.43°W., 30.3 ft. Ren. #80
10" Fir bears N.48°W., 20.5 ft.

All trees previously opened, scribes still visible.
Set - Brass cap.

8/75

112

Glen Mc Chesney
For Weyerhaeuser Co.
Labor Day, 1975
(Filed 12/80)
C.S. 58/8

East 1/4 corner for Sec. 36
Found - No trace of orig. fir post, 1900.
6" now 10" Hemlock scribing visible bears S.55°W., 14.5 ft. center measurement.
1967 County brass cap. Ren. #81
18" Hemlock, scribing visible bears S.47°W., 35.7 ft. center measurement. Ren. #81
8" dead Hemlock, scribing visible bears N.46°W., 20.8 ft. center measurement

Accessories added this date:
48" Fir, N.15°W., 17.8 ft. with W nail and plate.
48" Red Cedar, S.51°W., 37.3 ft. with W nail and plate.
Note: CC corner for Sec. 31. T25-1. S.6 T.26-1 appx. 401' S. & 2 ft. East.

Gary L. Langlitz
S.J. Flaese
F.C. Silagy
Douglas County Surveyors Office
April, 1978
C.S. 59/46

1-79