

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25. S. T. S. R. 3. W. R. W. W. M.

KOIKE-CHAPMAN CO., EUGENE, ORE. 21881

29

Sec. Cor. to Secs. 18 & 19, T25-3W. & Secs. 13 & 24, T25-4W.

Found - GLO Brass Cap in place & BT's. as follows:

- 30", now 30" D.Fir S.70 $\frac{3}{4}$ °E. 13.9 ft., down & dead, shows old scar.
- 36", now 36" I. Cedar S.45 $\frac{3}{4}$ °W. 11.9 ft., now stump.
- 30", now 32" D.Fir N.26°W. 11.2 ft., dead, still standing, shows old scar.
- 6", now 12" I. Cedar N.60 $\frac{3}{4}$ °E. 27.7 ft., snag, scribe visible on open face.

- New BT's: 8" I.Cedar N.61°E. 29.6 ft. Mkd: T25S R3W S18 CS BT.
7" D.Fir S.16°E. 17.4 ft. Mkd: T25S R3W S19 CS BT.
8" D.Fir S.41°W. 43.7 ft. Mkd: T25S R4W S24 CS BT.
6" I.Cedar N.75°W. 41.2 ft. Mkd: T25S R4W S13 CS BT.

30

Sec. Cor. to Secs. 6 & 7, T25-3W. & Sec. 1 & 12, T25-4W.

Found - GLO Brass Cap in small spring branch - No trace of 12"x18"x18" Pits.

- 5", now 18" D.Fir N.64°E. 99.0 ft., shows good scar. Didn't open.
- 5", now D.Fir S.6 $\frac{1}{2}$ °W. 61.4 ft., shows good scar. Didn't open.

- New BT's: 15" D.Fir S.55°E. 21.9 ft. Mkd: T25S R3W S7 CS BT.
5" Cedar N.76°W. 6.1 ft. Mkd: S1 CS BT.

Note - Spring is S.40°W. 53.0 ft.

31

$\frac{1}{4}$ Corner to Sec. 6, T25-3W. & Sec. 1, T25-4W.

Found - GLO Brass Cap, 1944, & Both BT's;

- 5", now 16" D.Fir S.41°W. 141.9 ft., shows faint scar. Didn't open.
- 7", now 16" Laurel S.44°E. 83.2 ft., shows faint, bark scribe.

We rescribe Laurel & Marked New Fir:

- 16" Laurel S.44°E. 83.2 ft. Mkd: $\frac{1}{4}$ S 1 CS BT.
- 9" D.Fir N.36°W. 20.7 ft. Mkd: $\frac{1}{4}$ S 1 CS BT.

Note - This corner lies in small opening surrounded by young fir on west slope of hill.

32

$\frac{1}{4}$ Corner to Sections 18 and 17.

Found - 30" Fir S.17°E. 22.4 ft., scribing visible in prev. opened scar.

32" Fir N.7 $\frac{1}{2}$ °W. 29.7 ft., scar healed over, but very plain.

No Brass Cap at Corner, obviously destroyed in logging. (1944-Price)

Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1964
T25S R3W $\frac{1}{4}$ S18/S17

Both BT's. alive & in good condition, no other trees near.

33

Sec. Cor. to Secs. 33 & 34, T25-3W. &
Secs. 4 & 3, T26-3W.

Found - 1943 GLO Brass Cap.

20", now 28" R.Cedar N.74 $\frac{1}{2}$ °W. 39.6 ft., shows scribe.
(This BT down)

12", now 13" R.Cedar S.56 $\frac{1}{2}$ °E. 57.4 ft., down &
shows scribe.

Other BT's. are stumps cut off below scribe.

- New BT's: 16" R.Cedar S.86°W. 64.9 ft. Mkd: T26SR3WS4 CS BT.
25" R.Cedar N.4°W. 95.5 ft. Mkd: T25SR3WS33 CS BT.
11" R.Cedar N.34°E. 38.7 ft. Mkd: T25SR3WS34 CS BT.
13" R.Cedar S. 6°E. 77.4 ft. Mkd: T26SR3W S3 CS BT.

May 14, 1965

34

$\frac{1}{4}$ Corner to Sec. 32, T25-3W. & Sec. 5, T26-3W.

Found - Orig. 16" B.Oak S.11°E. 90 lks., now low cut stump.

Orig. 12" W.Oak North 32 lks., now fallen snag.

15" Fir (1943 Resurvey) N.83 $\frac{1}{2}$ °E. 24 lks., now stump, scribing visible.

13" Fir (1943 Resurvey) S.22 $\frac{1}{2}$ °E. 19 lks., now stump, scribing visible.

Brass Cap at Corner (GLO 1943)

- New BT's: 11" Oak S.63°W. 23.6 ft. Mkd: $\frac{1}{4}$ S5 CS BT.
7" Oak N.45°W. 29.6 ft. Mkd: $\frac{1}{4}$ S32 CS BT.

Milo E. Godfrey, Deputy Co. Surv.
Wm. Stoffel & Mike Stone
November 1964
C. S. File No. 53/47

Vernon R.
Tracy
M. D. &
J. B.
C.
S.
File
No.
54/7

Bruce R. Rogers, Deputy
Wm. Stoffel & Mike Stone
July 15, 1965
C. S. File No. 54/7