

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy
Mike Stone & Jack Heritage
February 1966
C. S. File No. 54/7

41

Sec. Cor. to Secs. 31 & 32, T25-3 and Secs. 6 & 5, T26-3W.
Found - 1943 GLO Brass Cap & Stumps of following BT's.
(Brass Cap lies at Fence Corner, course E.-W. & S.
Orig. 40" Fir Stump S. 60° W. 4.6 ft., fragmentary bark
scribe visible.
60" Fir Stump N. 12 $\frac{3}{4}$ ° E. 42.9 ft., scribe & reverse visible.
20" Fir Stump S. 58 $\frac{1}{2}$ ° E. 43.6 ft., burned. "S" scribe visible.
22" Fir Stump N. 66 $\frac{1}{2}$ ° W. 42.2 ft., badly burned, some scribe visible.
New BT's: 7" D. Fir N. 23 $\frac{1}{2}$ ° E. 50.2 ft. Mkd: T25S R3W S 32 CS BT.
15" D. Fir N. 49° W. 130.4 ft. Mkd: T25S R3W S31 CS BT.
No trees available to S.E. or S.W.

42

$\frac{1}{4}$ Corner to Sec. 34, T25-3 and Sec. 3, T26-3W.
Found - 1942 GLO Brass Cap Mkd. & BT's. as follows:
Orig. 16" R. Cedar S. 17° W. 2.6 ft., shows old scar. Do not open.
54", now 56" D. Fir N. 15° W. 15.2 ft., shows good scar. Do not open.
5", now 6" Yew Stump S. 88° E. 14.5 ft., shows " $\frac{1}{4}$ S3BT" unhealed face.
New BT's - 6" Yew N. 10° E. 25.1 ft. Mkd: $\frac{1}{4}$ S 34 CS BT.
16" R. Cedar S. 6° E. 31.4 ft. Mkd: $\frac{1}{4}$ S 3 CS BT.
Note - This corner lies 24 ft. East of small creek, course S. E.

43

$\frac{1}{4}$ Corner to Sections 23 and 24.
Found - 1943 GLO Brass Cap, out of ground.
Orig. 36", now 42" Fir S. 65° W. 48.8 ft., Open, face pitched
over, "23" scribe visible. Alive but top broken off approx.
80 feet up.
Orig. 60", now 70" Fir N. 20° E. 17.8 ft., now stump & turned out,
shows "24" scribe on face.
Reset - Brass Cap Mkd: " $\frac{1}{4}$ S 23/S 24 1943".
New BT's: 14" Hemlock S. 38° W. 70.9 ft. Mkd: $\frac{1}{4}$ S23 CS BT.
12" Hemlock N. 58° E. 141.1 ft. Mkd: $\frac{1}{4}$ S24 CS BT.
Note - Corner falls on N. edge of cat road, course N.E. & S.W. & on
edge of logged-off unit in Section 24. June 9, 1966

44

$\frac{1}{4}$ Corner to Section 7 only, T25-2W.
Found - 1943 GLO Brass Cap under 36" Log.
36", now 38" Fir, 4' high stump, S. 57 $\frac{1}{2}$ ° E. 37.6 ft., face
pitched over & nearly healed, no scribe visible.
30", now 32" Fir Stump 3' high, S. 81 $\frac{1}{2}$ ° E. 33.0 ft., healed base.
New BT: 30" Hemlock N. 18° E. 19.4 ft. Mkd: $\frac{1}{4}$ S 7 CS BT.
(Bearing approx. from top of log over Brass Cap)
No trees to S.E. due to logging. Corner lies in N.W. Cor. of cut unit.

45

Cl. Corner to Secs. 18 & 19 only, T25-2W.
Found - 1943 GLO Brass Cap mkd.
All BT's. are now turned out or stumps including BT's. recorded
in Ren. #23.
New BT's: 15" R. Cedar N. 42° E. 49.1 ft. Mkd: CC T25S R2W S18 CS BT.
9" Laurel S. 21° E. 22.3 ft. Mkd: CC T25S R2W S19 CS BT.
4" I. Pipe is drive into stump of 14" Hemlock S. 28E. 55.2 ft.
Pipe is weld mkd. "T25S R2W S19 CCC BT" & stands 4.4 ft.
above stump. Corner lies in N.W. corner of Cut off unit.

46

$\frac{1}{4}$ Corner to Section 19 only, T25-2W.
Found - 1943 GLO Brass Cap mkd.
30", now 36" Fir, alive, S. 21° E. 28.4 ft., shows very good scar.
N. E. BT., now stump.
New BT's: 6" Hemlock N. 89° E. 39.1 ft. Mkd: $\frac{1}{4}$ S19 CS BT.
5" Hemlock S. 36° E. 2.3 ft. Mkd: $\frac{1}{4}$ S19 CS BT.
This corner lies on N. - S. cutting line, cut off to East.
Basalt Boulder 6" x 4' x 4' bears west 1.0 ft.