

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

53

Sec. Corner to Sections 28 - 29 - 32 - 33.

Found - 1943 GLO Brass Cap mkd. & squared cedar post, See Ren. #12.

Orig. 1883 BT's., as follows:

14" I. Cedar, now snag, N. $53\frac{1}{2}^{\circ}$ E. 6.6 ft., burned, no scribe found.

8" I. Cedar, now stub, 4' high, S. 72° E. 4.6 ft., frag. scribe.

20", now 22" Hemlock S. 70° W. 24.4 ft., now snag, scribe visible.

48" I. Cedar, now badly burned stump, N. 38° W. 9.9 ft.

1943 BT's., as follows:

20", now 27" Fir S. $58\frac{1}{2}^{\circ}$ E. 25.1 ft., now snag, scribe visible on burned face.

7", now 9" Yew S. $25\frac{3}{4}^{\circ}$ W. 12.5 ft. Alive, shows scribe on unhld. blz.

New BT's: 5" Yew S. 15° E. 11.9 ft. Mkd: T25S R3W S33 CS BT.

18" I. Cedar N. 78° E. 28.8 ft. Mkd: T25S R3W S28 CS BT.

No other tree available.

- - - - -

54

$\frac{1}{4}$ Corner to Sections 28 and 33.

Found - 1943 GLO Brass Cap mkd.

Orig. 1883 BT's., now stump N.E. & windfall to S.W.

1943 resurvey BT's. as follows:

24", now 32" Fir S. $23\frac{1}{2}^{\circ}$ E. 31.0 ft., shows good scar. Do not open.

N.E. BT., now shattered stump.

New BT's: 4" D. Fir N. 3° W. 4.6 ft. Mkd: $\frac{1}{4}$ S CS BT (only)

6" I. Cedar S. 76° E. 36.7 ft. Mkd: $\frac{1}{4}$ S33 CS BT.

Note - This corner lies on steep, west slope on E-W cutting line. Cut to N.

- - - - -

Sec. Corner to Sections 27 - 28 - 33 - 34.

Found - 1943 GLO Brass mkd.

No trace Orig. 1883 BT's. 1943 Resurvey BT's. as follows:

20", now 30" Fir N. 32° E. 62.0 ft., now snag with healed blaze.

36", now 44" Fir S. $61\frac{3}{4}^{\circ}$ E. 50.2 ft. Alive, shows good scar.

N.W. & S.W. BT's., now stumps.

New BT's: 16" D. Fir N. $24\frac{1}{2}^{\circ}$ W. 47.4 ft. Mkd: T25S R3W S28 CS BT.

16" D. Fir N. 14° E. 72.5 ft. Mkd: T25S R3W S27 CS BT.

No trees available to S. W.

Note - Corner lies on N. - S. cutting line, cut off to west.

- - - - -

55

$\frac{1}{4}$ Corner to Sections 27 and 34.

Found - 1943 GLO Brass Cap Mkd. & 1943 BT's. as follows:

40" Fir N. 7° E. 28.4 ft., now dead snag, shows " $\frac{1}{4}$ S27 BT" on unhealed blaze.

48", now 50" Fir S. 64° E. 10.6 ft., shows good scar. Alive.

New BT's: 9" Hemlock N. 51° E. 26.4 ft. Mkd: $\frac{1}{4}$ S27 CS BT.

7" Hemlock S. 29° E. 9.9 ft. Mkd: $\frac{1}{4}$ S34 CS BT.

Note - This corner lies at S.E. Corner of cutoff unit in Sec. 27, Approx. 1000 ft. East of Kelley Creek Road.

- - - - -

56

$\frac{1}{4}$ Corner to Sections 29 and 32.

Found - 1943 GLO Brass Cap mkd.

Orig. 42" Fir, now turned out, lying nearly face down, S. $32\frac{1}{2}^{\circ}$ W. 7.3 feet.

1943 Resurvey BT: 36", now 42" I. Cedar N. $68\frac{1}{4}^{\circ}$ E. 32.3 ft., Alive, top broken out, shows scribe on unhealed blaze.

New BT's: 12" W. Fir N. $81\frac{1}{2}^{\circ}$ E. 47.8 ft. Mkd: $\frac{1}{4}$ S29 CS BT.

No trees available in Sec. 32 due to logging. Corner lies in middle of logged off area approx. 100 ft. East of logging road, course N.W. & S.E.

- - - - -

57

$\frac{1}{4}$ Corner to Sections 30 and 29.

Found - 1943 GLO Brass Cap mkd. & BT's. recorded in Ren. #17, as follows:

40", now Cedar Snag, N. 40° W. 14.5 ft. scribed " $\frac{1}{4}$ S30 CS BT, now stump.

48", now 48" R. Fir Snag, N. 61° E. 365.7 ft., scribed " $\frac{1}{4}$ S29 CS BT".

New BT's: 5" D. Fir S. 54° W. 42.4 ft. mkd: $\frac{1}{4}$ S 30 CS BT.

4" D. Fir S. 83° E. 16.8 ft. Mkd: $\frac{1}{4}$ S BT.

Note - Brass Cap lies almost under North side of burned log.

Mt. Scott Lookout bears N. 82° E.

- - - - -

58

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
June & July, 1966
C. S. File No. 54/27