

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Township Corner:

R	3	S 36	S 31	R	2	T24S
	W	S 1	S 6		W	T25S

81

Found - GLO Brass Cap, 1943, mkd. as above, & stumps of Orig. BT. 48", now 50" Fir N. $50\frac{1}{2}^\circ$ W. 42.2 ft., shows frag. scribe on burned face. Rescribe "T25S R3W S1 CS BT".
All other BT's. gone or out of place due to logging.
New BT: 54" D. Fir, (Stump 8.0 ft. high), N. 37° E. 26.4 ft. Mkd. T24S R2W S31 CS BT.
No other trees available. Corner lies in Greasewood Thicket, 20 ft. E. of cat road & 20 ft. W. of bottom of small draw.

$\frac{1}{4}$ Corner to Section 13, only, T25-3W. 82
Found - GLO Brass Cap mkd. " $\frac{1}{4}$ S13/ 1943".
12", now 16" Sugar Pine S. 13° W. 4.0 ft. appears to be dying, shows very good scar. Do not open.
14", now 20" D. Fir N. $49\frac{1}{2}^\circ$ W. 42.9 ft. Alive & in good condition, shows very good scar. Do not open.
New BT: 7" D. Fir S. 10° W. 18.8 ft. mkd. $\frac{1}{4}$ S13 CS BT.
Note - This corner lies at bottom of 20 ft. high, Rock Bluff, course N.W. - S.E. on very steep, S.W. slope.

Section Corner to Sections 12 and 13 only, T25-3W. 83
Found - GLO Brass Cap, 1943, mkd.
Orig. 22", now 24" Hemlock N. 15° W. 11.2 ft., now burned snag, no scribe found.
14", now 18" Fir S. $56\frac{1}{2}^\circ$ W. 31.0 ft. Alive, healed blaze. Do not open.
14", now 16" Fir N. $53\frac{1}{2}^\circ$ W. 24.4 ft. Alive, frag. scribe visible on burned face. Rescribe "T25S R3W S12 CS BT".
New BT: 10" D. Fir S. 14° W. 8.6 ft. Mkd: T25S R3W S13 CS BT.
Note - This corner lies on gentle rolling to steep S.W. slope.

Closing Corner Sections 7 & 18 only, T25-2W. 84
Found - 1943 BLO Brass Cap mkd.
20", now 24" I. Cedar N. $11\frac{3}{4}^\circ$ E. 52.1 ft., now stump, scribe visible on unhealed blaze.
12", now 21" I. Cedar S. 63° E. 74.6 ft., Alive, shows partial scribe marks on nearly healed blaze.
New BT: 18" I. Cedar N. 84° E. 61.2 ft. mkd. T25S R2W S7 CS BT.
Note - This corner lies on very precipitous S. W. slope approx. 40 ft. N. of top of 80 ft. bluff, course N.W. & S.E.

$\frac{1}{4}$ Corner to Section 18, T25-3W. 85
Found - GLO Brass Cap mkd. " $\frac{1}{4}$ /S18 1942".
22", now 26" Hemlock N. 77° E. 13.9 ft. mkd. " $\frac{1}{4}$ S18 CC BT" on unhealed blaze.
54", now 60" Fir S. $18\frac{1}{2}^\circ$ E. 42.9 ft., shows good scar. Alive, we do not open.
New BT's: 11" Hemlock S. 45° E. 25.6 ft. mkd. $\frac{1}{4}$ S18 CS BT (4' off ground)
18" Red Cedar N. 60° E. 32.3 ft. mkd. $\frac{1}{4}$ S18 CS BT.
Note - Corner lays on S. W. moderate slope.

$\frac{1}{4}$ Corner to Sec. 36, T24-3W. & Sec. 1, T25-3W. 86
Found - GLO Brass Cap mkd. " $\frac{1}{4}$ 1944".
42", now 38" Fir Stump N. 46° W. 9.2 ft., face burned, Rescribe " $\frac{1}{4}$ S36 CS BT".
46", now 48" Fir Stump S. 81° W. 34.3 ft., burned, no scribe, Rescribe " $\frac{1}{4}$ S 1 CS BT".
Set - $\frac{1}{2}$ " Iron Pipe alongside Brass Cap 6 ft. above ground.
Corner lies approx. 125 ft. west of logging road on slight S.W. slope in logged off area. Mt. Scott Lookout bears S. 40° W.

Vernon "Ray" Tracy
Joe Brady & Jack Heritage
July & August, 1966
C. S. File No. 54/27