

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 3 W. R.W.W.M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

123

V.R.Tracy &  
Crew  
C.S. File  
No. 54/27

Sec. Corner to Sections 23 - 24 - 25 - 26.  
Found - GLO Brass Cap mkd. in 1943.  
Orig. 12", now 13" Yew, S. 45° W. 6.6 ft., frag. scribe marks  
on rotted face. Rescribe "T25S R3W S26 CS BT".  
Orig. 30", now 32" Hemlock N. 25° W. 40.9 ft., partial scribe  
marks visible on nearly healed blaze.  
All other BT's. destroyed by recent logging.  
New BT's: 9" Hemlock N. 9° W. 52.4 ft. mkd. T25S R3W S23 CS BT.  
11" Hemlock N. 40° E. 40.0 ft. mkd. T25S R3W S24 CS BT.  
9" Hemlock S. 18° E. 148.0 ft. mkd. T25S R3W S25 CS BT.

Sept. 1, 1966

124

1/4 Corner to Sec. 3, T25-3W. & Sec. 34, T24-3W.  
Found - GLO Brass Cap mkd. in 1944 with steel fence post alongside.  
Orig. 30", now 42" I. Cedar N. 4° W. 13.2 ft., prev. opened & face rotten.  
Orig. 48", now 52" Fir, now broken stub 10' high, S. 68° W. 7.3 ft., shows  
good scar. We do not open.  
34", now 40" I. Cedar N. 37 1/2° W. 25.7 ft. (recorded 27.1 ft.) Alive, shows  
good scar. We do not open.  
New BT's: 12" D. Fir S. 31 1/2° W. 34.2 ft. mkd. 1/4 S 3 CS BT. *Fnd. OK. 12-81*  
9" D. Fir N. 36 1/2° E. 17.0 ft. mkd. 1/4 S34 CS BT. *by B. Holt M 90-16*  
Note - Norman Price called for distances to be reversed on Orig. BT's.,  
but we find corner to be set as called for using Orig. distances  
of Orig. BT's., only bearings differ.

125

Sec. Cor. to Secs. 4 & 3, T25-3W. & Secs. 33 & 34, T24-3W.  
Found - GLO Brass Cap mkd. in 1943.  
50", now 54" Fir N. 58° E. 8.3 ft. Alive, shows good scar  
& old bark scribe. *Fnd OK 12-81*  
48", now 51" Fir South 35.6 ft. Alive, shows good scar. *by B. Holt M 90-16*  
38" Fir Stub N. 44° W. 32.3 ft., very badly decayed.  
5", now 7" Fir S. 29 1/2° E. 13.2 ft. Alive, shows good scar.  
6", now 8" Fir, N. 39 1/2° W. 33.0 ft. Alive, shows good scar.  
Due to larger Firs being marketable Trees, we mark new BT'S:  
8" D. Fir N. 13° E. 17.5 ft. Mkd: T24S R3W S34 CS BT.  
7" Live Oak S. 46° W. 29.2 ft. mkd: T25S R3W S 4 CS BT.  
Note - This corner lies on W. slope approx. 75 ft. W. of Rock Bluff,  
40 ft. high. See Ren. #3.

126

1/4 Corner to Sec. 4, T25-3W. & Sec. 33, T24-3W.  
Found - GLO Brass Cap mkd. in 1944, set in concrete in Basalt Bassett.  
Corner lies on S. W. Slope. See Ren. #1.  
Orig. 20", now 28" Madrone S. 67 1/4° W. 48.2 ft. Alive, prev. opened,  
rotting inside.  
36", now 37" Fir N. 26 1/2° W. 31.7 ft., now Snag, shows good scar.  
36", now 37" Fir, shattered Stump, S. 51 1/2° E. 17.8 ft., shows "4 BT" scribe.  
New BT's: 8" Madrone S. 27° E. 21.3 ft. mkd. 1/4 S 4 CS BT.  
12" Chinquapin N. 85° E. 19.1 ft. mkd. 1/4 S 33 CS BT.

127

Sec. Cor. to Secs. 3 & 2, T25-3 and Secs. 34 & 35, T24-3W.  
Found - GLO Brass Cap mkd. in 1944 with steel fence post set alongside  
and bent over. Reset fence post alongside Cap.  
60" Fir Stump N. 33 1/2° E. 52.1 ft., shows "T24S R3W S35 BT"  
scribe on unhealed blaze. *Fnd. OK. 12-81*  
12", now 20" R. Cedar S. 29° E. 4.6 ft., shows good scar. *by B. Holt M 90-16*  
Rescribe "T25S R3W S 2 CS BT".  
6", now 16" Fir S. 48 1/2° W. 40.3 ft., 48" log lying against  
scar, only top of scar visible.  
8", now 14" R. Cedar Snag, N. 51 1/2° W. 37.6 ft., Dead and  
burned, No scribe.  
New BT's: 6" D. Fir N. 10° E. 23.9 ft. mkd. T24S R3W S35 CS BT.  
17" R. Cedar N. 69° W. 35.6 ft. mkd. T24S R3W S34 CS BT.  
Note - Corner lies on moderate west slope approx. 120 ft. W. of top of spur.

Vernon "Ray" Tracy  
Jack Heritage  
September, 1966  
C. S. File No. 54/27