

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 4 R. W. W. M.

SEC. COR. 11-12-14-13

Location identified from remains of 2 OBTs as described in Gov't field notes one down but in good shape N.46°W., 29 lks. and the other a stump N.72°E., 27 lks. bearing marks.
Drove car axle for corner with 4" sq. Cedar Post alongside scribed S13 on SE. face, S14 C.S. on SW. face, R.4W. S.11 on NW. face and T.25S., S 12 on NE face. Marked New BTs.
Fir 26" dia. S.47°E., 48 lks. T. 25 S. R. 4 W. S. 13 C.S.B.T.
Fir 30" dia. N.77°45'E., 65 lks. T. 25 S. R. 4 W. S. 12 C. S. B. T.
Fir 24" dia. N.45°44'W., 53 lks. T. 25 S. R. 4 W. S. 11 C. S. B. T.
Fir 34" dia. S.11°25'W., 20 lks. T. 25 S. R. 4 W. S. 14 C. S. B. T.

11

1/4 COR 11/12

Location identified by down and rotten OBT S73°E. 20 lks. bearing proper marks. Also a Fir 24" dia. N.70°E., 29 lks. which had been marked by Surveyor Thiel many years ago which I reblaze and scribe 1/4 S 12 C.S.B.T. Blaze and Scribe a New BT A 24" Fir N.25°W., 125 lks. 1/4 S. 11 C. S. B. T.
Drove 1 1/4" car axle flush with ground for corner.

12

1/4 COR. 11/14

Location identified from old Ash BT which appeared to have scribe marks but nearly rotted away. Blaze does not face right. Another hole apparently old blaze faces correctly but all blaze marks gone. Places corner on blazed E and W line. Drove 1 1/4" dia. axle flush with ground for corner. Drove 4" sq. Oak Post along side scribed 1/4 S. on E. face, S 11 on N. Face S 14 on S. face and C.S. on W. face. New BTs.
14" W. Oak N.42°W., 71 lks. blazed and scribed 1/4 S.11 C.S.B.T.
18" Fir S.29°E., 44 lks. blazed and scribed 1/4 S.14 C.S.B.T.

13

NE. COR D. L. C. #49

Location identified from old Oak BT. which has old scribe marks. Drove 1 1/2"x1 1/2"x36" Iron Bar for Corner marked two new BT.
12" fir N.40°W., 50 ft.
12" W. Oak N.66°W., 58.5 ft.
1 1/2" Iron Bar S51°W., 334 ft.
Added notes: From wh. 18" W. Oak (at Gate) S.48°W., 65' A.B. August 15, 1941
Theil changed this to S.58 1/4°W., 22° also pins.

14

SE. COR D.L.C. #49

Location identified from old Oak B.T. Set a 3"x3"x36" Oak Stake
Marked new witness tree as follows:
15" center part of 3 forked Cedar N.74°30'W., 56 lks.
8" Cedar N.43°30'E., 68 lks.

15

COR. 2-1-11-12 (F. B. #7)

W. Oak 6 ins. S.6°E., 15 lks.
Ash 7 ins. S.21°W., 17 lks.

16

1/4 COR BET. SECS. 20 and 21.

Location identified from Original bearing tree now down and almost destroyed but part of the scribed "T" of the BT. still visible.
White Oak 18" N.50°E., 213 lks.
Drove a 1"x3" channel iron 36" long 35" in the ground for the corner from which:
Oak 8" dia. bears N.45°E., 11.5 ft.
Cedar 12" dia. bears N.86°W., 188.7 ft.
Both blazed and scribed 1/4 S. C. S. B. T.

17

CORRECTED
From field on 6/2/55
In 37/204 on R.G.I.

Ben B. Irving, Deputy County Surveyor
Sept. 14, 1929
Witness N. E. Richardson
Royal Abeen
Av Abeen
C.S. No. 13 Page 298
C.S. File 37/5
C.S. 36/58
Aug. 20, 1930
H. L. Eppstein Co. Sur.
P. D. Wolford
Clyde Holman
Aug. 28, 1930
Eppstein Co. Sur.
N. E. Richardson
Clyde Holman
May 28, 1903
C. E. Roberts
These corners were all renewed by Ben B. Irving, Deputy Co. Sur. in the course of a survey made for the State of Oregon.
N. E. Richardson
Harvey L. Eppstein Jr.
Robert Hellwell