

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 4 R. W. W. M.

These corners were all renewed by Ben. B. Irving
 Deputy County Surveyor in the course of a survey for the
 State of Oregon.
 Wit. N. E. Richardson, Harvey L. Eppstein Jr.
 Robert Helliwell.

C. S. File No. 5-66

1/4 CORNER BE. SECS. 17 and 20 18
 Location identified from original bearing trees both of
 which are standing. The BT. Fir 18" dia. S.70°E., 52 lks.
 is now dead and was chopped out. Scribe marks in good
 condition. Set a 6"x6"x48" Cedar Post for the corner
 properly scribed and marked new B.Ts. as follows:
 Fir 12" Dia., N.37°E., 36 lks.
 Fir 30" dia., S.79°E., 65 lks.
 Fir 24" dia., N.32°W., 58 lks.
 Original B.T. remarked. RECORDED CORNER NO. 41
 June 19, 1939

SW. CORNER JAMES ODLE D.L.C. #41 19
 Location identified from x on rock 2 1/2 x 2 1/2 x 3' above the
 surface N.50°E., 13 lks., and both original bearing trees
 which are
 A Fir 24" dia., N.89°E., 16 lks.
 A Fir N.30°W., 3 lks.
 The original corner tree has been destroyed by fire only
 a part of the stump remaining. Drove a 4"x4"x36" post
 in the old stump and remarked the bearing object and both
 bearing trees. June 11, 1939

N.E. CORNER OF THE JAMES ODLE D.L.C. #41 20
 Original corner has been removed or destroyed. Location
 identified from an Oak 20" dia., S68°W., 25 lks., which
 is an original B.T. Has been chopped out but scribe marks
 are still visible. Oak S.10 1/2°E., 127 lks. has been cut
 but the old stump remains and agrees for bearing and
 distance. Set a sand stone 8"x10"x30" in a mound of
 rock for the corner. Chisled a A on top and CL. 41 on
 the SW. face. Marked RECORDED CORNER NO. 56
 An Oak 12" dia., which bears N.40°E., 25 lks.
 An Oak 12" dia. which bears S.6°W., 66 1/2 lks.
 for new bearing trees. June 21, 1939

S.E. CORNER OF THE JAMES ODLE D.L.C. #41 21
 S.E. Corner identified from an Oak which shows axe marks
 but is badly rotted and no scribe marks could be found.
 Using this as the original bearing tree which was an
 Oak 15" dia., S.48°W., 60 lks. it would place the S.E.
 corner N.89°47'E., 1935.8ft. from the S.W. corner of the
 claim and South 4878.5 ft. from the N.E. corner. This
 does not check the original lengths of these lines but
 does check the original bearing very close.
 Drove a 3/4"x24" pipe for the corner 18 ins. in the ground.
 A Fir 24" dia. bears S.70°E., 56 lks. blazed and scribed
 SE. D.L.C. 41 C.S.B.T.
 A Fir 50" dia. bears N.21°E., 83 lks.
June 22, 1939

N.W. CORNER OF SECTION 16 22
 Position identified from the stump of an old Fir which is
 presumed to be the 80" Fir S.60°E., 57 lks. as described in
 the original Gov't. field notes. This is the only evidence
 of such a tree which approximately agrees with the ties
 given in the notes of James Odle C.L.C. # 41 and the
 distance as called from the Calapooia Creek on the section
 line north. The 1/4 section and section corner North of
 this corner were both completely destroyed and the one West
 was in an old slashing. The 1/4 section corner and the
 section South of this corner had been destroyed. The 1/4
 corner East from this corner was located and had been
 recently renewed by Deputy County Surveyor Boyer. The ties
 to these adjoining corners are : 1/4 Corner 9 and 16 N.88°55'E.
 2592.1 ft. (recorded 89.85 chs.) N.E. Corner D.L.C. 41
 North 1321.23 ft. and East 359.3 ft. (recorded North 19.92 chs
 and East 5.83 chs.). Drove a 1"x72" pipe, 54" in the ground
 for corner. Blazed and scribed a Fir 18" dia., which
 bears S.18°W., 107.6 ft.
 An Oak 14" dia. which bears N.35°W., 115.5ft.
 An Oak 12" dia. which bears N.11°E., 115.3 ft.
June 22, 1939