

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 4 R. W. W. M.

S.W. CORNER OF SECTION 16. 23

✓ This corner was set from double proportional measurements from the nearest corner in each direction as provided for by law, its location having been entirely lost and obliterated. Drove a  $\frac{3}{4}$ "x36" pipe 26" in the ground for the corner, from which:

A Cedar 12" dia., bears S.36°W., 61.5 lks. 103

A Fir 56" dia. bears N.60°W., 107 lks.

both properly blazed and scribed. No other trees were close enough to be used for bearing trees. This corner is located above and in the clearing for the California-Oregon Power Co's. high tension power line. June 21, 1939

These corners were all renewed by Ben. B. Irving Dep. Co. Sur. in the course of a survey for the State of Oregon. Wit. N.E. Richardson Harvey L. Eppstein Jr., Robert Hellmwell

$\frac{1}{2}$  CORNER BETWEEN SECTION 16 and 17. 24

✓ This corner was set by proportional measurement between the N.W. and the S.W. corners of section 16, its location having been completely destroyed on the ground. Drove a  $\frac{3}{4}$ "x36" pipe for the corner, 30" in the ground piled rock around the pipe.

A Fir 12" dia. bears N.41°W., 43 lks. blazed and scribed  $\frac{1}{4}$  S 17 C.S.B.T.

June 22, 1939

SEC. COR. 7-8-17-18 25

✓ Find stump of 80" Fir, orig. B.T. N.80°W., 8 lks. Drove Fir Post--Renewed or remarked 40" Fir N.63°E., 154 lks. New B.T.'s.

Red Fir 18" dia. N.48°W., 38 ft.

A Fir 30" dia. S.70°W., 55 ft.

A Laurel 20" dia. S.55°E., 57 $\frac{1}{2}$  ft.

S.W. COR. ASA MOORE D.L.C. 51 26

✓ New B.T. for 24" Oak N.35°E., 124 lks. which fell down (on top new car). Set new B.T. in its place

W. Oak 30" dia. N.77°E., 106.0 ft.

Renewed from stump.

SE. COR. G. P. STRATTON. D. L. C. # 38 27

(Renewed from orig. B.T. N.53°E., 106 lks., 10" B. O.) Set Sand Stone Rock cross on top and marked new tree to replace one lost in N.W. Quadrant

Laurel 12" dia. N.5°W., 15 ft.

W. Oak 15" dia. S.37°W., 47 ft.

INTERSECTION OF E. AND W. MID-SEC. LINE SE. 18 WITH E. LINE DEARDORFF D.L.C. 28

Set Sand Stone Rock, Cross on top W. Oak 6" dia., N.60°W., 57 ft. #134

$\frac{1}{2}$  CORNER SECTIONS 1 and 2. 29

Renewed this corner from old Bearing trees. Marked

A 14" Fir N.36°00'W., 19.5 ft.

A 24" Fir S.68°30'E., 50.7 ft.

An 8" Oak S.56°00'W., 39.6 ft. old B.T. In good condition.

$\frac{1}{4}$  CORNER SEC. 23-26

Found a 30" snag with scribe  $\frac{1}{4}$ S visible. Two new BTs were marked and a stake set at the corner. These BTs are:

A 24" Cedar, Bearing N 5° W for 21.5 feet

A 9" Fir, bearing " 61° E for 31 feet

Dec. 1941  
Authur Boyer Dep.  
Wit. W.S. Creer  
Mr. Crowell  
C.S. FILE 35/61

N.E. Richardson D.C.S.  
E. S. Woodford  
May 1945.  
35/61

Glande Kerr, 2125  
July 23, 1951  
C.S. 40/344

RE-RENEWED, SEE CORNER NO. 103

RE-RENEWED, SEE CORNER NO. #134

RE-RENEWED, SEE CORNER NO. 68

30