

Douglas County Surveyor's Record of
Government Corners Renewed

25

T. S.

4

R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE., 97196

F. J. Cole, Deputy County Surveyor
May 4th, 1914.

With: Verner Abeene and C. J. Hunt.

Filed:
FB 39, page 34.
Vol. 2, page 256.

James W. Byron, Deputy County Surveyor
Survey for Wilby Lumber Co.
November, 1955.
County Surveyor's File No. 47/44.

N. W. COR. OF SEC. 1.

Renew corner from remains of orig. B. T.'s.

Set a post from which

Original B. T. an Oak 12" dia. brs. S. 37° E., 181 lks. 67

New B. T. - W. Oak, 6" Dia. brs. S. 42° W., 33 lks.

New B. T. - W. Oak, 9" Dia. brs. N. 54° W., 28 lks.

New B. T. - W. Oak, 9" Dia., brs. N. 30° E., 96 lks.

SEC. COR. N. SIDE OF SEC. 2.

NO TRACE OF CORNER FOUND - M.E.C. 32

Old trees not in evidence. Set a post from which: 6/10/63

A Cedar 14" in Dia., brs. S. 68° W., 57 lks. L.L.

A Fir 18" Dia., brs. N. 58° W., 87 lks. #142

Center $\frac{1}{4}$ corner of section 2.

Set 39.60 ch. south of $\frac{1}{4}$ sec. corner on N. boundary.

(Mid section lines run and intersected).

From which:

An Ash, 10 inches Dia., N. 51° W., 119 lks. dist.

A Maple, 36 inches Dia., S. 21° 30' E., 576 lks. dist.

Section corner to secs. 25, 26, 35 and 36.

Found both Cedar B.T.s as renewed by Ben B. Irving, reset 3 inch Ren. #2
by 3 inch post alongside. Found scribed part of Orig. 6" Cedar. 34

Set brass cap marked $\frac{26}{35}$ $\frac{25}{36}$ T25S R4W Co. Su. Office.

Blazed and scribed:

18 inch Cedar, N. 31° 30' W., 78.0 feet, mkd. S 26, T 25, R 4 W.

Rebark Scribe 48 inch R. Fir, N. 70° E., 19.8 feet, mkd. S. 25 C. S. B. T.

Section corner to secs 26, 27, 34 and 35.

Corner reset by double proportion measurement, using $\frac{1}{4}$ corner to North,
 $\frac{1}{4}$ corner to South, $\frac{1}{4}$ corner to West and Sec. cor. to secs. 25, 26, 35 & 36.

Set Brass Cap marked $\frac{26}{34}$ $\frac{27}{35}$ T 25, R 4 W, Co. Su. Office 1955.

Blazed and Scribed:

60 inch Cedar, N. 36° 08' E., 265.19 feet, mkd. S 26, C. S. B. T.

6 inch Laurel, N. 58° 47' E., 59.84 feet, mkd. S 26, C. S. B. T.

5 inch Laurel, S. 18° 24' 30" E., 15 feet, mkd. S 35, C. S. B. T.

No trees near in SW or NW quad.

$\frac{1}{4}$ sec. corner to secs. 26 and 35.

Corner set at midpoint and on true line between section corners.

Set iron pipe with Brass Cap mkd. $\frac{1}{4}$ S $\frac{26}{35}$ Co. Su. Office 1955.

Blazed and scribed:

10 inch Cedar, N. 33° 47' E., 255.01 feet, mkd. $\frac{1}{4}$ S 26, C. S. BT.

10 inch Cedar, S. 25° 31' 30" E., 60.29 feet, mkd. $\frac{1}{4}$ S 35, C. S. BT.

$\frac{1}{4}$ sec. corner to secs. 34 and 35.

Corner reset from original B. T. found, an 8 inch Cedar, now 24 inches,
which we opened and found $\frac{1}{4}$ S scribe, I rescribe $\frac{1}{4}$ S BT.

Set iron pipe with Brass Cap mkd. $\frac{1}{4}$ S $\frac{34}{35}$ T 25 S, R 4 W, Co. Surveyors
Office 1955.

Blazed and Scribed:

14 inch Ewewood, N. 10° 30' E., 43.8 feet, mkd. $\frac{1}{4}$ S 35, C. S. BT.

12 inch Cedar, N. 52° 40' W., 66 feet, mkd. $\frac{1}{4}$ S 34, C. S. BT.

$\frac{1}{4}$ sec. corner to secs. 27 and 34.

Corner renewed from original B Ts:

10 inch Cedar S. 58° W., 7.92 feet.

12 inch Cedar - stump only left, scribed BT. Also found broken
top of Cedar down hill (East) scribed $\frac{1}{4}$ S.

Set 5 inch X 5 inch Cedar post at corner from which:

18 inch R. Fir, S. 74° W., 47.5 feet, mkd. $\frac{1}{4}$ S 34 C. S. BT.

34 inch Cedar bears N. 21° E., 22.0 feet, mkd. $\frac{1}{4}$ S 27 C. S. BT.

BLM tag 100 feet West on logging road.

31

32

33

34

35

36

37

38