

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 4 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

39

$\frac{1}{4}$  sec. corner to secs. 26 and 27.  
Found original BT - 48 inch Cedar, S.10°E., mkd.  $\frac{1}{4}$  S.  
Set Brass Cap mkd.  $\frac{1}{4}$  sec. 27/26 T 25 S, R 4 W., Co. Surveyors Office 1955.  
Blazed and scribed:  
18 inch Cedar, N.87°E., 39.8 feet, mkd.  $\frac{1}{4}$  S 26, C. S. BT. 114  
8 inch Red Fir, S.44°W., 29.0 feet, mkd.  $\frac{1}{4}$  S 27, C. S. BT.

James W. Byron,  
Dep. County  
Surveyor.  
Nov. 4, 1955.  
C. S. File No.  
47/44.

40

Section corner to secs. 17, 18, 19 and 20.  
Found 2 orig. B. T.s:  
Fir, S.40°E., 64 lks.  
Fir, S.57°W., 62 lks.  
80 inch Fir down.  
Set 36 inch angle iron with brass cap at corner inscribed, Survey point -  
Wilford Haines # 239.

Wilford N. Haines Survey for Mt. Baldy Lumber Co.  
February 15, 1956.  
C. S. File No. W2 - 14.

41

$\frac{1}{4}$  corner to sections 17 and 20.  
Found scribed stake, original BT, S.70°E., 52 lks. (dead) and 30 inch Fir,  
S.79°W., 42.9 feet. Other 2 BTs down. REN. # 18 104  
Set 36 inch angle iron with brass cap inscribed, survey point - Wilford  
N. Haines # 239.

42

$\frac{1}{4}$  corner to secs. 19 and 20.  
Set 36 inch angle iron with brass cap incscribed, Survey point - Wilford  
N. Haines # 239, from the old BT in section 19.  
Scribed 30 inch fir, S.75°26'E., 42.0 feet.

43

$\frac{1}{4}$  corner to secs. 20 and 29.  
Found stumps of 2 original BTs.  
Set 36 inch angle iron with brass cap inscribed, survey point - Wilford  
N. Haines # 239.

44

$\frac{1}{4}$  corner to secs. 20 and 21. Fd. SEE M 93-19: M 94-54  
Found 1 inch by 3 inch channel iron and 2 BTs set by C. S. REN. # 17  
Set 36" angle iron with brass cap 4.73 feet east on fence line inscribed,  
survey point - Wilford N. Haines # 239.

45

Center  $\frac{1}{4}$  corner section 20.  
Set 36 inch angle iron with brass cap at intersection of N & S and E & W  
center lines inscribed, survey point - Wilford N. Haines # 239.  
Scribed:  
10 inch Inc. Cedar, West 16.5 feet.  
16 inch Inc. Cedar, S.33 $\frac{1}{2}$ °E., 39.9 feet.

F.B. 69  
H-69

46

S. E. corner D. L. C. No. 46.  
Corner renewed at old fence post. N. W. BT found shows old blaze but  
not cut out. Ben B. Irving used old fence post for corner on Fair Oaks  
cem. job.  
Set brass cap at corner mkd. S. E. corner D.L.C. 46, T 25 S, R 4 W.,  
County Surveyor's Office, 1956, from which:  
32 inch B. O. bears N.76°45'W., 46.5 feet scribed S.E. corner 99  
Cl. 46 CS BT.  
34 inch W. O. bears N.5°15'E., 65.0 feet scribed S. E. corner Cl. 46  
CS BT.

County Surveyor's  
Office.  
Sept. 17, 1956.  
C. S. File No. 47/133.  
C.S. 37/13

47

$\frac{1}{4}$  Section Corner to Sections 13 & 18. R. + 5 W.  
Found - Orig. 12" W. Oak, now 20" (down) S.11°E. 58.1 ft. I open & find  
good scribing  $\frac{1}{4}$ S".  
Stump Hole S.49°E. 49.5 ft. (Record 49°E. 49.5 ft.) #144  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1958  $\frac{1}{4}$  S13/S18 T25S  
R5W R4W.  
New BT's: 14" R. Fir bears N.67°W. 54.3 ft. scribed  $\frac{1}{4}$  S13 CS BT.  
15" W. Oak bears N.52 $\frac{1}{2}$ °E. 33.7 ft. scribed  $\frac{1}{4}$  S18 CS BT.

C. S. File No. 49/124

RE-RENEWED SEE CORNER NO. #144