

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 45 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

56

N. E. Corner D. L. C. No. 41.  
Found - Both Orig. BT's. & both BT's. recorded by B.B.Iring. *Rev. #20*  
Also find Stone set by B.B.I. out of place & not in  
ground. We use record bearing & dist. from Orig. BT's.  
to locate corner. We do not reopen Orig. S.W. BT. as  
it does show good scar.  
The S.E. BT. now stump only. Orig. BT's. check record.  
B.B.I. BT's. do not check record. We find them thus:  
12", now 12" W.Oak N.31 $\frac{1}{2}$ °E. 18.4 ft. record N.40°E. 16.5'.  
12", now 14" W.Oak S.7 $\frac{1}{2}$ °W. 53.6 ft., record S.6°W. 43.9 ft.  
Note - We find bottom of old pointed stake at corner & still in  
position.  
Set Brass Cap at Corner Mkd: County Surveyor's Office, 1961  
N.E. Cor. DLC 41 T25S R4W.  
New BT's: 12" W.Oak bears N.31 $\frac{1}{2}$ °E. 18.4 ft. scribed NE Cl 41 CS BT.  
10" W.Oak bears S.12°E. 26.7 ft. scribed NE Cl 41 CS BT.  
*(See Also #59)*

James W. Byron, Deputy  
Clete Putnam  
June 27, 1961  
C. S. File No. 49/124

57

$\frac{1}{4}$  Section Corner to Sec. 34, T24-4W., & Sec. 3, T25S-4W.  
Found - Old scribed Stake at Corner & Orig. 8", now 40" Fir S.11°E. 169.4 ft.,  
Opened several years ago, shows Orig. scribing " $\frac{1}{4}$ " &  
rescribing " $\frac{1}{4}$ ".  
Original West BT. not found.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961  $\frac{1}{4}$  S34 T24S  
S 3 T25S  
Corner in East West Fence Line.  
New BT's: 14" R.Fir bears S.43°W. 4.5 ft. scribed  $\frac{1}{4}$  S 3 CSBT.  
18" R.Fir (in Fence Line scribed above Fence) bears  
S.43°E. 3.0 ft. scribed  $\frac{1}{4}$  S34 CS BT.

James W. Byron, Deputy  
Clete Putnam  
July 10, 1961  
C. S. File No. 49/124

58

Sec. Corner Secs. 3 & 4, T25-4W, & Secs. 33 & 34, T24-4W.  
Found - Orig. 10", now 48" Fir N.78°W. 113.5 ft., shows bark  
scribing "BT", not old, probably Theil. This tree  
grew rapidly so no scar is apparent.  
Orig. 36", now 60" Fir Stump S.51°W. 139.9 ft., shows old  
bark scribing "BT44".  
Orig. N.E. BT. not found.  
Find old scribed Stake at Corner, Theils.  
Set - Brass Cap at Corner Mkd: County Surveyor's Office, 1961  $\frac{S33}{S4}$   $\frac{S34}{S3}$  T24S  
T25S R4W  
New BT's: 16" R.Fir bears S.25°E. 22.6 ft. scribed S 3 T25S R4W CS BT.  
14" R.Fir bears S.55°W. 23.0 ft. scribed S 4 T25SR4W CS BT.  
18" R.Fir bears N.35°W. 29.5 ft. scribed S33 T24SR4W CS BT.  
20" R.Fir bears N. 2°E. 11.0 ft. scribed S34 T24S R4W CS BT.

59

N. E. Corner D.L.C. No. 41 - Rock in Mound ← See Cor. #20/56

60

N. W. Corner D.L.C. No. 49 - 1" x 36" Steel Shaft with gear attached.

Set by  
Edwin S. Woodford.  
See Map  
File  
M 22 - 18

SEE REN. #121 → N. W. Int. Corner D.L.C. No. 49 -  $\frac{1}{2}$ " x 30" I. P.

61

SEE REN. #102 → N. - N.W. Corner D.L.C. No. 49 - 1" x 36" with gear attached.

62

63

Sec. Cor. to Secs. 5 & 4, T25-4W & Secs. 32 & 33, T24-4W.  
Found - 28" Rotted oak Stump S.53 $\frac{1}{2}$ °W. 128.7 ft. No scribe marks.  
28" W. O. N.38 $\frac{1}{2}$ °W. 55.4 ft. & chopped it open & fd. scribing.  
48" W. O. S.54 $\frac{1}{2}$ °E. 219.1 ft., shows good scar.  
No trace of other Bearing Trees.  
1" I. Rod and a Sandstone 9" x 16" x 6" at Corner.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  $\frac{S32}{S5}$   $\frac{S33}{S4}$   
T24-4W  
New BT's: 7" W.O. N.60°E. 19.0 ft. Mkd: T24S R4W S33 CS BT.  
9" D.Fir N.24°W. 55.2 ft. Mkd: T24S R4W S32 CS BT.  
7" D.Fir S.14°E. 46.5 ft. Mkd: T25S R4W S4 CS BT.  
5" W.O. S.41 $\frac{1}{2}$ °W. 28.7 ft. Mkd: T25S R4W S5 CS BT.

Milo E. Godfrey, Deputy  
V. Tracy and M. Stone  
May 10, 1963  
C. S. File No. 53/9