

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25. S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

69
Sec. Cor. to Secs. 2 & 3, T25-4W. & Secs. 24 & 35; T24-4W
Found - 20" W.Oak S.7 $\frac{1}{4}$ °W. 223.1 ft. (slope dist.) Cut open & fd. good scrbing.
20" W.Oak S.10°E. 429.0 ft. Opened & found good scribing "R4".
24" W.Oak N.5°E. 306.9 ft. (slope dist.) Opened & fd. good scribing.
No Trace of N. W. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's T24S R4W $\frac{S34}{S3}$ | $\frac{S35}{S2}$
Rocks piled below Pipe-Office, 1963 T25S
New BT's: 24" D.Fir S.75°W. 65.7 ft. Mkd: T25S R4W S3 CS BT.
34" I.Cedar N.51°W. 30.5 ft. Mkd: T24S R4W S34 CS BT, scribed above fence.
16" W.Oak S.50°E. 63.7 ft. Mkd: T25S R4W S2 CS BT.
Note - Corner lies on steep South slope, bedrock close to ground surface.
A fence corner, fences north, south & west is fastened to N.W. BT.
June 1963 - C.S. 53/9

70
Section Corner common to Sections 19 - 20 - 29 - 30.
Found - Corner Tree, uprooted & rolled downhill approximately
20 feet N. W. of corner.
20" Fir N.50°W. 20.5 ft., uprooted & down.
32" Fir N.51°E. 85.8 ft., uprooted & down, scribing visible
on face.
10" Fir S.19 $\frac{3}{4}$ °W. 104.3 ft., now dead snag, scrib. vis. on face.
22" D.Fir S.49 $\frac{1}{2}$ °E. 68.6 ft., alive & in good condition, scrib.
visible on partially healed face.
Set - (In hole left by uprooted corner tree) Brass Cap Mkd:
County Surveyor's Office, 1964 T25S R4W $\frac{S19}{S30}$ | $\frac{S20}{S29}$
New BT's: 14" D.Fir S.37°W. 78.8 ft. Mkd: T25S R4W S30 CS BT.
16" D.Fir N.20 $\frac{1}{2}$ °W. 47.5 ft. Mkd: T25S R4W S19 CS BT.
20" D.Fir N.80°E. 75.0 ft. Mkd: T25S R4W S20 CS BT.
Note - Corner lies on very steep west slope approximately 100 feet
West of top of ridge.
Feb. 27, 1964

MILO E. GODFREY, Deputy County Surveyor
Vernon Tracy and Mike Stone
June 1963 - Feb. 1964
C. S. File No. 53/47

71
 $\frac{1}{4}$ Corner to Sections 19 and 30.
Found - G.D.O. Brass Cap set in 1957.
22" Fir S.21°W. 21.8 ft, scribing visible, Tree alive
and in good condition.
30" Fir N.7°W. 33.0 ft., uprooted & down.
New BT: 6" D.Fir S.33°E. 28.0 ft. Mkd: $\frac{1}{4}$ S30 CS BT.
No suitable tree available north of line.
Feb. 27, 1964

72
 $\frac{1}{4}$ Corner to Sec. 35, T25-4W. & Sec. 2, T26-4W.
Found - G.L.O. Brass Cap set in 1957.
10" Fir N.60°E. 10.6 ft., is now dead snag, scribing visible.
12" Fir S.49°W. 9.5 ft., uprooted & down, scribing visible.
New BT's: 15" D.Fir S.16°E. 21.8 ft. Mkd: $\frac{1}{4}$ S 2 CS BT.
13" D.Fir N.70°W. 42.2 ft. Mkd: $\frac{1}{4}$ S35 CS BT.
Note - Corner is on point of small spur sloping south; approx. 25 ft.
South of wire fence running E. & W.; & approx. 75 ft. East of gate
where fence line crosses new logging road.
Aug. 24, 1964

73
Section Corner to Sections 2 - 3 - 10 - 11.
Stone 6" x 6" x 18" 14" underground in field.
48" Fir S.85°E. 9.00 chains - 36" Fir N. 8° E. 140.4 feet.
44" Fir N.60°W. 105.5 ft. - 8" Oak S.81 $\frac{3}{4}$ °W. 189.8 feet.
Nov. 1944

74
 $\frac{1}{4}$ Corner to Sections 3 and 10.
Stone 6" x 6" in Fence Line
36" Maple S. 56° E. 54 lks.
11/2/64 - SEARCHED FOR - NOT FOUND
Nov. 1944

BEN B. IRVING
FOR MANNING
Nov. 8, 1944
C. S. File No. 53/69