

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

93
 $\frac{1}{4}$ Corner to Sections 16 and 21.
Found - BLM Cadastral Brass Cap & both BT's., dead but standing:
13", now 13" W.Oak N.30 $\frac{1}{2}$ °E. 98.3 ft., never healed over, scribe visible.
12", now 14" Fir S.46°W. 61.1 ft. "S21 BT" visible on partially grown over face.
New BT's: 7" W.Oak S.81°E. 29.8 ft. Mkd: $\frac{1}{4}$ S21 CS BT.
6" D.Fir N. 5°W. 54.8 ft. Mkd: $\frac{1}{4}$ S16 CS BT.

FD. B.C.
5184 R. DALAN
M 96-54

94
 $\frac{1}{4}$ Corner Sections 28 and 27.
Found - BLM Cadastral Brass Cap, 1957 & BT's., as follows:
9", now 11" W.Fir S.20°E. 64.7 ft., partially grown over, We do not open.
7", now 7" W.Fir snag N.89°W. 4.6 ft., shows "S28 BT" scribe.
New BT.-115", Yew S. 44° W. 31.9 ft. Mkd: $\frac{1}{4}$ S28 CS BT.

95
Sec. Corner to Sections 27 - 28 - 33 - 34.
Found - BLM Cadastral Brass Cap, 1957 & BT's., as follows:
15", now 16" Cedar Stump N.26 $\frac{1}{2}$ °E. 20.5 ft., scribe visible on entire face, "T25SR4W S27 BT."
17", now 20" Cedar S.74 $\frac{1}{2}$ °E. 28.7 ft., All scribe visible.
18", now 20" D.Fir, dead & down, S.54°W. 54.1 ft., scribe not visible.
12", now 16" Cedar N. 3 $\frac{1}{2}$ °W. 66.0 ft. scribed "T25SR4WS28BT"
New BT's: 10" Cedar S.28°W. 48.5 ft. Mkd: T25S R4W S33 CS BT.
6" Cedar N.80°E. 23.4 ft. Mkd: S27 CS BT(only).

Vernon "Ray" Tracy
Mike Darby & Jack Barnett
January 1965
C. S. File No. 53/47

96
 $\frac{1}{4}$ Corner to Sections 22 and 23.
Found - BLM Brass Cap, 1957 & BT's. as follows:
13", now 14" Fir S.49 $\frac{1}{4}$ °E. 180.8 ft. Tree alive, did not open.
9", now 11" Fir Snag S.5 $\frac{1}{2}$ °W. 116.8 ft., shows scribe.
New BT: 11" D.Fir S.12 $\frac{1}{2}$ °W. 97.8 ft. Mkd: $\frac{1}{4}$ S22 CS BT.
Note - This corner lies 8.0 ft. East of N. - S. fence and 16.0 ft. south of small creek flowing N. W.

97
South 1/16 Sections 22 and 23.
Found - BLM Brass Cap mkd. 1957 & BT's. as follows:
14", now 18" Cedar Stump N.6 $\frac{1}{2}$ °E. 39.3 ft., shows "S1/16 S23 BT" scribe. Stump is 42" high.
15", now 16" Fir N.42 $\frac{1}{2}$ °W. 68.6 ft., face pitched over, "S 1/16 S2" visible.
New BT: 10" Cedar S.81°E. 31.1 ft. Mkd: S 1/16 S23 CS BT.
Note - Corner falls in N. - W. fence line.

98
S. E. Corner D. L. C. No. 39.
Found - Stumps of both Orig. BT's., as follows:
Orig. 30", now 42" Fir Stump N.40°W. 7.9 ft. Open & fd. scribe.
Orig. 15", now 21" Fir Stump N.70°E. 17.2 ft. Open & find "BT".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965
T25S R4W S E DLC 39
New BT's: 13" Cedar N.52°E. 40.8 ft. Mkd: SE DLC 39 CS BT.
16" Cedar S.65°E. 31.5 ft. Mkd: SE DLC 39 CS BT.

99
S. E. Corner D. L. C. No. 46.
Found - Brass Cap & one BT. as recorded Ren. #46.
34" W.Oak N.5 $\frac{1}{2}$ °E. 65.0 ft., shows good upper & lower scars. Do not open.
New BT: 11" D. Fir N.82°E. 159.7 ft. Mkd: SE DLC 46 CS BT.
Note - Brass Cap lays on E. edge of driveway to Fair Oaks Church, flush with ground. S. E. Corner of church bears N.42 $\frac{1}{2}$ °W. 66.2 feet.

RENEWED SEE CORNER NO. 119