

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 4 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Vernon "Ray" Tracy  
Mike Darby & Jack Barnett  
January & February 1965  
C. S. File No. 53/47

N. W. Corner D. L. C. No. 47. 100  
Found - Orig. 20", now 34" Oak N.7°E. 37.0 ft., prev. opened  
& shows faint "25" scribe.  
Other BT gone, find hole approximate location.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T25S R4W NW DLC 47  
New BT's: 11" D.Fir S.46°E. 78.2 ft. Mkd: NW DLC 47 CS BT.  
25" W.Oak N.32°W. 22.3 ft. Mkd: NW DLC 47 CS BT.  
The Sec. Cor. of Sections 5 - 6 - 7 - 8 bears East 241.5 feet.

FD. OK 11/8/67  
M 105-17  
D. BENITZ

S. E. Corner D. L. C. No. 49. 101  
Found -  $\frac{3}{4}$ " x 22" I. P. set loosely 12" in ground. Ren. No. 15,  
15", now 24" Cedar N.74 $\frac{1}{2}$ °W. 37.0 ft., "S" visible on broken stump  
and "C 49" scribed visible on chopped out log laying nearby.  
8", now 22" Cedar N.43 $\frac{1}{2}$ °E. 44.9 ft., stump 18" high, open  
& find "BT" scribe.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T25S R4W S. E. DLC 49  
New BT's: 31" Cedar N.80°W. 38.0 ft. Mkd: SE DLC 49 CS BT.  
(This tree is most southerly of a group of 3 from one trunk.)  
6" D.Fir N.40°W. 35.8 ft. Mkd: SE DLC 49 CS BT.

North N. W. Corner D. L. C. No. 49. 102  
Found - 1" Steel Shaft with gear attached, recorded Ren. #62.  
No trace of Original BT's.  
New BT's: 21" D.Fir N.64°E. 4.2 ft. Mkd: N. N.W. DLC 49 CS BT.  
10" D.Fir N.26°W. 17.3 ft. Mkd: N. N°W. DLC 49 CS BT.  
Note - This corner lies in E. - W. Fence approximately 100 ft.  
East of Fence Corner.

Section Corner to Sections 16 - 17 - 20 - 21. 103  
Found -  $\frac{3}{4}$ " x 38" I. P., out of ground & out of place. - Ren. #23  
No trace of BLM Brass Cap set in 1957.  
5", now 8" Fir N.62°E. 27.4 ft., lying face down.  
5", now 10" Fir S.15 $\frac{1}{2}$ °E. 23.8 ft., alive & healed over. Didn't open.  
15", now 17" Fir S.41 $\frac{1}{2}$ °W. 87.8 ft. alive & healed over. " "  
16", now 18" Cedar N.46°45'W. 91.7 ft., now 8 ft. high snag,  
"T25SR4WS17BT" scribe visible on partially grown over face.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1965  
T25S R4W S17 S16 S20 S21  
Set I.P. alongside.  
New BT: 6" D.Fir N.30°E. 15.0 ft. Mkd: T25S R4W S16 CS BT.  
No tree suitable to N.W.

FD. S.C.  
5/8/67 E.  
DOLAN  
M 76-57

$\frac{1}{4}$  Corner to Sections 17 and 20. 104  
Found - Haines' "T" Iron & BLM Brass Cap, 1957.  
21", now 24" Fir N.83°E. 98.7 ft., doan & dead, scribe visible.  
14", now 20" Cedar S.41 $\frac{1}{2}$ °W. 32.7 ft., scribe visible on  
partially grown over face, alive & in good condition.  
New BT: 26" Cedar N. 10° W. 55.1 ft. Mkd:  $\frac{1}{4}$  S17 CS BT.  
Note - Corner lies on edge of heavy reproduction area approximately  
200.0 ft. East of ridge top.

N. 1/16 to Sections 19 and 20. 105  
Found - BLM Brass Cap, 1957  
40", now 42" Fir N.30 $\frac{1}{2}$ °W. 62.0 ft., scribe visible on partially  
healed over face. Other BT. gone.  
New BT: 4" D.Fir S.72°E. 12.5 ft. Mkd: N 1/16 S20 CS BT.  
Note - This corner lies on steep E. slope approx. 50 ft. W. of ravine.

E. 1/16 Sections 17 and 20. 106  
Found - BLM Brass Cap mkd. in 1957, & both BT's. down.  
18", now 20" Fir N.3 $\frac{1}{4}$ °W. 97.4 ft., lying face up, scribe visible.  
17", now 22" Fir S.9°E. 39.6 ft., lying face down, scar visible.  
New BT's: 6" Laurel N.13°W. 19.2 ft. Mkd: E 1/16 S17 CS BT. (mkd. belw. fork)  
18" D.Fir S.62°W. 35.0 ft. Mkd: E. 1/16 S20 CS BT.  
This corner lies on top of small spur sloping S.