

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 4 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

128

1/4 Corner for Secs. 7 and 18.

Found - Possible orig. SE BT (?) Ground depression and parts of oak roots in place. Depression large enough to have had 40" oak in place. No other large trees in vicinity. No other evidence.

Note - Location found by proportioned location from State Forestry crew proportioned from W 1/4 of 18 and #133 NE sec. cor. Sec. 18. NW corner of Sec. 18 gone. Proportioned using record bearings & distances. Area has been reportedly logged & burned several times. Call to ridgetop fits well according to S.F. Location fits well on aerial E-W fence intersects road approx. 75 ft. south of approx location. S.F. location is at west edge of roadway. Orig. NE BT would fall in roadway.

I do not renew

1/18/74

1/4 Sec. Cor. Betw. Sec. 33, T 24 S, R5W, & Sec. 4, T25 S, R5W

127

Found: A Stone 5"x12"x24", firmly set, with a "+" chiseled on top. From which - An orig. 12" now 36" W. Oak bears S 31 1/2° W., 19.8 ft. alive and well healed.

We rescribe " 1/4 S4 CS BT" on a double blaze. At the corner point, we set a 1" x 30" I pipe with brass cap attached mkd.

DOUGLAS CO. SURVEYOR 1/4 T 24 S S 33 R S 4 5 T 25 S W

We place the stone alongside the brass cap. There are no other trees near. This corner lies in an old E-W fenceline. Compass Declination: 20° East.

128

Section Corner for Secs. 5 & 6; and Secs. 31 and 32, T24-4.

Set - 3/4" Iron Pipe by single proportion.

Found - Stone with X 10.0 ft. East of 1947 record. Ren. #2 of T24-4.

7/76

West 1/16 corner for Secs. 20 and 29.

Found - BLM 1957 brass cap properly marked on a 2" pipe 1 in. above ground. A 32" Fir snag, bears N.44 1/2° W., 28.8 ft. (Rec. 29.04 ft.) with well healed single blaze. Blaze pitched over. A 23" Fir stump bears S.22 1/2° W., 69.9 ft. Cut ow. No scribing visible.

Left cap in position.

New BT's-A 12" D. Fir, bears S.39° E., 47.65 ft. scribed "W 1/16 S29 CS BT" in double blaze.

A 9" Incense cedar, bears N. 7 1/2° E., 25.6 ft. scribed "W 1/16 S20 CS BT" in a double blaze.

10/3/78

1/4 Corner common to Sec's. 26 & 35.

Found - BLM B.C. at the 1/4 Cor. location, properly stmpd, appx 2" above grnd. Along Northerly side of B.C., is a 1" I.P. w/a County BC., properly stmpd., protruding 10" above ground. Ren. # 36.

BT's - 10" Cedar, now 24" Cedar w/well healed blaze bears N.31° E., 254.8-ft. (Rec. per Ren#36 is N. 33°47'E., 255.01-ft..per 1957 Resurvey is N.29°45'E., 254.8-ft.) Renewal #36.

13" Cedar, now a 24" stump about 6-ft. high w/well healed blaze bears N.40 3/4 °E., 331.3-ft. (Rec.N.39 1/2 °E., 335.3-ft.).

1957 Resurvey.

9", now 19" Cedar w/well healed blaze bears S.48 1/2 °E., 98.5-ft. (Rec. S.50°E.) Renewal#116.

Set - None set, but we do remove the County Surveyor B.C. mon. leaving the BLM mon. at corner position as found.

New BT's- 8" D. Fir dbl. blazed & scribed "1/4 S26 CSBT" bears N.49 1/2 °E., 13.1-ft.

8" D. Fir single blazed & scribed "1/4 S35 CSBT" bears West, 62.5-ft. This tree has logs lying around the base-blaze is centered app. 2 feet above ground.

New BO - Set an anle iron fence post 2.0-ft. West of monument.

11/16/81

130

Gary L. Langlitz  
P. Earle  
County Surveyor  
Office  
C.S. 56/43  
1/18/74

Gary L. Langlitz  
Clell E Goodwin  
A V Cangie  
M.L Ladig  
C.S. 57/34  
July 16, 1975

W. S. Barnes for:  
Richard McGarvey  
July 1976  
M 60 - 70

Karen Reed  
Douglas Co. Survey-  
ors Office  
S. J. Flauser  
Oct. 3, 1978  
C.S. 60/17

Larry E. Monrean  
Deputy Douglas Cou.  
Surveyors Office  
T.R. Plouff, witness  
November 16, 1981  
C.S. 61/29