

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 5 R. W. W. M.

✓ 1/4 COR. BET. SEC'S. 8 and 9. 10  
Renew from old B.T. Set in a 1" x 40" Iron Pipe and a  
4" x 36" Cedar Stake from which:  
A 24" Fir bears N.26°W., 8 lks.  
A 36" Madrone bears S.72 1/2°W., 45 lks.

✓ 1/4 COR BET. SECS. 7 and 18. 11  
Renew from old B.T's. Set in a 1 1/4" x 40" Iron Pipe from  
which:  
A 24" B. Oak bears N.45°W., 27 lks.  
A 20" B. Oak bears N.13 1/2°E., 20 1/4 lks.

✓ COR TO SECS. 20-21-28-29. 12  
Made diligent search for Cor. and found 3 old stakes in  
different stages of decay all bearing scribe marks. Stakes  
all lying together. I could find no trees to correspond  
with field notes. Set 4" x 5" x 48" Cedar post and mark  
new trees C.S.B.T.  
A B. Oak 15" in dia. N.15°30'W., 57.6 ft. *Revised*  
A B. Oak 12" in dia. N.71°30'E., 38.3 ft. *Correction*  
A Laurel 8" in dia. S.52°00'W., 59.0 ft. *F.B. 49/28*  
A Fir 48" in dia. S.47°E., 66ft. *99'*

✓ 1/4 COR. BET. SECS. 20 and 21 13  
Measured South on approximate Sec. line from Creek 15.00 chs.  
and found a 20" double oak with an old scar and which has  
been chopped out but shows no scribe marks. I ran from tree  
N.49°W., 429 ft. and found a 1 1/2 inch Iron Pipe from which  
the before mentioned tree bears S.49°45'E., 421 ft. No  
trace of other B.T's to be found. Mark the tree bearing  
scars C.S.B.T. and mark a new tree *After check of 6/5/54 Cole's Field Notes*  
A W. Oak 8" dia. S.79°W., 186ft. *F.B. 49/28*  
Erected mound of rock over pipe. *also see sketch in F.B. 49/28*

✓ 1/4 COR. BET. SECS. 22-23. 14  
Established this corner from the old B.T.s which are standing  
but dead and rotten. Scribe marks visible on tree S.E. trees  
check for direction and distance. Set a 5" x 5" x 48" Oak  
Stake from which New trees  
A Fir 16" in dia. S.59°30'E., 20.5 Ft. mkd. C.S.B.T.  
A Fir 16" in dia. S. 71°W., 51.5 ft. Mkd. C.S.B.T.

✓ SEC. COR. TO SECS. 22-23-26-27. 15  
Found two original B.T's. broken off about 6 ft. above the  
ground. Old scribe marks visible. Other trees down and  
slid down hill. Set a Maple stake 6" x 6" x 40" from which:  
Original B.T's. bear N.33 1/2°E., 12.6 ft.  
S.87°E., 13.2 ft.  
Mark new trees  
A Fir 26" dia. bears N.49 1/2°E., 50.3 ft.  
A Fir 50" dia. bears N.33°W., 44.0 ft.  
A Fir 24" dia. bears S.42 1/2°W., 16.6 ft.  
A Fir 24" dia. brs. S.49°30'E., 36.6 ft.

✓ 1/4 SEC. COR. BET. SEC'S. 23-26. 16  
Renew Cor. form original B.T. S.66°W., 52.8 ft. Old tree  
dead scribe marks visible. Set 4" x 4" x 40" Oak post from  
which a pit where other B.T. has stood bears N.57°W., 24.2 ft  
Mark new trees  
A W. Oak 15" dia. S.79°E., 129.6 ft.  
A W. Oak 6" dia. S.12°E., 49.0 ft.

✓ RENEWED COR. OF SECS. 26-27-34-35. 17  
I renewed the cor. from original B.T's. A 7" Laurel stand-  
ing dead bearing scribe marks. Set a Fir Post properly  
marked from which orig. B.T. Laurel 7" N.77°E., 42.2 ft.  
Laurel N.55°W., 19.8 ft.  
remaining of orig. B.T. S.50°W., 19.8 ft.

F.C. Freear Dep. Co.  
Mar., 1919  
Wit.  
R.L. Stearns  
Bob Davis

R.M. 1-4

Nov. 1920  
J. W. Cole Dep. Co. Sur.  
L. H. Smick chain  
P. D. Wolford chain

F.B. 49/28

F.B. 49/31

F.B. 49/32

F.B. 49/33

J.W. Cole  
N.E. Richardson  
Sept. 2, 1925.