

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

39

Section corner to secs. 2 & 3, T 25 S., R 5 W., and secs. 34 & 35, T 24 S., R 5 W.

Found:

Ash tree (now 18 inches) with scribe marks facing corner position.
24 inch W. Oak with evidence of old face but face destroyed some years ago.

Measured 36.6 feet from ash tree and 45.6 feet from Oak. At the intersection of these two distances, I get a needle bearing of S.1½°E., to the Ash tree and N.80½°W., to the Oak. Since the Oak has a very bushy top and shows no evidence of another tree growing close to it, I assume it to be the B. T. set by Frear and Boyer. Also, corner position lines up with N. & S. fence across main road.

Set 1 inch iron pipe with Brass cap mkd. County Surveyors at corner position.

T24S R5W

34 | 35

312

T25S R5W

Office

83

Rescribe:

24 inch W. Oak, N.80½°W., 45.6 feet (measured to face) T24S, R5W., S 34 CS BT.

Scribe:

36 inch Maple, N.11°E., 202 feet (to center of tree) T24S, R5W S 35 CS BT.

James W. Byron, Deputy County Surveyor
March 13, 1957.
C. S. File No. 47/164.

40

¼ corner to sec. 3, T25S, R5W., and sec. 34, T24S, R5W.

Found: 16 inch rotted W. O., S.45½°W., 448 feet, down in creek- no scribing found. Also fd. shell of old pine stump, S.9½°W., 650 feet- no scribing found. Found also ¾ inch iron pipe at corner - BTs check for bearings and distance.

Set an iron pipe with brass cap at corner alongside ¾ inch iron pipe. I mark brass cap ¼ S 34 T 24 S R 5 W., County Surveyor's Office, 1957.

3 T 25 S

Blaze and scribe two trees:

22 inch Maple, N.73½°E., 537.3 feet mkd. ¼ S 34 T24S, R5W, CS BT.
40 inch W. O., S.35½°W., 551.6 feet mkd. ¼ S 3 T25S, R5W, CS BT.

James W. Byron, Deputy County Surveyor
May 10, 1957.
C. S. File No. 47/192.

41

S. E. Corner of D. L. C. #37.

Found - 2" Iron Pipe at Corner under E. W. Fence, 12" under surface, Checks 180 ft. West to Creek.

New BT's: 9" Ash bears S.39½°W. 10.2 ft. scribed S.E DLC 37 CS BT.
12" Ash bears N.78°E. 14.0 ft. scribed S W DLC 37 CS BT.

88

J. Byron
M. Godfrey
S. Bilow
For C. Wahl
June 4, 1958
C.S. File #49/96
M 10-36

42

Renew Township Corner Twp. 24 & 25 S., R's. 4 & 5 W.

Found - Laurel Tree, now 30" diam., standing but dead. Chopped open & found good scribing "BT" (N.41°E. 13.2 ft.)

Laurel Tree, standing & alive, but rotted out inside, now 40" diam. N.74°W. 207.9 ft.

Stump Hole S.22°E. 25.7 ft.

Oak Tree (dead & down), now 16" diam. S.22°W., instead of S.29½°W. 82.5 ft., chopped out upper blaze & found reverse scribe "R5W T25S & S".

T24S

S36 | S31 R4W

S 1 | S 6

T25S

Set Brass Cap at Corner Mkd: County Surveyor's R5W

FD. 7/9/54
B. H. H. 17/10/54
M. 9/2/54

New BT's: 8" W. Oak S.52½°W. 24.4. ft. mkd. T25S R5W S 1 CS BT.
10" W. Oak S.44°E. 45.0 ft. mkd. T25S R4W S 6 CS BT.
8" W. Oak N.48°W. 15.6 ft. mkd. T24S R5W S36 CS BT.
7" W. Oak N.15°E. 25.9 ft. mkd. T24S R4W S31 CS BT.

James W. Byron, Deputy
Milo Godfrey
S. A. Bilow
December 2, 1958
C. S. File No. 49/124