

**Douglas County Surveyor's Record of
Government Corners Renewed**

25 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

49

$\frac{1}{4}$ Sec. Cor. to Sec. 2, T25S R5W, & Sec. 35, T24S R5W.
Found - 14"; now 20" B.Oak N.88°E. 26.7 ft. (Stewart's BT.),
I open & find good reverse scribing "T".
Also find auto Spring dozed out of ground by near corner.
Set Brass Cap at Corner Mkd: County Surveyor's $\frac{1}{4}$ $\frac{S35}{S2}$ T24S R5W
Office, 1960 T25S
New BT's: 10" W.Oak bears N.46°E. 15.0 ft. scribed $\frac{1}{4}$ S35 CS BT.
8" R.Fir bears S.58°E. 41.6 ft. scribed $\frac{1}{4}$ S 2 CS BT.
E. W. Fence 8 feet South.

C. S. File No. 49/124

50

Section Corner to Secs. 4 & 3, T25S R5W, & Secs. 33 & 34, T24S R5W.
Found - $\frac{3}{4}$ " I. P. at Corner
New 28" Oak N.73°E. 33.8 ft. shows good scars.
No Brass Cap Set
New BT's: 10" Laurel bears N.29°W. 20.0 ft. scribed T24S R5W S33 CS BT.
18" Fir bears S.22½°E. 58.0 ft. scribed T25S R5W S3 CS BT.
Note: 4 way fence corner is 12' North.

Sec Ren. #46A

#148

*FD 11/87
M 101-30
M. Helm Burger*

RE-RENEWED, SEE CORNER NO.

51

Township Corner $\frac{S36}{S1} | \frac{S31}{S6}$ T24S R6W R5W T25S
Found - Remains of all 4 Original B.T's:
S.W. & N.E., now down, S. E. BT., now snag, outside rotted off.
N.W. BT., standing, center rotted.
All check record, no scribing found.
Set Brass Cap at Corner Mkd: $\frac{S36}{S1} | \frac{S31}{S6}$ T24S R6W R5W T25S County Surveyor's Office, 1960
New BT's: 13" Laurel bears S.59°W. 51.6 ft. scribed S1 T25S R6W CS BT.
6" B. Oak bears S.64°E. 18.9 ft. scribed S 6 T25S R5W CS BT.
14" Laurel bears N.19°E. 20.1 ft. scribed S31 T24S R5W CS BT.
26" W. Oak (Orig) N.69°W. 50.8 ft. scribed S36 T24S R6W CS BT.
Note - See signed statement by Harry Bainbridge in file.

James W. Byron, Deputy
Milo Godfrey
Clete Putnam
March 17, 1960
C. S. File No. 49/124

RE-RENEWED, SEE CORNER NO.

52

Section Corner to Sections 3, 4, 9, and 10.
Found - Orig. 7", now down, 10" W. Oak S.34°W. 26.4 ft. I open & find good scribing "T".
Orig. 14", now 30" W. Oak, shows old axe work, center rotted, no scribing, N.45½°E. 60.1 ft.
Laurel Stump that checks for S.E. BT.
No trace of N.W. BT. found.
Also find Stone with + on top, at Corner.
Set Brass Cap at Corner Mkd: County Surveyor's $\frac{S4}{S9} | \frac{S3}{S10}$ T25S R5W
Office, 1960
New BT's: 7" W.Oak bears S.54°W. 28.4 ft. scribed S 9 T25S R5W CS BT.
7" W.Oak bears S.43°E. 18.0 ft. scribed S10 T25S R5W CS BT.
5" W.Oak bears N.79°E. 6.8 ft. scribed S 3 CS BT.
5" W.Oak bears N.63½°W. 38.0 ft. scribed S 4 CS BT.

April 20, 1960 C. S. File No. 49/124

53

Section Corner to Sections 2, 3, 10, and 11.
Found - Orig. 12", now 22" W.O. S.23°E. 35.0 ft., I open & find good scribe marks "S".
Orig. 20", now rotted B.O. Stump, show old axe work, N.86°W. 32.3 feet.
No trace of Orig. N.E. or S.W. BTs. found.
Also find 2" x 3" x 24" Stone at Corner.
Set Brass Cap at Corner Mkd: County Surveyor's $\frac{S3}{S10} | \frac{S2}{S11}$ T25S R5W
Office, 1960
Reset Corner Stone alongside Brass Cap.
New BT's: 9" R.Fir bears S.75°E. 23.3 ft. scribed S11 T25S R5W CS BT.
7" R.Fir bears S. 7°W. 41.7 ft. scribed S10 T25S R5W CS BT.
8" R.Fir bears N.67°W. 14.3 ft. scribed S 3 T25S R5W CS BT.
11" R.Fir bears N.30°E. 49.7 ft. scribed S 2 T25S R5W CS BT.