

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 5 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

122

^{FO. OK 2/91}
^{M 111-45}
1/4 Corner for Sections 15 and 22.
This Corner set from survey RM 2 - 38
Set - Brass cap at 1/4 Cor. mkd. County Surveyor's Office T 25 S R 5 W
1973 1/4 S 15
S 22

New Bearing Objects - SE Corner of cement pad of well house,
N. 89°W., 45.9 ft.
5/8" I. Rod, S. 7°E., 21.6 ft.

Not - This corner falls in old N-S fence post line (no fence).

Cooper Creek survey for Doug. Co.
John M. Powell, Co. Surveyors Office
J. Heritage
G. Commons
C.S. File 56/28 RM 2 - 38
February, 1973

123

1/4 Corner for sections 22 and 27.
This corner set from survey RM 2 - 38
Set - Brass cap at 1/4 Cor. mkd. County Surveyor's Office T 25 S R 5 W
1973 1/4 S 22
S 27

New BT's - 8" D. Fir, N. 80°W., 23.4 ft. scribed 1/4 S22 CS BT.
5" D. Fir, S. 54°W., 11.7 ft. scribed 1/4 S BT.

124

1/4 Corner for Sections 21 and 22.
This corner set from survey RM 2 - 38
Found - 5/8" Iron rod single proportioned in by B. Rogers. See
survey No. 55/289.

Set - County Surveyor's Brass Cap at 1/4 Corner.

T 25 S R 5 W
1/4 S 21 S 22
1973

New BT's - 8" D. Fir, N. 31°E., 14.5 ft. Scribed 1/4 S22 CS BT.
12" D. Fir, S. 78°W., 38.4 ft. Scribed 1/4 S21 CS BT.

3/19/73

JAN 76

125

1/4 Corner for Section 4 & 5

Found: An axle set flush in the ground approx. one foot south of a fence
corner of fences running North, South and East. (See Ren. #26)

From Which: A 14" now 32" I. cedar bears S 70°E., 60.7 ft. and
A 8" now 20" B. Oak bears S 12°W., 37.6 ft.

We find no orig. evidence. This corner lies approx. 50 ft. east of a
farm house.

Gary L Langlitz
Clell E Goodwin
A.V. Cangie
M. Lenora Ladig
7/1/75
C.S. 57/34

126

1/4 Sec. Cor. Betw. Sec. 33, T24S, R5W, & Sec. 4, T25 S, R5W. Ren#28-
Found: A stone 5"x12"x24", firmly set, with a "+" chiseled on top
From which- An orig 12" now 36" W. Oak bears S 31 1/2°W., 19.8 ft.
Alive and well healed.

We rescribe " 1/4 S 4 CS BT" on a double blaze.

At the corner point, we set a 1"x 30" I. pipe with brass cap attached mkd.

T 24 S
DOUGLAS CO. SURVEYOR
1975 1/4 S 33 R
S 4 5
T 25 S W

We place the stone alongside the brass cap. There are no other trees near.
Compass Declination: 20° East, This cor. lies in an old E-W fence line.

7/16/75
C.S. 57/34

127

East 1/16 Corner Sec. of S5 T25-5 & S 32 T24-5

Corner Location determined by single proportionate measurement.

At the corner point, we set a 1"x24" I. Pipe with brass cap attached: Mkd:

T 24 S R
DOUGLAS CO SURVEYOR
1975 E 1/16 S 32 5
S 5 W

7/31/75
C.S. 57/34

And mark the following bearing tree:

A 12" W. Oak bears S 67 1/2°E., 32.2ft. scribed: "E 1/16 S5 CS BT" on a
double blaze.

Note: This corner is located approx. 14ft. north of a fence corner.

Compass Declination: 20° East