

Douglas County Surveyor's Record of  
Government Corners Renewed

T 25                      T. S.                      R 5                      R. W. W. M.

FOKE-CHAPMAN CO., EUGENE, ORE. 21881

Douglas County  
Surveyors Office  
Randall Smith  
Terrie Franssen  
June 28, 1990  
C.S. 64/9

Section Corner for Secs. 35 and 36; and Secs. 1 & 2 of T.26-5  
Found - A 2½" dia. 1960 DCSO brass cap on a 1¼" O.D. iron pipe,  
         protruding 17" above ground.                      Ren. #72  
         24" now 54" dia. D. fir with a fully healed previously opened  
         blaze bears S.42½°E., 4.6 ft. (agrees w/rec.) Orig. BT.  
         10" now 12" dia. down and rotted madrone bears N.7½°E., 63.4 ft.  
         Orig. BT.  
         20" now 40" dia. 25 ft. high madrone snag with a rotted center  
         bears N.40½°W., 55.5 ft. (Rec. N.40½°W, 58.1 ft.) Orig. BT.  
         18" now 27" dia. D. fir with a fully healed double blaze, bears  
         N.51°E., 12.5 ft. (agrees with BLM rec.) Ren. No. 72  
         11" now 16" dia. maple with a fully healed double blaze, bears  
         N.37°W., 10.1 ft. (agrees w/rec.) Ren. No. 72  
         10" now 12" dia. down D. fir with a fully healed double blaze  
         root hole bears S.20°W., 58.7 ft. (agrees w/BLM rec.) Ren. #72  
New BT - 10" dia. D. fir double blazed and scribed "T26S R5W S2 CS BT"  
         bears S.16½°W., 50.5 ft.

151

6/28/90

152