

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 6 R. W. W. M.

CONT. - - An Ash 16" diam., bears S.25°W., ^{26.7}26.7 ft. #32
Both blazed and scribed Cl. 47 and 48 and C.S.B.T.

✓ INTERIOR ANGLE CORNER ON THE WEST BOUNDARY OF THE E. WILLIAMSON D.L.C. NO. 48 33

This corner is located at an anchor post and fence corner. The bearing trees as set by Surv. Briggs were identified and checked for bearing and distance. One had been cut and sprouted but when the old stump was chopped out the scribe marks were plain. Drove a $\frac{3}{4}$ " x 36" Iron Pipe for the corner from which:

- An Oak 8" diam. bears S.24°E., 16.6 ft.
- An Oak 18" diam. bears N.12°W., 23 ft.

Both blazed and scribed Cl. 48 C.S.B.T. This is identical with Ext. angle corner on the South Boundary of D.L.C. 47.

✓ EXTERIOR ANGLE CORNER ON WEST BOUNDARY OF THE E. WILLIAMSON D.L.C. NO. 48. 34

All traces of this corner have been destroyed. It's position comes in the edge of a prune orchard and was located by measuring 54.1 ft. (82 lks.) North of the N.E. Corner of the Jos. Cline D.L.C. # 49 which is a Sand Stone 5" x 12" x 12" above the ground as described in the original field notes. Drove a $\frac{3}{4}$ " x 36" Iron Pipe for the corner there were no trees available which were suitable for use as bearing trees.

✓ N.E. CORNER OF THE JOS CLINE D.L.C. NO. 49 35

The Sandstone 32" x 12" x 62" above ground was in place as described in the original field notes. No suitable bearing trees were available. Drove a $\frac{3}{4}$ " x 36" Iron Pipe along side the corner rock. This corner is located in a fence angle alongside the county road between Oakland and Elkton on the West side of Calapooia Creek. - SEE FOUND C.S. 44/123

✓ N.W. CORNER OF THE J. W. KNOTT D.L.C. NO. 58. 36

Original stone in place, all bearing trees destroyed. Drove an Iron Pipe $\frac{3}{4}$ " dia. alongside stone. 159
An Ash 8" diam. bears N.50°E., 35 ft. blazed and scribed N.E.Cor. Cl. 58 C.S.B.T.

✓ S.W. CORNER OF THE J. H. MEDLEY D.L.C. No. 46 37

All evidence of the original Corner destroyed or obliterated. A $\frac{3}{4}$ " x 36" Iron Pipe set for the corner using a tie given in the deed of property to G. M. Leeper from bearing tree (now down and rotten) given as the corner on the South Boundary of the County Road. 158
An Oak 10" diam. bears N.8°E., 94 ft. Blazed and scribed S.W. Cor. Cl. 46 C.S.B.T.

✓ COR. N. SIDE SEC. 5. 38

24" Alder S.50°20'W., 49.5 ft. still standing but partly decayed, found 5"x5"x18" Rock. New trees set: 114
8" Fir N.72°W., 37.7 ft.
8" Forked Ash S.57°E., 35.3 ft.

✓ COR. BET. SECS. 4 and 5. 39

Set $1\frac{1}{2}$ " Iron Bar. Marked new trees:
18" Black Oak S.27°E., 131.5 ft.
18" White Oak N.85 $\frac{1}{2}$ °E., 145 ft.

✓ CEN. SEC. 5. 40

Set $\frac{1}{2}$ " G. I. Pipe from which:
26" Fir bears S.8°E., 72.2 ft.
26" Fir bears N.37 $\frac{1}{2}$ °E., 63.0 ft.

Ben B. Irving D.C.S.
 Witness N. E. Richardson
 Jas McHughill
 C.S. FILE 111-10
 160

A. Boyer
 Willis K. Ausland
 Ore. State Dr.
 Jan. 1942
 C.S. FILE 36/18