

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 6 R. W. W. M.

Renew M. E. Corner D.L.C. 38. - FOUND O.K. APRIL, 1964 **61**
Found - Now 28" B.O. Stump S.38°W. 28.7 ft. I open & find good
scribing "BT".
Corner falls on bank slope. I do not find Pipe set by B.B.I. *REN #1*
Set Brass Cap 160 ft. South of N.E. Corner D.L.C. 38 Mkd. Cap,
County Surveyor's Office, 1958 160 ft. North to N.E. Corner
D.L.C. 38 T25S R6W W.C.
New BT's: 20" B.Oak bears S.46°E. 17.5 ft. scribed W. C. NE DLC 38 CS BT.
35" Maple bears N.27½°E. 45.7 ft. scribed W.C. N.E.DLC 38 CS BT.
See Sketch in File - - - - -

James W. Byron
Milo Godfrey
S. A. Blilow
August 22, 1958
C.S. File No. 49/76

Section Corner to Sections 4, 5, 8, & 9. **62**
Found - All four Orig. BT's.
Orig. 15", now 24" W. Oak S.31½°W. 50.2 ft., shows old
scar, center rotted.
Orig. 12", now 24" Oak Stump N.27½°E. 26.4 ft., shows
good reverse scribing inside Stump "BT".
Remains of old Oak Stump that checks bearing & distance ///
for Orig. S. E. & N.W. BT's.
Set Brass Cap at Corner Mkd:

| | | | |
|---|---|---|---|
| S | 5 | S | 4 |
| S | 8 | S | 9 |

 T25S R6W County Surveyor's
Office, 1958
New BT's: 7" R. Fir bears N.10°E. 55.4 ft. scribed S 4 T25S R6W CS BT.
14" W. Oak bears S.46°E. 58.3 ft. scribed S 9 T25S R6W CS BT.
10" W. Oak Bears N.49°W. 17.9 ft. scribed S 5 T25S R6W CS BT.
24" W. Oak bears S.32°W. 52.0 ft. scribed S 9 T25S R6W CS BT.

James W. Byron
Milo Godfrey
S. A. Blilow
November 12, 1958
C. S. File No. 49/123

¼ Section Corner to Sections 7 & 18. **63**
Found - Both Orig. BT's:
Orig. 40", now 48" Fir Stump N.27°W. 11.9 ft. Tree cut
10' down hill shows good bark scribing "1/4 S".
Orig. 60", now 66" Fir S. 5°W. 21.8 ft., shows faint 146
bark scribe "1/4 S".
Set Brass Cap at Corner Mkd:

| | | |
|-----|---|----|
| 1/4 | S | 7 |
| 1/4 | S | 18 |

 T25S R6W County Surveyor's
Office, 1958
New BT's: 66" W. Fir S. 5°W. 24.3 ft. scribed 1/4 S18 CS BT (bark Scbd)
7" W. Fir N. 7°E. 4.8 ft. scribed 1/4 S 7 CS BT.

¼ Section Corner to Sections 8 & 9. **64**
Found - Germond's 40" Oak, S.26½°W. 35.0 ft., now stump, good
scribing "1/4 S". (SEE VOL. 2 PG. 157)
18" Oak Stump that checks bearing & distance for Orig. #191
S.E. BT (Stump low cut, no scribing found).
I do not find Stone set by Germond.
Set Brass Cap at Corner Mkd:

| | | | | |
|-----|---|---|---|---|
| 1/4 | S | 8 | S | 9 |
|-----|---|---|---|---|

 T25S R6W County Surveyor's
Office, 1958
New BT's: 12" R. Fir bears N. 8½°E. 21.6 ft. scribed 1/4 S 9 CS BT.
8" W. Oak bears N.68½°W. 60.3 ft. scribed 1/4 S 8 CS BT.

¼ Section Corner to Sections 7 & 8. **65**
Found - Germond's 50" Fir, now 61", N.60°W. 17.8 ft., good blaze,
no scribing found.
Completely rotted stump N.52°E. 10.6 ft., pitched over
sliver from face of this tree scribed "1/4 S8 BT" was stuck
in fence beside remnant of old stump.
Part of old squared Oak Post (no scribing visible) lying
on ground alongside of Corner.
Set Brass Cap at Corner Mkd:

| | | | | |
|-----|---|---|---|---|
| 1/4 | S | 7 | S | 8 |
|-----|---|---|---|---|

 T25S R6W County Surveyor's
Office, 1958
New BT's: 13" D. Fir N.86°E. 10.7 ft. "1/4 S8 CS BT."
11" D. Fir N.30°W. 32.8 ft. "1/4 S7 CS BT."

COR. LIES IN FENCE CORNER - FENCES E. N. & S.
& DIRECTLY ON TOP OF RIDGE.
ALL B.T.'S BURNED
& DEAD. OCT. 16, 1962
M. E. H. - C. E. 49/123