

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 6 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

N. E. Corner D. L. C. No. 47.

Found - Pile of Broken Sandstone Rocks at Corner. *REN #54*
W. Oak Stump, now 36", N.14°W. 197.3 ft. - found scribing
"CS BT" facing N.82°E. (see record of survey by Briggs,
1891). South portion of Stump gone.
Stump Hole with portions of Oak Stump in place N.1½°E.
244.2 ft. Too far gone to find any markings.

Set - Iron Pipe with Brass Cap Mkd: County Surveyor's T25S R6W
in mound of rocks Office, 1961 *D.L.C. #47 / N.W. / D.L.C. #46*
New BT's: 8" W.Oak N.80°E. 21.0 ft. Mkd: DLC 46 N.W. C. CS BT.
12" W.Oak N.6°W. 153.3 ft. Mkd: T25SR6W DLC #47 NEC CS BT.
Fence Corner bears S.70°W. 6 ft. Fences South & East.

Milo E. Godfrey, Deputy
Vernon Tracy
Clete Phnam
Sept. 5, 1961
C.S. File No. 49/123

73

S.W. Corner D. L. C. No. 56.

Found - ¾" Rod at Corner & W. Oak, now 46", N.16°W. 115.5 ft. Had been
opened previously, but not deep enough, chopped deeper & *REN #46*
exposed old scribing on old face. "R" legible. (Orig. BT.)
Remains of rotted Oak Stump N.21°W. 114.2 ft. Too far gone to
find any markings. (Orig. BT.)
W. Oak, now 42", N.57¼°E. 81.5 ft., shows good axe scar.
No trace of tree reportedly marked in 1951, 10" Y.Oak N.38°E. 31.7 ft.

Set - Brass Cap for Corner alongside Rod Mkd: County Surveyor's
Office, 1962 T25S R6W S.W. D.L.C. 56 L".

New BT's: 15" W.Oak S.30°W. 19.3 ft. Mkd: SW D.L.C. 56 CS BT".
7" W.Oak N.73°E. 24.8 ft. Mkd: SW D.L.C. 56 CS BT.

Fence Corner, fences N. S. & E. bears N.56°W. 11.5 ft.

S. E. Corner D. L. C. No. 57.

Found - Sandstone, set firmly in ground, 6" x 10" x 18" above ground.
Chisled on N.W. face of rock, "T25 RLW J N Smith."
Old Oak Stump N.88°W. 47 lks. (not 411 lks.) Stump too badly
decayed to find scars or scribing. Rock leaning badly. I
straighten it up & Mark "X" on top (2" diam.)

New BT's: 10" D.Fir S.55°E. 14.4 ft. Mkd: SE DLC 57 CS BT.
7" B.Oak N.34°W. 32.3 ft. Mkd: SE DLC 57 CS BT.

Corner lies 3 feet East of N. & S. fence line.

N. E. Corner D. L. C. No. 57.

Found - Sandstone 20" x 14" x 6" (measured above ground) firmly set
in ground at corner. I mark "X", 2" diam. on top of Rock.

New BT's: 8" W.Oak N.19°E. 145.3 ft. Mkd: N.E. D.D.C. 57 CS BT.
28" W.Oak N.72°E. 214.9 ft. Mkd: N.E. D.L.C. 57 CS BT.

Corner lies in E. & W. fence line. Fence Corner - Fences E. W. & North
bears West approx. 135 feet. *FD. "C 57" ON S.E. FACE OF ROCK*

N. W. Corner D. L. C. 57.

Found - 24" W.Oak N.83¾°W. 70.8 ft. scribing still visible, not
completely healed over. *REN #48*

12" Ash N.56½°E. 47.0 ft. scribing still visible. Scar not healed.
Road has been widened. Corner Rock not found. Corner falls in East edge
of travelled portion of road as it is now.

Drove ¾" Steel reinforcing Road at Corner. BT's, still in good condition.

1-26-71 - FOUND O.K. V.R.T. C.S. 49/123

Corner Common to

S.E. D.L.C. No. 44 |
N.E. D.L.C. No. 55 |

Found - Flat Slab of Sandstone 18" x 12" x 3", firmly set in gound at
corner. Chisel marks on top edge looks like "JK".

Old BT's, same as for S.W. Corner D.L.C. No. 56.
20" W.Oak, now 46", N.20°W. 66.0 ft., found scribing.
Oak Stump, Old, N.25°W. 66.0 ft.

New BT's: 24" W.Oak N.79°W. 39.0 ft. Mkd: S.E. D.L.C. 44 CS BT.
22" W.Oak S.79°E. 19.2 ft. Mkd: N.E. D.L.C. 55 CS BT.

Brass Cap at S.W. Corner D.L.C. No. 56 bears S.9°E. 48.9 feet.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July 19, 1962
C. S. File No. 49/123

74

75

76

77

78