

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

N. W. Corner, most Northerly, of D. L. C. No. 51. 79
Found - $\frac{3}{4}$ " Iron Bolt in Fence Corner, Fences South - East & Northwest.
Rotted Fir Stump N.40 $\frac{1}{2}$ °W. 13.2 ft. scribing visible on portion
of old face "5" & "BT". This tree was marked by Germond. REN. #55
No trace of Germond's N.E. BT.
No trace of Original BT. found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S R6W N NW. Cor. D.L.C. #51
Set Bolt back alongside Brass Cap.
New BT's: 13" W.Oak N.72 $\frac{1}{2}$ °E. 40.3 ft. Mkd: N NW D.L.C. 51 CS BT.
14" W.Oak S.30°W. 19.5 ft. Mkd: N NW D.L.C. 51 CS BT.

Most Westerly N.W. Corner D. L. C. No. 51. 80
Found - Fir Stump, now 30", S.80°E. 25.7 ft., chopped open & found
good scribing "C". REN. #57
B. Oak, now 16", S.57°W. 6.6 ft., shows good scar. Didn't open.
These two trees marked by Germond. No trace of either Orig. BT.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S R6W W NW Cor. D. L. C. #51
Blaze & Rescribe 16" B.Oak S.57°W. 6.6 ft. Mkd: "W NW DLC 51 CS BT"
New BT: 6" D.Fir S.67°E. 8.3 ft. Mkd: W NW DLC 51 CSBT.
Fence Corner (fences E. & S.) bears S.45°E. 9.0 ft.

N. E. Corner D. L. C. No. 51. 81
Found - Orig. 18" B.Oak, now 32", N.40°E. 89.8 ft. Tree has been
previously opened. Fairly good scribing visible on partly
rotted old face, "T25S R6-C", Tree dying.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S R6W NE Cor. DLC 51
New BT's: 18" W.Oak S.75°W. 23.0 ft. Mkd: NE DLC 51 CS BT.
11" W.Oak N.33°E. 24.3 ft. Mkd: NE DLC 51 CS BT.
A Fence Corner (fences West & South) bears S.5°W. 24.5 ft.

Section Corner to Sections 15 - 16 - 21 - 22. 82
Found - B. Oak, now 36", N.78 $\frac{1}{2}$ °E. 200.6 ft., previously opened, but
not deep enough. Chopped open & found good reverse scribing "BT"
Tree hollow & dying.
Oak, uprooted & down, N.44°W. (instead of N.46 $\frac{1}{2}$ °W.) 304.9 ft.,
badly rotted, but fragments of reverse scribing found.
Stump Hole S.22°W. 75.9 ft. - Stump Hole S.47 $\frac{1}{2}$ °E. 147.8 ft.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T25S R6W S16 S15
S21 S22
New BT's: 14" W.Oak S.21°W. 60.6 ft. Mkd: T25S R6W S21 CS BT.
18" D.Fir N.55°W. 49.5 ft. Mkd: T25S R6W S16 CS BT.
8" W.Oak S.48°E. 63.4 ft. Mkd: T25S R6W S22 CS BT.
21" W.Oak N.78 $\frac{1}{2}$ °E. 160.1 ft. mkd: T25S R6W S15 CS BT.
A scribed Oak Stake in Fence Corner (Fences W. & N.) bears N.5°W. 6.2 ft.

Most Northerly N.W. Cor. D.L.C. No. 50. 83
Found - 2 Rocks set by Wm. Thiel in 1886. One Rock Mkd? "Γ"
B. Oak, now 30", S.45°E. 40.9 ft. This tree had been opened years ago,
probably by Thiel, I cut open again, but find center rotted away.
No scribing found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
T 25 S. R 6 W. N NW Cor. D.L.C. 50.
New BT's: 10" W.Oak S.12°W. 7.4 ft. mkd: "N NW DLC 50 CS BT".
15" W.Oak N.77°W. 31.6 ft. mkd: "N NW DLC 50 CS BT".
Note - See Vol. 1, Page 73 for Thiel's Renewal.

Most Westerly S.W. Corner D.L.C. No. 49. 84
Found - Sandstone Rock (12" x 9" x 5" above ground) mkd. "49 T CS".
Oak, 30", Orig. BT., S.5°E. 107.6 ft., uprooted & down. good scrbing.
Corner Rock in Good Condition - No Other Monument Set.
New BT's: 15" B.Oak S.34°E. 25.6 ft. Mkd: W SW DLC 49 CS BT. (this tree showed
2 blazes facing Cor. possibly mkd. as BT. previously.
14" W.Oak N.61°E. 30.4 ft. Mkd: W SW DLC 49 CS BT.
This corner lies in N.&S. fence. Line. Traces of old fence line to East
INTERSECTS N.&S. FENCE AT CORNER.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July 20, 1962
C. S. File No. 49/123

SCRIBING VISIBLE IN NOT
COMPLETELY HEALED OVER
SCAR ON 32" MAPLE
N.20°W. 80.2'