

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

85

$\frac{1}{4}$ Corner to Sections 10 and 15.
Found - B. Oak, now 24", N.22°W., (instead of N.12°W.) 29.7 ft.
Chopped open & found reverse scribing " $\frac{1}{4}$ ". Center of tree
rotted away - hollow.
B. Oak, now 28", S.69°W. (instead of S.73°W.) 27.1 ft. Chop
open & find good scribing "T", tree in good condition.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W $\frac{1}{4}$

S10	S15
-----	-----

Office, 1962
New BT's: 15" D. Fir S.77°W. 15.3 ft. Mkd: $\frac{1}{4}$ S15 CS BT.
6" D. Fir N.23°E. 10.6 ft. Mkd: $\frac{1}{4}$ S10 CS BT.
Note - Set Corner at intersection of distances, since neither
distance fit at intersection of bearings.

86

Section Corner to Sections 19 - 20 - 29 - 30/
Found - Rotten Shell, remains of Oak Tree, N.85 $\frac{1}{4}$ °W. 198.7 ft. Faint
reverse scribing visible on inside. "W" "S" "9" & "B" legible.
W. Oak, now 36", N.12 $\frac{1}{2}$ °E. (instead of N.17 $\frac{1}{2}$ °E.) 195.4 ft.
two good scars plainly visible.
B. Oak, nearly dead, S.61 $\frac{3}{4}$ °W. 203.0 ft. (instead of 198.0 ft.)
Now 28" diam., Did not open.
W. Oak, now 24", S.87°E. (instead of S.83 $\frac{3}{4}$ °E.) 320.8 ft.
Faint scar visible. Blaze & Rescribe this tree:
"T25S R6W S29 CS BT"
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W

S19	S20
S30	S29

Office, 1962
New BT's: 9" W. Oak N.36°W. 65.0 ft. Mkd: T25SR6W S19 CS BT.
8" W. Oak S.75°W. 147.1 ft. Mkd: T25SR6W S30 CS BT.
24" B. Oak N.47°E. 156.0 ft. Mkd: T25SR6W S20 CS BT.
Corner falls in fence corner, fences North, South & East from Corner.
This location satisfies more calls than any other, 3 distances &
2 bearings to original trees.
Note - All distances from old BT's, measured from face of trees.

87

Section Corner to Sections 14 - 15 - 22 - 23.
Found - 1" Pipe set by Frear at Corner. *Ren. #*
Badly rotted & burned Oak Snag N.52°E. 11.2 ft. Scribing visible. *#187*
B. Oak, now 24", N.68°W. 25.1 ft., shows faint scar.
B. Oak, now 30", S.23 $\frac{1}{2}$ °W. 67.3 ft., shows fairly plain scar.
W. Oak, now 44", S.33°E. 35.0 ft. Cut open & fd. reverse Orig. scbng.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W

S15	S14
S22	S23

Office, 1962
New BT's: 18" B. Oak S.52°E. 13.0 ft. Mkd: T25S R6W S23 CS BT.
9" Madrone S.70°W. 41.6 ft. Mkd: T25S R6W S22 CS BT.
9" W. Oak N.10°W. 14.8 ft. Mkd: T25S R6W S15 CS BT.
6" W. Oak N.46°E. 18.2 ft. Mkd: S14 CS BT.
Corner lies in old E. & W. Fence Line approx. 40 ft. West of Ridge Top.

88

Section Corner to Sections 10 - 11 - 14 - 15.
Found - 5/8" Iron Rod at Corner, not recorded.
Rotted remnants of Oak Snag N.8°W. 27.1 ft. Good reverse scribing.
B. Oak, now 31", S.14 $\frac{1}{2}$ °E. 133.3 ft., shows very plain scar.
B. Oak, now 36", S.83°W. 33.0 ft., shows faint scar, Tree dying.
Rotten Oak, down, N.26°E. 94.4 ft., badly rotted, reverse scribing.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W

S10	S11
S15	S14

Office, 1962
New BT's: 11" W. Oak N.58°W. 38.6 ft. Mkd: T25S R6W S10 CS BT.
28" Dbl. B. Oak, (measured below fork), S.22°W. 59.7 ft. Mkd:
T25S R6W S15 CS BT.
20" B. Oak S.34°E. 33.4 ft. Mkd: T25S R6W S14 CS BT.
21" W. Oak N.84°E. 65.6 ft. Mkd: T25S R6W S11 CS BT.
Fence Corner, (Fences E. & N.) bears N.15°W. 4.0 ft.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy
Mike Stone
August 1962
C. S. File No. 49/123

RE-RENEWED - SEE RE-RENEWED #187