

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R.W.W.M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

Milo E. Godfrey, Deputy  
Mike Stone  
October 15, 1962  
C. S. File No. 49/123

**99**  
 $\frac{1}{4}$  Section Corner for Sections 17 and 20.  
 Found - 24" Fir Stump N.66°W. 29.0 ft. Found bottom of old axe scar, but tree was cut off below all scribing. *Ren. #28*  
 Stump Hole & Remnants of Oak Tree S.9°W. 17.2 ft. Definite traces of old axe face, but no scribing left, most of face has rotted away.  
 Stump hole & rotten remains of Oak Stump N.45 $\frac{1}{2}$ °W. 58.1 ft. Too far gone to find any trace of scars or scribing.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$  S17 S20 Office, 1962  
 New BT's: 10" D.Fir S.59°E. 9.7 ft. Mkd:  $\frac{1}{4}$  S20 CS BT.  
 9" D.Fir N.12°W. 44.3 ft. Mkd:  $\frac{1}{4}$  S17 CS BT.  
 Corner lies 7 ft. South of a new E. & W. Fence Line.

*FD. OK  
1/18/1  
R. DOLAN  
11/87-39*

**100**  
 $\frac{1}{4}$  Corner to Sections 9 and 10.  
 Found - 36" W.Oak (nearly dead) S.54°W. 58.3 ft. (not 60.7 ft.)  
 Chopped open & found good scribing "BT".  
 24" W.Oak S.85°E. 28.5 ft. (not 29.7 ft.) chopped open & found good scribing on old face, part of "4" & "5".  
 Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$  S9/S10 Office, 1962  
 New BT's: 9" W.Oak S.88°W. 16.6 ft. Mkd:  $\frac{1}{4}$  S9 CS BT.  
 10" W.Oak S.41°E. 32.3 ft. Mkd:  $\frac{1}{4}$  S10 CS BT.  
 Corner lies directly on top of ridge.

**101**  
 $\frac{1}{4}$  Corner to Sections 6 and 5.  
 Found - 1 $\frac{1}{2}$ " Iron Rod set by Ausland, 1941. Also found Rock set by B.B.Irving, 1947, about 10 ft. West of corner. *REN. No. 45:44 50 A.1*  
 Orig. 54" Laurel N.63°W. 43.6 ft., opened years ago, no scribing.  
 No trace found of Orig. S.E. Bearing Tree.  
 27" Fir Stump N.46 $\frac{3}{4}$ °W. 50.8 ft., shows good scars, but old face burned off.  
 42" Fir Snag N.47 $\frac{1}{2}$ °E. 25.7 ft., good scribing found "S"  
 Note - Fir Stump & Snag do not fit position where Ben's Rock was fd.)  
 Alongside I.Rod Set Brass Cap Mkd: County Surveyor's Office, 1962  
 T25S R6W  $\frac{1}{4}$  S6/S5 Set Rock alongside.  
 New BT's: 16" W.Fir N.37°E. 81.7 ft. Mkd:  $\frac{1}{4}$  S5 CS BT.  
 12" D.Fir N.53°W. 15.0 ft. Mkd:  $\frac{1}{4}$  S6 CS BT.  
 A Fence Corner - Fences North, South & East, bears N.45°W. 5.5 feet.  
 Nov. 1, 1962

*Fd. ok 7/8/9  
RMJ-72  
B. SHANZ*

**102**  
 $\frac{1}{4}$  Corner to Sections 3 and 2.  
 Found - Burned Fir Stump S.59°W. 15.6 ft. Ends of scribe marks visible along unburned edge of badly charred face. *Ren. #9*  
 Stump Hole & part of Fir Stump N.63°E. 32.0 ft. (in place)  
 Too far gone to find scars or scribing. These trees mkd. by Stewart.  
 Stump Hole S.87°E. 7.9 ft. (Orig. BT.)  
 No trace of Original N.W. Bearing Tree.  
 Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$  S3/S2 Office, 1962  
 New BT's: 4" Madrone N.78°E. 36.4 ft. Mkd:  $\frac{1}{4}$  S2 CS BT"  
 18" D.Fir S.33°W. 93.0 ft. Mkd:  $\frac{1}{4}$  S3 CS BT.  
 Corner is in fence corner, fences N., S., and West.  
 Nov. 15, 1962

*Vol. 3, p. 112*

**103**  
 $\frac{1}{4}$  Corner to Sections 26 and 35.  
 Found - 1 $\frac{1}{2}$ " Iron Rod set by Richardson, 1946, *Ren. No. 42*  
 18" Fir N.77 $\frac{1}{2}$ °E. 8.3 ft., good bark scribing visible, Tree dead & rotten  
 No trace of S.W. Tree marked in 1946.  
 Orig. W.Oak, now 24", S.12°E. 23.1 ft. Alive & standing.  
 Orig. W.Oak N.26°W. 54.1 ft., down & rotten in 1946, still in existence.  
 DID NOT SET BRASS CAP.  
 New BT's: 8" W.Oak N.10°E. 24.5 ft. Mkd:  $\frac{1}{4}$  S26 CS BT.  
 13" W.Oak S.25°E. 34.8 ft. Mkd:  $\frac{1}{4}$  S35 CS BT.  
 Nov. 15, 1962