

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

104

Center  $\frac{1}{4}$  Corner of Section 3.  
Found - Rock (Top 5" x 10") Set by Stewart, 1922. "X" chiseled  
in top of rock. *Cx-505*  
Fir Snag, 24" diam.) S. 54°W.  $\frac{3}{4}$  37.7 ft., cut open & fd.  
good scribing.  
Rotten & badly burned Fir Snag S. 22°E. 62.8 ft. No mks.  
Alongside Rock at Cor. Set Iron Pipe with Brass Cap Mkd:  
"County Surveyor's Office, 1962 T25S R6W Cent.  $\frac{1}{4}$  S 3 +"  
New BT's: 15" D. Fir S. 12°W. 13.7 ft. Mkd: "C  $\frac{1}{4}$  S3 CS BT".  
20" I. Cedar S. 48°E. 59.8 ft. Mkd: "C  $\frac{1}{4}$  S3 CS BT".

105

Sec. Cor. to Secs. 3 & 4, T25-6W. & 33 & 34, T24-6W. *REN. #13*  
Found -  $1\frac{1}{4}$ " I.P. set by Stewart, 1922.  
Fir Tree, now 26", N. 16°W. 9.2 ft. (to face) Scribing  
visible on pitched over face.  
Stump Hole & portions of Fir Roots N. 14°E. 16.8 ft.  
Rottedn Fir Stump S. 37°E. 136.2 ft., bark gone, no scribing.  
Rotten Fir Stump S. 48°W. 46.8 ft., opened & fd. good scribing.  
Stump Hole & fragments of Laurel Roots N. 39°W. 72.6 ft. (Orig.)  
Stump Hole with B. Oak growing out of one side N.  $\frac{1}{4}$ °E. 39.6 ft.  
No trace found of other Original BT's.  
DID NOT SET BRASS CAP  
New BT's: 12" W. Oak S. 74°W. 63.5 ft. Mkd: T25S R6W S4 CS BT.  
11" D. Fir N. 28°E. 35.4 ft. Mkd: T24S R6W S34 CS BT.  
7" W. Oak S. 32°E. 9.5 ft. Mkd: T25S R6W S3 CS BT.  
Corner lies in a N. & S. Fence Line. Nov. 16, 1962

106

$\frac{1}{4}$  Corner to Sections 4 and 3. *REN. #11*  
Found - Sandstone Rock, 6"x8"x9" with "X" cut in top.  
Laurel Snag S. 11° E. 17.8 ft., snag still standing, but  
dead & badly rotted, entire North side gone.  
Uprooted & badly burned firs N. 51°W. 4 ft. and S. 10°E.  
12 ft. No markings found on either.  
No trace found of Orig. S.W. Oak.  
Set - Brass Cap Alongside Rock Mkd: County Surveyor's Office, 1962  
T25S R6W  $\frac{1}{4}$  S4/S3  
New BT's: 6" D. Fir N. 25°W. 15.7 ft. Mkd:  $\frac{1}{4}$  S4 CS BT.  
9" D. Fir N. 26°E. 15.7 ft. Mkd:  $\frac{1}{4}$  S3 CS BT.  
Corner lies on E. slope approximately 70 ft. West of small stream  
flowing Southeast.

107

$\frac{1}{4}$  Corner to Sections 2 and 11.  
Found - Old Oak, uprooted & down for years, N. 28°W. 34.3 ft., cut  
open & found good reverse scribing "BT".  
Depression in ground, old stump hole?, S. 15°W. 17.2 ft.,  
fragments of Oak wood lying alongside depression, good  
reverse scribing "BT" on wood fragment.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$  S 2  
Office, 1962 S11  
New BT's: 9" D. Fir N. 62°W. 44.8 ft. Mkd:  $\frac{1}{4}$  S 2 CS BT.  
17" Madrone S. 64°W. 20.9 ft. Mkd:  $\frac{1}{4}$  S11 CS BT.

108

Section Corner to Sections 3 - 4 - 9 - 10  
Found - 2 Rocks, buried, largest 6"x10"x16" (No marks) *REN. #10*  
Rottedn Fir Stump N. 19°W. 24.6 ft., scribing visible  
on old face, "S" & "BT".  
40" Fir Snag S. 58°W. 25.0 ft., shows good axe scar.  
16" Fir N. 68°E. 14.0 ft., shows good scar.  
Orig. S.E. BT. is uprooted & out of position, impossible  
to tell where it stood. Scribing visible.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W S 4 | S 3  
(Set Rocks Alongside) Office, 1962 S 9 | S10  
New BT's: Rescribe 16" D. Fir N. 68°E. 14.0 ft. (to face) mkd:  
S 3 CS BT".  
11" I. Cedar S. 32°E. 69.0 ft. Mkd: T25S R6W S10 CS BT.  
21" D. Fir S. 10°W. 51.3 ft. Mkd: T25S R6W S 9 CS BT.  
13" I. Cedar S. 75°W. 94.2 ft. mkd: T25S R6W S9 CS BT.  
No trees near to N.W. Fence Cor. bears N. 52°W. 33.0 ft.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy and Mike Stone  
November 1962  
C. S. File 49/123