

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

114
 $\frac{1}{4}$ Section Corner to Section 5, T25-6W. & Sec. 32, T24-6W.
 Found - Rock called for in earlier renewals. - Cor. #50
 14" White Fir Snag, N.72°W. 37.7 ft., standing but rotten.
 Scribing visible " $\frac{1}{4}$ BT". (Boyer's tree) - Cor. #38
 No trace of Boyer's S. E. tree.
 Rotten Alder Snag S.50 $\frac{1}{2}$ °W. 49.5 ft., no markings found.
 Clump of Ash growing out of old stump hole, N.65 $\frac{3}{4}$ °E. 76.0 ft.
 (Ren. calls for 20"W.Oak N.65 $\frac{3}{4}$ °E. 75.9 ft.)
 No trace of Original Bearing Trees found.
 Set - Brass Cap alongside Rock Mkd: County Surveyor's $\frac{1}{4}$ S32 T24S R6W
 Office, 1962 S 5 T25S
 New BT's: 11" W.Oak N.51°W. 45.7 ft. Mkd: $\frac{1}{4}$ S32 CS BT.
 12" Ash S.50°W. 28.2 ft. Mkd: $\frac{1}{4}$ S5 CS BT.
 Corner lies in fence corner, fences south & west from corner.

115
 Section Corner to Secs. 4 & 5, T25-6W. & Secs. 32 & 33, T24-6W.
 Found - Gun Barrel set by Stewart lying on ground by Corner.
 Also Rock 4"x10"x11" Set at Corner. (See Renewal #12, T24-6W)
 18" Fir Snag S.77°E. 58.0 ft., previously opened, good scrbing.
 17" Fir, N.69°E. 59.0 ft., uprooted & dead, shows good scar.
 Laurel S.22°W. 154.0 ft., standing but dead & badly dedayed.
 No marks found.
 Remains of old fir stump S.57 $\frac{1}{2}$ °E. 28.4 ft. Orig. BT. No marks.
 Fir, not Laurel, N.11 $\frac{1}{2}$ °E. 25.1 ft. Tree uprooted & dead.
 Cut open & fd. good scribing "T24S B". Tree approximately
 20" diam. when marked. Original.
 Set - Brass Cap at Cor. Mkd: County Surveyor's S32 | S33 T24S R6W
 Office, 1962 S 5 | S 4 T25S
 Set Gun Barrel & Rock Alongside Brass Cap.
 New BT's: 5" Madrone N.44°W. 24.8 ft. Mkd: S32 CS BT.
 9" D.Fir N.75°E. 24.7 ft. Mkd: T24S R6W S33 CS BT.
 9" W.Fir S.78°E. 67.7 ft. Mkd: T25S R6W S4 CS BT.
 6" Madrone S.78°W. 54.4 ft. Mkd: T25S R6W S5 CS BT.
 Corner lies in fence corner, fences north, south & west, on N.W.
 slope, 230 ft. south of creek.

116
 $\frac{1}{4}$ Corner to Sec. 1, T25-6W. & Sec. 36, T24-6W.
 Found - 21" Black Oak S.12°W. 44.9 ft., cut open & fd. good rev.scrbing.
 Old Oak, down & badly decayed, N.19°W. 67.3 ft., no markings.
 Set - Brass Cap at Cor. Mkd: County Surveyor's $\frac{1}{4}$ S36 T24S R6W
 Office, 1962 S 1 T25S
 New BT's: 12" W.Oak S.20°E. 37.3 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
 14" W.Oak N.62°W. 24.9 ft. Mkd: $\frac{1}{4}$ S36 CS BT.
 A Fence Corner, fences North, South, East & West, bears N.63°E. 13.0 ft.

117
 $\frac{1}{4}$ Corner to Sections 2 and 1.
 Found - 1 $\frac{1}{4}$ " Iron Pipe set by Springer, 1923. REN.#15
 Bl. Oak, now 20", N.28°E. 19.8 ft. Cut open & found scribing,
 part of "BT" on badly rotted old face.
 16" Bl.Oak S.59°W. 38.3 ft., Tree down & badly burned,
 no scribing found, some old axe marks visible.
 No trace of Original S.W. BT.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962
 T25S R6W $\frac{1}{4}$ S2/S1
 New BT's: 8" W.Oak N.81°W. 16.0 ft. Mkd: $\frac{1}{4}$ S 2 CS BT.
 16" Bl.Oak N.47°E. 56.3 ft. Mkd: $\frac{1}{4}$ S1 CS BT.
 Corner lies on top of ridge in fence corner, old fences running
 North, South and West.

118
 Most Westerly S. W. Corner D. L. C. No. 61.
 Found - 1 1/8" Steel Shaft in mound of rocks, set by Springer, 1923.
 15" Bl. Oak N.51°E. 85.1 ft.(slope dist.) cut open but entire
 center portion rotted away, no scribing found, scars
 show plainly on surface. REN.#16
 Repile Rocks around Corner Monument.
 New BT's: 6"D.Fir N.57 $\frac{1}{2}$ °E. 24.1 ft. Mkd: WSW DLC 61 CS BT.
 6" Pine S.2 $\frac{1}{2}$ °E. 31.0 ft. Mkd: WSW DLC 61 CS BT.
 Old fence corner bears West 2.5 ft. Cor. lies on SE. slope approx. 150' N. of stream.

Milo E. Godfrey, Deputy County Surveyor
 Vernon Tracy
 Mike Stone
 November 1962
 C. S. File No. 49/123