

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

119

Sec. Cor. to Secs. 1 & 2, T25-6W. & Secs. 35 & 36, T24-6W.
Found - 2" Steel Shaft set by Springer, 1923, top of shaft 4" below surface.
Rotted remnants of Old Oak (in Place) N:65 $\frac{1}{4}$ °W. 116.8 ft. Good rev.scribg.
31" Bl. Oak N.73 $\frac{3}{4}$ °E. 184.3 ft. (not 188.1 ft.) shows 2 good scars,
tree alive & in good condition. REN #14
No trace of S. E. or S. W. trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1962

| | | | |
|-----|-----|------|-----|
| S35 | S36 | T24S | |
| S 2 | S 1 | T25S | R6W |

New BT's: 15" D.Fir S.52°W. 21.4 ft. Mkd: T25S R6W S2 CSBT.
7" W.Oak S.29°E. 8.4 ft. Mkd: T25S R6W S1 CS BT.
10" Bl. Oak N.34°E. 11.1 ft. Mkd: T24S R6W S36 CS BT.
10" D.Fir N.41 $\frac{1}{2}$ °W. 43.0 ft. Mkd: T24S R6W S35 CS BT.
Corner lies in fence Corner, old fences North, South and West from corner.
Dec. 3, 1962

120

Section Corner to Sections 23 - 24 - 25 - 26.
Found - $\frac{3}{4}$ " Galv. Iron Pipe at Corner. (REN #19)
24" B. Oak N.41°W. 37.0 ft., shows good scar. Tree dying.
10" W. Oak S.44 $\frac{3}{4}$ °W. 71.0 ft. Cut open & fd. good scribing "S".
30" Oak Stump S.18°E. 81.7 ft. Portion of straight scribe mark
visible on old face, not grown over.
10" W. Oak N.75 $\frac{1}{2}$ °E. 64.8 ft., shows good scar.
Only trace found of Orig. BT's. were stump holes to NE. & SE.
No trace found of Orig. S. W. tree.
DID NOT SET BRASS CAP.
New BT's: 16" W.Oak N.47 $\frac{1}{2}$ °W. 70.5 ft. Mkd: T25S R6W S23 CS BT.
15" D.Fir S.61°W. 9.3 ft. Mkd: T25S R6W S26 CS BT.
8" W.Oak S.86°E. 31.3 ft. Mkd: T25S R6W S25 CS BT.
8" D.Fir N.55 $\frac{1}{2}$ °E. 74.3 ft. Mkd: T25S R6W S24 CS BT.
A North & South Fence line bears West 8.5 feet.
Jan. 4, 1963

121

$\frac{1}{4}$ Corner to Sections 23 and 26.
Found - 30" W.Oak N.60°W. 61.4 ft., down & dead, cut open & fd. scribing.
No trace of S. E. Tree. Cor. position falls in center of sm. creek.
Set - Wit. Cor. 25 ft. West of $\frac{1}{4}$ Corner - Brass Cap Mkd:
County Surveyor's Office 1963 T25S R6W WC $\frac{1}{4}$ S23 25 ft. E. to Cor.
S26
New BT's: 13" W.Oak S.37°W. 10.2 ft. Mkd: WC $\frac{1}{4}$ S26 CS BT.
18" W.Oak N.77°E. 71.2 ft. Mkd: WC $\frac{1}{4}$ S23 CS BT.

122

$\frac{1}{4}$ Corner to Sections 12 and 13.
Found - 42" W.Oak, dead, N.52°W. 565.6 ft. Cut open & fd. good scribing.
45" W.Oak, not B.Oak, N.71 $\frac{3}{4}$ °E. 525.4 ft. No scar visible.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T25S R6W $\frac{1}{4}$ S12 S13
New BT's: 24" D.Fir S.5°E. 70.9 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
Reblaze: 45" W.Oak N.71°E. 525.4 ft. (to old face) Mkd: $\frac{1}{4}$ S12 CS BT.
Note - Corner lies inside right of way of Co.Rd. No. 10-A. Fence
along north R/W line is 3 feet North of corner.

123

$\frac{1}{4}$ Corner to Sections 23 and 24.
Found - 38" Dead Oak Snag N.56°W. 85.8 ft. Cut open & found good
reverse scribing " $\frac{1}{4}$ S & "BT".
Rotted remains of Oak Stump N.33°E. 86.5 ft. No marks left.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R6W $\frac{1}{4}$ S23/S24
New BT's: 9" B.Oak S.46°E. 20.2 ft. Mkd: $\frac{1}{4}$ S24 CS BT.
18" Dbl. Madrone N.65°W. 22.6 ft. Mkd: $\frac{1}{4}$ S23 CS BT.
A North & South Fence Line bears West 137 feet.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy & Mike Stone, Chairman
December 1962 January 1963
C. S. File No. 49/123