

Douglas County Surveyor's Record of  
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21881

$\frac{1}{4}$  Corner to Sections 22 and 27. 124  
Found - 30" W.Oak N.75°W. 31.7 ft. Cut open & fd. good scribing "B".  
No trace of S.W. tree found.  
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$   $\frac{S22}{S27}$   
Office, 1963  
New BT's: 20" W.Oak N.64°W. 67.2 ft. Mkd:  $\frac{1}{4}$  S22 CS BT.  
16" W.Oak S.78°E. 111.4 ft. Mkd:  $\frac{1}{4}$  S27 CS BT.

$\frac{1}{4}$  Corner to Sections 26 and 25. 125  
Found - 12" Bl. Oak S.50°E. 13.2 ft., down & rotten, face with good rev.scrbng.  
Rotten base of Oak Stump N.83 $\frac{1}{2}$ °W. 25.1 ft., no mks. fd., portion  
found below ground surface only.  
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963  
T 25 S R 6 W  $\frac{1}{4}$  S26/S25  
New BT's: 10" D.Fir N.75°W. 6.9 ft. Mkd:  $\frac{1}{4}$  S26 CS BT.  
10" D.Fir S.75°E. 14.0 ft. Mkd:  $\frac{1}{4}$  S25 CS BT.  
Corner lies on fairly steep N.W. slope.

$\frac{1}{4}$  Section Corner to Sections 17 and 16. 126  
Found - Rock (top 6"x6" - 7" above ground) chisled " $\frac{1}{4}$ S" on E. face.  
32" Bl.Oak N.69 $\frac{1}{2}$ °E. 95.4 ft., slope dist., This tree had been  
opened several years ago. Inside badly rotted. Found reverse  
of axe notch & portion of old face below previous opening,  
No scribing found.  
Large Stump Hole S.59°W. 219 ft. (slope dist.) No trace of wood left.  
Alongside Rock set Brass Cap Mkd: County Surveyor's Office, 1963  
T25S R6W  $\frac{1}{4}$  S17/S16  
New BT's: 10" D.Fir N.77°W. 47.3 ft. Mkd:  $\frac{1}{4}$  S17 CS BT.  
7" D.Fir N.47°E. 45.0 ft. Mkd:  $\frac{1}{4}$  S17 CS BT.  
An old fence cor. (fences N., S. & E.) bears N.70°E. 92.5 ft.  
This cor. was obviously renewed several years ago, but did not find  
any record of renewal, Probably Stewart or Cole.

$\frac{1}{4}$  Corner to Sections 16 and 21. 127  
Found - 20" W.Oak S.37 $\frac{1}{2}$ °E. 71.9 ft. Tree had been opened, mks. nearly  
gone, opened lower down & fd. rev. scrbing, part of "B" & "T",  
good reverse axe notch at bottom of old face.  
30" Oak Snag N.11°W. 93.7 ft. Has been opened previously & badly  
rotted. A few fragments of old face fd., but no scribe marks.  
Set - Brass Cap Mkd: County Surveyor's T25S R6W  $\frac{1}{4}$   $\frac{S16}{S21}$   
Office, 1963  
New BT's: 20" W.Oak N.89°E. 18.0 ft. Mkd:  $\frac{1}{4}$  S16 CS BT.  
10" W.Oak S.13°W. 12.5 ft. Mkd:  $\frac{1}{4}$  S21 CS BT.  
Corner falls in old wood road, on gentle S.W. Slope.

Section Corner to Sections 28 - 29 - 32 - 33. 128  
Found -  $\frac{3}{4}$ " Ir. Bolt with square head. Rev. # 29  
13" Fir Snag N.30°W. 34.4 ft. scribing visible "S29 CS BT."  
15" Bl.Oak S.44°W. 9.4 ft., shows 2 very good axe scars) good  
13" W.Oak S.16°E. 11.4 ft., shows 2 very good axe scars) cond.  
18" W.Oak N.75°E. 32.0 ft., shows 2 good axe scars. ) ition  
Old Oak Stump 42.2 ft. No mks. found (Orig. BT.)  
Alongside Bolt at Cor. Set Brass Cap Mkd: County Surveyor's T25SR6W  $\frac{S29}{S32}$   $\frac{S28}{S33}$   
Office, 1963  
New BT: 7" D.Fir N.11°W. 18.0 ft. Mkd: T25S R6W S29 CS BT.

$\frac{1}{4}$  Corner to Sections 20 and 29. 129  
Found - W.Oak, now 50", N.30°E. 595.3 ft., previously opened, fd. rev.scribng.  
Rotted remnants of very large Oak Stump, in place, approx. 750 ft.  
N. of Cor. Old axe mks. on one frag. of wood. This does not  
check for bear. & dist. from cor. but I believe it was other old BT.  
Set - Brass Cap (from N.E. BT.) mkd: County Surveyor's T25S R6W  $\frac{1}{4}$   $\frac{S20}{S29}$   
Office, 1963  
New BT's: 16" B.Oak N.32°W. 19.6 ft. Mkd:  $\frac{1}{4}$  S20 CS BT.  
12" W.Oak S.49°E. 12.5 ft. Mkd:  $\frac{1}{4}$  S29 CS BT.  
Corner position falls in bed of small stream.

Milo E. Godfrey, Deputy County Surveyor  
Vernon Tracy  
Mike Stone - January 1963 C. S. File No. 49/123

RE-RENEWED SEE CORNER NO. 188