

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

MOORE-CHAPMAN CO., EUGENE, ORE. 21881

130

$\frac{1}{4}$ Corner to Sections 29 and 32.
Found - 46" W.Oak S.78°E. 305 ft. Cut open & fd. good scribing "B", pt.of "T".
Old, Rotten Oak Stump, cut low, N.85°E. 338.6 ft. Cut low to fd.scrbng.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6 W $\frac{1}{4}$ S29
Office, 1963 S32

New BT's: 20" B.Oak S.10 $\frac{1}{2}$ °W. 133.9 ft. Mkd: $\frac{1}{4}$ S32 CS BT.
14" W.Oak N.76°E. 213.3 ft. Mkd: $\frac{1}{4}$ S29 CS BT.

131

$\frac{1}{4}$ Corner to Sections 31 and 32. *8 PER FIELD NOTES.*
Found - 54" Bl.Oak Snag N.10 $\frac{1}{2}$ °W.182.2 ft. Cut open & fd. good rev. scrbing.
No trace of S.E. BT. (location falls in plowed field) at corner,
Drove $\frac{3}{4}$ " Iron Reinf. Rod 14" below surface of ground.
Set - Wit. Cor. 125 ft. N. of $\frac{1}{4}$ Cor. Set Brass Cap Mkd:
County Surveyor's Office, 1963 T25S R6W WC $\frac{1}{4}$ S31/S32 Cor. 125 ft. S.
New BT's: 6" Madrone N.21 $\frac{1}{2}$ °E. 53.5 ft. Mkd: W.C. $\frac{1}{4}$ S32 CS BT.
36" Bl. Oak N.36°W. 99.6 ft. Mkd: W.C. $\frac{1}{4}$ S31 CS BT.

132

Section Corner to Secs. 32 & 33, T25-6W. & Secs. 4 & 5, T26-6W.
Found - 32" White Oak Snag S.52°E. 117.5 ft. with scribe marks.
Bl. Oak Stump S.4°W. 15.2 ft., rotted, no scribe.
25" White Oak N.83°W. 112.9 ft., showing good scar.
20" White Oak N.84°E. 53.5 ft., shows faint scar.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25-6W S32 | S33
Office, 1963 T26-6W S 5 | S 4

New BT's: 16" Bl.Oak bears S.49°E. 69.3 ft. Mkd: T26S R6W S4 CS BT.
13" W. Oak bears S.29°W. 29.3 ft. Mkd: T26S R6W S5 CS BT.
14" W.Oak bears N.39°W. 10.6 ft. Mkd: T26S R6W S32 CS BT.
15" W.Oak bears N.57°E. 26.5 ft. Mkd: T25S R6W S33 CS BT.

Corner is 1.0 ft. south of E-W fence line, approx. 1 chain West of top of ridge bearing North and South.

133

Cor. for $\frac{1}{4}$ Cor. Sec. 33, T25-6W. & Sec. 4, T26-6W.
Found - 20" Bl.Oak Snag S.2°W. 16.5 ft. with good scribe.
29" Bl. Oak N.27°W. 17.8 ft., down, dead and rotting. Did not open.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W $\frac{1}{4}$ S33
Office, 1963 T26S R6W S 4

New BT's: 14" D.Fir bears S.70°W. 23.3 ft. Mkd: $\frac{1}{4}$ S 4 CS BT.
16" D.Fir bears N.55°W. 14.4 ft. Mkd: $\frac{1}{4}$ S33 CS BT.

This corner is 1.5 feet south of E-W fence line and approx. 165 feet East of top of ridge which bears north and south.

134

Sec. Cor. for Sections 33 & 34, T25-6W. & Secs. 3 & 4, T26-6W.
Found - Following BT's. as recorded by H.L. Eppstein in 1930: *REN. #72*
24" B.Oak S.64 $\frac{1}{2}$ °W. 7.5 ft., down, rotting, no scribing left.
24" Fir Stump N.19°E. 22.4 ft., shows good scar. *#176*
20" Fir Stump S.12°E. 9.0 ft., opened & found scribe visible.
30" Fir N.56 $\frac{1}{2}$ °W. 25.0 ft., showing good scar.
No trace of Original Bearing Trees.
Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W S 33 | S 34
Office, 1963 T26S R6W S 4 | S 3

New BT's: 14" D.Fir bears S.85°W. 15.6 ft. Mkd: T26S R6W S4 CS BT.
7" D.Fir bears N.46°E. 64.5 ft. Mkd: S34 CS BT.
8" W.Oak bears S.35°E. 39.3 ft. Mkd: T26S R6W S3 CS BT.
Did not remark 30" Doug. Fir to the N. W.

135

Section Corner to Sections 26 - 27 - 34 - 35.
Found - Axle as called for in Renewal No. 41 by Richardson.
20" Fir N.65 $\frac{1}{2}$ °W. 85.1 ft., shows very plain scars. Did not open.
The S.E. & S.W. BT's. mkd. in 1946 have both been cut. Found stumps of both, which show very good axe scars, did not open.
DID NOT SET BRASS CAP.
New BT's: 4" D.Fir S.50°W. 14.2 ft. Mkd: S34 CS BT.
12" D.Fir N.62 $\frac{1}{2}$ °E. 114.0 ft. Mkd: T25S R6W S26 CS BT.
6" D.Fir S.85°E. 55.4 ft. Mkd: S35 CS BT.
Corner lies in fence corner, Fences East & South from corner.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracey and Mike Stone
January 1963
C. S. File No. 49/123

February
1963

April
11,
1963