

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 25 S. . . T. S. . . R. 6 W. . . R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21891

S. W. Corner D. L. C. No. 57. 136
 Found - Stone as called for in government notes (17"x 5" top,
 .8" above ground) Mks. visible on Stone "T25S R W".
 29" White Oak S.30°E. (not S.15°E.) 12 ft., shows
 very plain scar, Did not chop open.
 New BT: 6" D.Fir S.69°W. 34.0 ft. Mkd: S.W. DLC 57 CS BT.

137
 $\frac{1}{4}$ Corner to Sections 32 and 33.
 Found - 30" Bl. Oak N.31°E. 15.2 ft. Opened & found scribing "/ S"
 on badly rotted face. Tree dying.
 Stump Hole & Fragments of rotten Laurelwood S.60°W. 42.9 ft.
 Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
 T25S R6W $\frac{1}{4}$ S32/S33
 New BT's: 16" D.Fir S.18°W. 11.2 ft. Mkd: $\frac{1}{4}$ S32 CS BT.
 6" D.Fir N.14°E. 28.0 ft. Mkd: $\frac{1}{4}$ S33 CS BT.
 Note - Corner lies on N.W. slope approx. 175 ft. North of top of ridge.

138
 Section Corner to Sections 27 - 28 - 33 - 34.
 Found - 40" Bl. Oak S.8 $\frac{1}{2}$ °W. 793.3 ft. Cut open & found good scribing "B".
 North Side of Tree entirely dead.
 No trace of N. E. Bearing Tree.
 Set $\frac{3}{4}$ Brass Cap at Cor. Mkd: County Surveyor's T25S R6W $\frac{S28}{S33}$ $\frac{S27}{S34}$
 Office, 1963
 New BT's: Doug. Fir S.35 $\frac{1}{2}$ °W. 280.6 ft. Mkd: T25S R6W S 33 CS BT.
 Doug. Fir S.14°E. 295.7 ft. Mkd: T25S R6W S34 CS BT.
 No trees near in Sections 27 or 28.
 Note - Corner falls in N. & S. fence line 236.5 ft. North of 4 way
 Fence Corner.

139
 $\frac{1}{4}$ Corner to Sec. 36, T25-6W. & Sec. 1, T26-6W.
 Found - Stump Hole & Rotten remains of Oak Log N.36 $\frac{1}{2}$ °W. 52.8 ft.
 In rotten wood found old flattened areas appearing to be
 portions of old face, no scribing found.
 Stump Hole S.27 $\frac{1}{2}$ °E. 34.3 ft. No portion of tree remaining.
 This location also fits call in gov't. field notes for ridge top.
 Corner position lies in E. & W. fence line 3 ft. West of fence
 corner. (Fences E., W. & N.)
 Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W $\frac{1}{4}$ $\frac{S36}{S1}$
 Office, 1963
 New BT's: 6" D.Fir N.9°E. 18.2 ft. Mkd: $\frac{1}{4}$ S36 CS BT.
 5" W. Oak S.5°E. 19.0 ft. Mkd: $\frac{1}{4}$ S 1 CS BT.

140
 $\frac{1}{4}$ Corner to Sec. 35, T25-6W. & Sec. 2, T26-6W.
 Found - 46" Fir Stump N.32°E. 30.4 ft. Cut open & found one scribe
 mark "1" - Tree had been opened previously & grown over
 again, balance of upper face rotted.
 No trace of Cedar to S. E.
 Corner falls in E. & W. fence line, 33 ft. west of small stream.
 (Fits call in gov't. field notes)
 Set - Brass Cap at Cor. Mkd: County Surveyor's T25S R6W $\frac{1}{4}$ $\frac{S35}{S2}$
 Office, 1963
 New BT's: 15" W.Fir N.48 $\frac{1}{2}$ °E. 66.2 ft. Mkd: $\frac{1}{4}$ S35 CS BT.
 9" D.Fir S.58°W. 78.5 ft. Mkd: $\frac{1}{4}$ S 2 CS BT.

141
 $\frac{1}{4}$ Section Corner to Sections 19 and 30.
 Found - 62" Bl.Oak N.53 $\frac{1}{2}$ °W. 213.8 ft. Cut open & fd. good scrbing. " $\frac{1}{2}$ S".
 42" Bl.Oak S.67°W. 199.3 ft. Scar visible on bark, didn't open.
 Set - $\frac{3}{4}$ " I.Rifeng. Rod, 12" below ground surface.
 Corner position falls in Prune Orchard.
 Set - Wit. Cor. 30 ft. W. of $\frac{1}{4}$ Cor.
 Brass Cap Mkd: County Surveyor's T25S R6W WC $\frac{1}{4}$ $\frac{S19}{S30}$
 Office, 1963
 Rescribe: S.W. BT., 42" Bl.Oak S.63 $\frac{1}{2}$ °W. 172.4 ft. (from Wit. Cor.) Mkd:
 "W.C. $\frac{1}{4}$ S30 CS BT".
 New BT: 17" Bl.Oak N.65°W. 229.2 ft. Mkd: WC $\frac{1}{4}$ S19 CS BT.
 Witness Corner lies 2 feet East of N. and S. Fence Lane. July 19, 1963

Milo E. Godfrey, Deputy
 V. Tracy & M. Stone
 April 11, 1963
 C.S. File No. 49/123

Milo E. Godfrey, Deputy County Surveyor
 Vernon Tracy and Mike Stone
 June 1963
 C. S. File No. 49/123

FD. OK 4-91
 M 113-11