

Douglas County Surveyor's Record of
Government Corners Renewed

T. 25 S. T. S. R. 6 W. R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 21681

142

$\frac{1}{4}$ Corner to Section 7, T25-6W. & Sec. 12, T25-7W.
Found - 50" Fir Stump N.55°W. 62.0 ft., old & badly charred & rotten.
Two old axe faces on bark, scribe mark upper half of "S".
Cedar, down & half-burned away, N.83°E. 46.2 ft. No marks found.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R7W $\frac{1}{4}$ S12/S 7 R6W
New BT's: 15" D.Fir N.55°E. 24.8 ft. Mkd: $\frac{1}{4}$ S 7 CS BT.
10" D.Fir N. 2° W. 19.2 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
Corner lies on very steep & rocky north slope, approx. 50 ft. south of
small draw sloping east, at foot of slope:
A 27" I. Cedar with Grant & Evans' yellow tag bears N.70°E. 100.6 feet.,
(formerly used as NE. BT.)

143

West $\frac{1}{4}$ Corner to Section 6 only, T25-6W.
(on E. Line Sec. 1, T25S R7W)
Found - 32" Fir S.57°W. (not S.67°W.) 71.9 ft. Has been previously opened,
scribing visible on old face. Tree alive & in good condition.
36" Rotten Fir Snag S.38°E. 42.2 ft. Scribe marks vis. on portions
of old faces. Part of "S" & part of "B".
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R7W W $\frac{1}{4}$ S6 R6W
New BT's: 5" D.Fir S.27°E. 21.3 ft. Mkd: $\frac{1}{4}$ S 6 CS BT.
5" D.Fir N.75°E. 12.1 ft. Mkd: $\frac{1}{4}$ S 6 CS BT.

144

Sec. Cor. to Secs. 6 & 7, T25-6W. & Secs. 12 & 1, T25-7W.
Fd. - 38" Fir S.2°W. 11.9 ft. Faint bark scribing visible "12 T26 7W". Axe
marks visible at location for BT.
36" Fir S.2°E. 17.2 ft., old axe marks visible on bark (2scars), No scribing.
24" Fir N.40°W. 3.3 ft., illegible scribe marks visible on bark.
24" Fir N.60°E. 3.3 ft., Good axe scar visible. Did not span.
(Distances are all from face of tree.)
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T25S R7W $\frac{S1}{S12} | \frac{S6}{S7}$ R6W
Blaze & Rescribe: 24" D.Fir N.55°E. 4.2 ft. Mkd: T25S R6W S6 CS BT.
36" D.Fir S.5°E. 19.0 ft. Mkd: T25S R6W S7 CS BT.
24" D.Fir N.38°W. 4.5 ft. Mkd: T25S R7W S1 CS BT.
New BT: 16" D.Fir S.22°W. 21.8 ft. Mkd: T25S R7W S12 CS BT.
Corner lies on gentle west slope approx. 80 ft. W. of top of ridge.

145

Closing Corner Sec. 36, T24-7W. & Sec. 1, T25-7W.
Found - 50" D.Fir S.59 $\frac{1}{2}$ °W. 42.9 ft., old bark scribing visible, faces corner.
60" D.Fir N.49°W. 37.0 ft. Bark shows evidence of having been
flattened off with axe. Bark badly burned & no scribe marks found.
Did not find S.E. tree called for in notes.
Rotten Fir Snag S.10°W. 14.3 ft. with portion of old face showing
fragments of scribe marks. At time it was faced off, tree would
have been 12" to 15" diam., face & scribing faces approx. N.40°W.,
not toward corner as set from 2 BT's.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963 T24S R7W $\frac{S36}{S1} | \frac{R6W}{S7}$ CC
New BT's: 13" D.Fir N.30°W. 111.0 ft. Mkd: T24S R7W CC S36 CS BT.
28" I. Cedar N.31°E. 99.2 ft. Mkd: CC T24S & 25S R7W CS BT.
No trees available to S.W. except old, overripe & half dead D. Firs.
Did not mark new S.W. tree.
Corner lies approximately 10 ft. west of logging road, nearly at
south end of road.

146

$\frac{1}{4}$ Corner to Section 7 and 18.
Found - County Surveyor's Brass Cap (1958) in E. & W. Fence Line. REN. #63
66" Fir S.5°W. 24.3 ft. Tree now dead, bark badly burned. No Scrbng.
7" W.Fir Stump N.&E. 4.8 ft. Bottom of axe face near top of
stump, no scribing.
48" Fir Stump N.27°W. 11.9 ft. Stump badly burned, no scribing visible
Blaze & Rescribe 66" Fir Snag (in wood) S.5°W. 24.3 ft. Mkd: $\frac{1}{4}$ S18 CS BT.
Blaze & Scribe: 24" Fir Snag (15' high) N.81°E. 127.2 ft. Mkd: $\frac{1}{4}$ S7 CS BT.
No live trees left within reasonable distance of corner.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July 1963
C. S. File No. 49/123

RE-RENEWED, SEE CORNER NO. #193
RE-RENEWED, SEE CORNER NO. #192