

Douglas County Surveyor's Record of
Government Corners Renewed

T 25 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

147

$\frac{1}{4}$ Corner to Sections 11 and 12.
Found - 33" White Oak N.35°W. 236.9 ft. Cut open & fd. good scbng. "BT".
No trace of N. E. Bearing Tree.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R6W $\frac{1}{4}$ S11/S12
New BT's: 6" W. Oak N.73°E. 20.2 ft. Mkd: $\frac{1}{4}$ S12 CS BT.
6" W. Oak N.50°W. 112.2 ft. Mkd: $\frac{1}{4}$ S11 CS BT.
Note - Corner falls on grassy hillside (pasture) 25 ft. west of fence
line running N.35°W., -S.35°E.

FD OK 4/87
G. BUGHMAN
M 101-17

148

$\frac{1}{4}$ Corner to Section 6 and Section 7.
Found - Burned, hollow Shell of large Cedar Snag in 3-way fence corner,
(Fences East, West & South). No markings left on Cedar. REN #18
Remnants (in place) of large Fir Stump N.50°E. approx. 7 feet.
No trace of Orig. S. E. Tree.
No trace of either BT. mkd. in 1923 renewal.
Note - A small pond bears west from cor. approx. 4 chains distance,
see original line notes.
Also see affidavit of Guy Cole on field notes, C.S. 49/123.
Set - Brass Cap at Cor. (inside shell of old Cedar) Mkd: $\frac{1}{4}$ S 6
County Surveyor's Office, 1963 T25S R6W S 7
New BT's: 6" D. Fir N.55°E. 7.0 ft. Mkd: $\frac{1}{4}$ S6 CS BT.
14" Incense Cedar S.79°W. 39.6 ft. Mkd: $\frac{1}{4}$ S7 CS BT.

FD OK
7/89
Rm 3-72
B. SHANER

149

$\frac{1}{4}$ Corner to Sec. 18, T25-6W. & Sec. 13, T25-7W.
Found - 37" Fir N.2°W. 99.0 ft. Faint bark scribing visible " $\frac{1}{4}$ ".
Tree alive & standing, top partly dead.
36" Fir N.82°E. 42.2 ft., tree recently uprooted & down.
Bark shows evidence of having been face off with axe. No scrbng.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R7W $\frac{1}{4}$ S13/S18 R6W.
Build Mound of Stone around Cap.
New BT's: 22" D. Fir N.1°E. 8.2 ft. Mkd: $\frac{1}{4}$ S18 CS BT.
15" D. Fir S.85°W. 20.4 ft. Mkd: $\frac{1}{4}$ S13 CS BT.
Note - Corner lies on steep, rocky S.E. slope, approx. 100 feet south
of top of spur and between two large outcrops of rock.

150

$\frac{1}{4}$ Corner to Sec. 19, T25-6W. & Sec. 24, T25-7W.
Found - 18" W. Oak N.68°E. 27.1 ft. Opened upper scar & found good
scribing "S". Lower scar previously opened, Scbng. visible.
Stump Hole & rotten pieces of Oak Log S.32°W. 58.1 ft. Too far
gone to find any markings.
Set - Brass Cap at Cor. Mkd: County Surveyor's Office, 1963
T25S R7W $\frac{1}{4}$ S24/S19 R6W.
New BT's: 10" W. Oak (in fence line) N.32°W. 12.5 ft. Mkd: $\frac{1}{4}$ S24 CS BT.
16" Bl. Oak N.41°E. 28.0 ft. Mkd: $\frac{1}{4}$ S19 CS BT.
Note - Corner falls at base of 12" White Oak in Fence Corner, fences
approximately East, West and North from Corner.
The new bridge crossing the Calapooya on the Garden Valley Road
is visible from this corner & bears S14 $\frac{1}{2}$ °E. approx. 1 mile distance.

151

$\frac{1}{4}$ Section Corner to Sec. 36, T25-6W. & Sec. 31, T25-5W.
Found - County Surveyor's Brass Cap set in 1959 (Cor. No. 50C)
10" Doug. Fir, now 12", N.46°E. 68.6 ft. Blazes not
grown over, portions. of scribing visible through
pitched over face.
The S.W. Tree (20" Fir S.77°W. 7.9 ft.) is uprooted
and down.
New BT's: 15" D. Fir N.13°W. 16.0 ft. Mkd: $\frac{1}{4}$ S36 CS BT.

Milo E. Godfrey, Deputy County Surveyor
Vernon Tracy and Mike Stone
July and August 1963 - C. S. File No. 49/123