

**Douglas County Surveyor's Record of
Government Corners Renewed**

T. 25 S. T. S. R. 6 W. R. W. W. M.

ROKE-CHAPMAN CO., EUGENE, ORE. 21881

Sec. Cor. to Sections 7 & 18, T25-5 and Secs. 12 & 13, T25-6W.

172

This Corner Set from Survey of Range Line.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1972

| | | |
|---|-------------|---|
| R | T 25 S | R |
| 6 | S 12 S 7 | 5 |
| W | S 13 S 18 | W |

New BT's: 40" B.Oak N. 2° W. 102.7 ft. scribed T25S R6W S12 CS BT.
14" Laurel S. 15° E. 170.8 ft. scribed T25S R5W S18 CS BT.
7" D.Fir South 286.0 ft. scribed S13 CS BT.

Witness Corner to 1/4 Corner for Sec. 7, T25-5W. & Sec. 12, T25-6W.

173

This corner set from survey of Range Line.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1972

| | | |
|---------------------|----------------|-----|
| | T 25 S | |
| W.C. 99.8 ft. N. to | | |
| R6W | 1/4 S 12 S 7 | R5W |

New BT's: 27" Ash N. 46° W. 15.6 ft. scribed W.C. 1/4 S12 CS BT.
14" Maple S. 73° E. 62.0 ft. scribed W.C. 1/4 S 7 CS BT.

6/6/72

Sec. Cor. to Sections 6 & 7, T25-5W. & Secs. 1 & 12, T25-6W.

174

This corner set from survey of Range Line.

Set - Brass Cap at Cor. Mkd: County Surveyor's Office 1972

| | | |
|-----|------------|---|
| R R | T 25 S | R |
| 6 | S 1 S 6 | 5 |
| W | S 12 S 7 | W |

New BT's: 15" D.Fir N. 26° E. 300.7 ft. scribed T25S R5W S 6 CS BT.
16" W.Oak N. 87° E. 180.0 ft. scribed T25S R5W S 6 CS BT.

1/4 Corner for Sec.s 4 and 9.

175

Found - 1962 Brass cap Ren. #110
20" Madrone in Sec. 9 down and out of position.
10" Fir, bears N.40°E., 83.1 ft. (now dead).

JAN 1973

Larry Bishop
for Joe Cole
Dec. 1973
M 52 - 6

Section corners for Secs. 33 & 34., and Secs. 3 & 4 of T26 R6

176

Found- Brass cap and bearing trees as noted in Ren. 134
This corner is now located at the toe of a slide area. The brass cap and all bearing trees except two have been subjected to movement in the slide. Measurements from the two undisturbed bearing trees:
A 7" now 8" D. Fir bearing N. 46°E., 64.5 ft, with scribing "S34 CS BT" visible.
An 8" now 10" W. Oak bearing S.35°E., 39.3 ft, well-healed, are in agreement with each other and indicate the brass cap has moved approx. 4 ft. downhill.

Gary Langlitz
Pete Earle
C.S. 56/51
5-6-74

Based on the measurements from the two undisturbed B.T.'s as noted previously, we remove the brass cap & reset it at a witness cor. 100 ft. east of the true cor. We remark the brass cap to read as follows:

| | | |
|-------------------------------|----------------------|----------------|
| County Surveyor's Office 1974 | T25S | Witness Corner |
| | S33 S34 | R |
| | S4 S3 | 6 |
| | | W |
| | 100 ft. west to Cor. | |
| | T26S | |
| | 1974 | |
| | 1963 | |

We mark the following BT'S for witness corner:
18" D. Fir bears S.83°W., 19.2 ft. scribed: "WC T26S R6W S3 CS BT"
7" W. Oak bears N.52°E., 26.7 ft. scribed: "WC T25S R6W S34 CS BT"
10" W. Oak bears S.79 1/2°E., 32.8 ft scribed: "WC S3 CS BT"
15" Madrone bears S.15 1/2°W., 82.4 ft., scribed "WC T26S R6W S3 CS BT"

Note- This witness corner lies approx. 30 ft south of a dirt road.
Declination: 20° East

5-6-74

Francis L. Ingram, Doug. County Surveyor
John M. Powell & Crew
May 1972
C.S. File No. 56/16
Map File M 42 - 61

FD. OK 4-91
M 113-11