

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 7 R. W. W. M.

WITNESS CORNER TO  $\frac{1}{4}$  SEC. CORNER BET. 7 and 8. 11

I made a mound of rock 49.3 ft. North of  $\frac{1}{4}$  Cor. as  $\frac{1}{4}$  Cor. came in River. Corner was renewed from the old B.T.s both of which were standing but no marks were visible. Marked new trees. 61

A Myrtle 10" S.69°00'W., 13.2 ft. marked W. C. C.S.B.F.  
A Myrtle 10" S.75°30'E., 23.3 ft. marked W. C. C.S.B.F.

CORNER TO SECS. 4-5-8-9. 12

Renewed corner from 4 original B.T.s. I set a  $\frac{3}{4}$ " x 30 Iron pin from which original B.T.s

Oak bearing scars N.70°E., 193 ft. horizontal measure  
Oak bearing scribe S1°30'E., 277 ft. slope measure  
Oak bearing scribe S.5°W., 237.2 ft. slope measure  
Oak bearing scribe down N.87°W., 1011.7 ft.  
A Boulder marked with X S.36°E., 50 ft.

Corner in middle of spur leading up main ridge.

$\frac{1}{4}$  COR. N. SIDE SEC. 8. 13

I renewed this corner from the original B.T.s I set an Oak post and a Sand Rock 8"x 8"x 20" marked  $\frac{1}{4}$  S. C.S. The original tree called for as N.59°W., bore scars but I could find no scribe marks. The tree S.89°W. was nearly dead and blazes were badly decayed but I found a portion of scribe marks on lower blaze. I marked new trees. 90

A B. Oak 12" S.87°15"W., 133 ft. slope 12°00'  
A W. Oak 10" N.18°W., 98.5 ft. slope 12°15'

$\frac{1}{4}$  COR. ON THE SIDE OF SEC. 9. 14

I renewed this corner from the original B.T.s which were both alive and standing but bearing no scribe marks. I set a 4x4x36 inch Oak Post and remarked the old trees  $\frac{1}{4}$  S. C. S. B.T. both trees checked with Government Field Notes.

$\frac{1}{4}$  CORNER ON SOUTH SIDE SEC. 8. 15

I renewed this corner from an original B.T. which was 40 in. dia. plainly marked and facing N.59°E. I set post to correspond with facing 50 lks. from tree and checked position by measurement West to creek and a blazed line passing through this position. I marked a face of Bluff  $\frac{1}{4}$  S.C.S. B.O. and set a large Maple post for corner bluff bears S.31°E., 64.6 ft. 98

MOST NORTHERLY N.W. COR. D.L.C. # 49 (Mary Pierce) 16

Found S.S. Rock original set for this cor. Drove 11" Pipe, 1" pipe in center of 11" Pipe, beside rock from which 12" conc. cor. (S.E.) post of cemetery bears N.54°E., 197.2 ft. 49

INT. "E" CORNER D.L.C. # 49 (Mary Pierce) 17

Set from stumps of two original Ash Trees, the one N.13 lks for B.T. shows cut and old wood inside shell, decayed set 4" Oak Roller, 1" Iron Bar in center from which:  
White Oak 24" bears S.87°E., 56.8 ft. 60  
White Oak 12" bears S.44°W., 39.5 ft.  
both marked Cl. 49 C.S.B.T.

C.S. Vol. 32, p. 175  
K. Emmett  
J.W. Cole  
Surveyor  
Dec: 18-22, 1923  
Wit. Geo. A. Streese  
Ed Mosher  
Herman Itreese

F.B. 52 Page 32  
J.W. Cole G.S.  
Jan. 29-31, 1923  
Wit. H. Streese  
John Harding  
Ed Mosher

C.S. Vol. 3, p. 179  
Kerney Emmett  
J.W. COLE  
Jan. 29-30  
Wit. H. Streese  
John Harding above  
Ed Mosher

C.S. Vol. 3, p. 180  
Ed Thompson hus. of  
J.W. Cole  
Wit. same as above  
Feb. 7, 1924

C.S. File # 30/39  
Oct. 26, 1937  
A. Boyer D.C.S.  
Wit. D.A. Lane  
Will Lone  
Jno Paulson

Mrs. Anna Emery Thompson