

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

~~1/4 sec. corner to secs. 12 and 13.
Set a stake from Original B. T. - now a 3" B. Fir bearing North 3° West
for 16 lks.~~

Claude Kerr
July, 1955.
C. S. File No. 42/11.

IN T25E, R8W

~~Center 1/4 corner section 12.
At point for corner set a 3" x 3" x 5" fir post.~~

36a

Section Corner Common to 17, 18, 19, & 20.
Found - Rotted snag original BT. 12" now 16" Fir N.27°E. 7.9 ft.
Scribe Marks visible.
Find 18" Fir face rotted. No scribe marks found. Checks
bearing & distance for N. W. original BT.
The S. E. original BT gone. I open original 12" now 16"
Fir S.29 1/2°W. Record 50.2 ft. I find distance should
be 31.4 ft. (Checks Bearing) Find scribing "T".
Set Brass Cap at corner marked

S18	S17
S19	S20

 T25S R7W County Surveyor's
Office, 1957.
New BTs.: 16" R.Fir N.28°W. 6.0 ft. scribed S18 T25S R7W CS BT.
30" R.Fir S.22°E. 25.0 ft. scribed S20 T25S R7W CS BT.
This BT was opened about 15 years ago. I scribe
below. S20 T25S R7W CS BT.
I rescribe the original S. W. BT. 16" R.Fir S25°W. 31.4 ft.
scribed S19 T25S R7W CS BT.
6" R.Fir East 57.0 ft. scribed S17 T25S R7W CS BT.

James W. Byron, Dep. Co. Surveyor
S. Bilow
Nov. 6, 1957
C. S. File 49/10

