

Douglas County Surveyor's Record of
Government Corners Renewed

25 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

41

Sections 30 & 31 (T25S, R7W) and 25 & 36 (T25S, R8W).
60" Fir B.T. bears S56°W 64 links marked as described in govt.
field notes. Renewed corner by setting a 3/4" iron pipe in proper
location from which:
8" Fir bears S75°E 10.5' Mkd. at T25SR7" S. 31 R.E. 2741 B.T.
A chingnapin 8" diameter bears N47°E 26.7' Mkd. T25SR7W
S30 B.T.

Arthur R. Evans 1952
File 41 Envelope 57

FD OK 4/30/79 - K. Reea. Co. Surveyors Office c.s. 60/24

~~Section corner to secs. 1, 2, 11 & 12. THIS COR DESTROYED BY BYRON 11-57
See C. S. FILE 42/76 FOR RENEWAL~~
Found Scribed 4" x 4" x 3' 0" post which was badly burned.
Replaced post with a 3/4" inch iron pipe from which bears:
A Red Cedar 40", N.30°E., 85.8 feet - O. B. T. - Scribe marks Vis.
A Red Cedar, 38" N.34°W., 21.8 feet - O. B. T. - Scribe mks Visible.
A fir, 50", S.53°E., 47.5 feet - O. B. T. Scribe marks visible.
A Red Cedar, 10", S.63°W., 55.0 feet - New B. T. Marked
S 11 T 25 S, R 7 W B. T.

R. H. Gee
R. J. Henrikson
S. Dancho
June 14, 1955.
See C. S. File No. 42/24.

43

1/4 section corner to section 1 & 12.
Found B. T. for Sec. 1, Tree down but scribe marks "1/4 S 1 B T
visible.
Reset 1/4 corner according to records, turned bearing to other
B. T. which is now a stub, no bark.
Corner is a 3/4" inch iron pipe from which bears:
A 10" Hemlock, S.12°E., 9.3 feet - New B. T. - Marked "1/4 S 12
T 25 S, R 7 W B. T." Placed tag on this tree.
A 12" Hemlock N.53°W., 30.1 feet - New B. T. - Marked "1/4 S 1
T 25 S R 7 W B. T.

At a point 276' S. on center line of Sec. 12, go N.78°E. 10.0' to 48" Fir which has several
scribe marks and "S 11" carved with knife in bark. No record of this tree. Do not destroy.

1/4 sec. corner to secs. 33 and 34.
Found stump of old B. T.:
W. Oak, N.1/2°E., 432 lks. Found reverse of scribe marks
inside of hollow of stump.
Set steel axle with gear attached for corner.
Marked 2 new B. T.s:
20 inch B. Oak, N.2°W., 58.55 feet.
12 inch B. Oak, N.24°W., 66.22 feet.
Both new trees are in same quadrant, but no trees available in
any other quadrants.

Edwin S. Woodford
Wit: Art Nelson
August, 1949.
C. S. File No. 42/118.

44

Section corner to secs. 33 & 34, T 25 S., R 7 W., and secs. 3 & 4,
T 26 S., R 7 W.
Found 1 old B. T.:
24 inch Oak, S.75°E., 43 lks. - (tree now 36 inches), found
reverse of scribe marks in cut out slab.
Set a 1 inch x 30 inch steel shaft for corner.
Marked new tree:
15 inch Fir, S.30 1/2°E., 7.7 feet.

Edwin S. Woodford
Wit: Marr
Ilnhart
August, 1949.
C. S. File No.
42/119.

45

81

1/4 Corner to Sections 23 & 24.
Found - Both Original Bt's.
The N. E. BT. now down, has open face, good scribing "1/4 S".
The S. W. BT. now snag, I open & find good scribing "1/4 S BT".
Both BT's check for bearing & distance.
The S. W. BT. recorded 12" B. O., we find it to be 24" when
scribed.
Set Brass Cap at Corner marked, 1/4 S23/S24 T25S R7W County Surveyor's
Office, 1958.
New BT's: 9" R. Fir bears S.81°E. 15.0 ft. scribed 1/4 S24 CS BT.
16" R. Fir bears S.80°W. 18.5 ft. scribed 1/4 S23 T25S R7W CS
BT

James W. Byron, Deputy
M. Godfrey
S. Bilow
April 10, 1958
C. S. File No. 49/76

46