

Douglas County Surveyor's Record of  
Government Corners Renewed

25 T. S. 7 R. W. W. M.

KOKE-CHAPMAN CO., EUGENE, ORE. 97196

47

Section Corner to Sections 1, 2, 11, & 12.

Found - Orig. 34", now 46" Cedar. I open & find good scribing "T25S R7W S2" N.34°W., 21.8 ft.

Orig. 40", now 50" R. Fir shows fair bark scribing "S W T B".

Record bearing S.53°E., I find should be S.35°E. 47.6' (dist.OK)

Note: I also find 2 1/4" I.P. set alongside 3"x 3"x 2'-6" sq. & scribed Post, which seems to be old but definitely not at original position, as I cannot find any decayed wood there.

I do not find any trace of the N.E. or S.W. BT's.

Set Brass Cap at Corner Mkd:  $\frac{S\ 2}{S\ 1}$  T25S R7W County Surveyor's Office, 1957

Note: I also find 9" Cedar bears S.44°W. 73.6 ft. scribed by R. Gee, T25S R7W S11 BT. I scribe CS on this BT.

New BT's: See Note above for S. W. BT.

16" Cedar bears S.66°E. 5.0 ft. scribed S12 T25S R7W CS BT.

12" Cedar bears N.12°E. 29.7 ft. scribed S 1 T25S R7W CS BT.

46" Orig. Cedar N.38°W. 22.8 ft. rescribe S2 T25S R7W CS BT.

2 1/2 inch Iron Pipe bears S.6°E. 26.2 ft.

Note: On this date, I find Original 36", now 48" Cedar. I open & find good scribing, bears N.15°E., record N.30°E. Dist. checks record 85.8 ft. All BT's face to corner & all distances check record & one bearing checks. I find no trace of S.W. BT.

I destroy Cor. set by Gee, See Cor. No. 42, previous page.

48

~~1/2 Section Corner to Sections 2 & 11.~~

~~Found - Orig. 16" Cedar, now 32" Stump S.39°W., 19.1 ft. I open old scar near base & find good scribing "B"~~

~~25" R. Fir Snag that has been bark scribed "1/2 BT" bears N.29°E. 48.6 ft., record is N.12°W., 50.8 ft. I do not believe this is the Original BT., scribing does not seem to be old enough.~~

~~THIS CORNER REMOVED~~

~~The Orig. N. W. BT. would be under Log Road fill. TO AGREE~~

~~I use the Original S. W. BT. to fix position of 1/2 Corner. WITH CHAIN~~

~~Set Brass Cap at Corner Mkd:  $\frac{1}{2}$   $\frac{S\ 2}{S\ 1}$  T25S R7W County Surveyor's Office, 1957. 5-14-59~~

~~New BT's: 7" R.Fir bears S.19°E. 10.2 ft. scribed  $\frac{1}{2}$  S11 CS BT~~

~~13" Cedar bears N. 7°W. 64.4 ft. scribed  $\frac{1}{2}$  S 2 CS BT.~~

49

1/2 Section Corner to Sections 9 & 10.

Found - Orig. 12", now 24" B. Oak Stump N.65°E. 29.0 ft., Center rotted near base. Inside I find good scribing "BT" negative.

36" Fir that checks record bearing & distance for Orig. S. W. BT.

I cannot find any scribe Mks., Tree has been burned.

Set Brass Cap at Corner Mkd:  $\frac{1}{2}$  S9/S10 T25S R7W County Surveyor's Office, 1957.

Note: I find 2" I. Pipe 2 ft. above ground that bears S.54 1/2°W. 20.7 ft.

Mr. League says I. Pipe set by Boyer.

New BT's: 10" R.Fir bears S.3 1/2°E. 44.9 ft. scribed  $\frac{1}{2}$  S10 CS BT.

6" R.Fir bears N.19°W. 5.7 ft. scribed  $\frac{1}{2}$  S 9 CS BT.

50

Section Corner to Sections 10, 11, 14, & 15.

Found - 3"x 3" scribed Sq. Post at Corner. This Corner renewed about 15 years ago by County Surveyor, Boyer

I find all Four BT's. as renewed.

Cedar bears N.61°E. 56.1 ft. scribe & face grown over. I do not open.

Cedar bears S.15°W. 29.5 ft. some scribing visible.

Cedar bears N.70°W. 27.6 ft., some scribing visible.

Cedar bears S.43°E. 44.8 ft., scribing visible "14 25S R7W CS BT"

Set Brass Cap at Corner & alongside 3"x 3" Sq. Post.

Marked Cap  $\frac{S10}{S15}$  |  $\frac{S11}{S14}$  T25S R7W County Surveyor's Office, 1958.

I find No Original Bearing Trees.

James W. Byron, Deputy County Surveyor  
Chainmen: M. Godfrey  
S. Billow  
Nov., 1957 & May, 1958  
C. S. File No. 49/76